

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA17010121/K1GA3Q2-1
Date: 30/06/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd	Policy No:	P1764198
Claimant		
Vehicle No : SHB5360Y	Insured Vehicle No :	SLA9262D
Date of Loss: 24/05/2017	Nature of Claim:	TP
	Claim No:	C0435448

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5360Y		
Make & Model:	CHRYSLER 300C, 3.0 D (A)	Engine No:	HIDDEN
Reg. Date:	28/07/2010 (Man. Year: 2010)	Chassis No:	1C3C96CM3AY108625
Colour:	Black	Odometer:	1038610 km
Engine Capacity:	2987 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R16	Rear Tyre Size:	225/60 R16
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,884.40	10,071.20	9,813.20	49.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,840.00	1,240.00	2,600.00	67.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,724.40	11,311.20	12,413.20	52.32
Approved Total (Overridden) (S\$)		9,300.00		
Nett Amount (S\$)	23,724.40	9,300.00	14,424.40	60.80
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
+ Car Rental (8.0 x S\$129.47/day) (S\$)		1,035.76		
+ Doc/Search Fee (S\$)		5.00		
Nett Liability (S\$)		10,820.76		

INSPECTION

Date of Assignment:	24/05/2017	
Date Inspected:	24/05/2017	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	5.0 days	

Adjuster: KALVIN ANG WEI KUN

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 05 Dec 2017)
Parts: 143	CHRYSLER 300C 3.0 D (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB5360Y)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSY (DISC 10%) (CONSISTENT)	Deformed	1,830.00 F	*1,647.00 F
2	6		*FRT BUMPER CLIP (DISC 10%) (CONSISTENT)	Necessary	60.00 F	*54.00 F
3	6		*FRT BUMPER RIVET (DISC 10%) (CONSISTENT)	Necessary	120.00 F	*108.00 F
4	1		*MOULDING FRT BUMPER RH (DISC 10%) (CONSISTENT)	Cracked	650.00 F	*585.00 F
5	1		*FRONT BUMPER INDICATOR LAMP RH (DISC 10%) (CONSISTENT)	Cracked	77.00 F	*69.30 F
6	1		*FRONT FENDER ASSY ,RH (DISC 10%) (CONSISTENT)	Dented	1,020.00 F	*918.00 F
7	1		*TYRE RIM (DISC 10%) (CONSISTENT)	Cracked	958.00 F	*862.20 F
8	1		*TIE ROD RH (DISC 10%) (CONSISTENT)	Bent	200.00 F	*180.00 F
9	1		*TIE-ROD ENDS RH (DISC 10%) (CONSISTENT)	Bent	144.00 F	*129.60 F
10	1		*ARM ASSY -FRONT LOWER RH (DISC 10%) (CONSISTENT)	Bent	580.00 F	*522.00 F
11	1		*ARM ASSY-FRONT UPPER RH (DISC 10%) (CONSISTENT)	Bent	640.00 F	*576.00 F
12	1		*KNUCKLE -FRONT AXLE RH (ARM) (DISC 10%) (CONSISTENT)	Bent	1,580.00 F	*1,422.00 F
13	1		*BEARING -FRONT WHEEL HUB RH (DISC 10%) (CONSISTENT)	Bent	492.00 F	*442.80 F
14	1		*STRUT ASSY -FRONT AXLE RH (DISC 10%) (CONSISTENT)	Bent	302.00 F	*271.80 F
15	1		*LINK SWAY ,RH (DISC 10%) (CONSISTENT)	Bent	380.00 F	*342.00 F
16	1		*CROSSMEMBER ASSY FRONT (DISC 10%) (CONSISTENT)	Bent	1,850.00 F	*1,665.00 F
17	1		*TYRE (DISC 30%) (CONSISTENT)	Punctured	395.00 F	*276.50 F
18	1		*ENERGY ABSORBER ,FRONT BUMPER (CONSISTENT)	Serviceable	408.00 F	*- F
19	1		*FRONT BUMPER RAIL (CONSISTENT)	Serviceable	1,246.00 F	*- F
20	1		*FOG LAMP ASSY -FRONT RH (CONSISTENT)	Serviceable	89.00 F	*- F
21	1		*NOZZLE FRT BUMPER RH (CONSISTENT)	Serviceable	320.00 F	*- F
22	3		*SENSOR FRT BUMPER (CONSISTENT)	Serviceable	960.00 F	*- F
23	1		*HEADLAMP ASSY ,FRONT RH (CONSISTENT)	Serviceable	2,100.00 F	*- F
24	1		*FENDER PROTECTOR -FRONT RH (CONSISTENT)	Serviceable	130.00 F	*- F
25	1		*FRT FENDER LAMP (CONSISTENT)	Serviceable	60.00 F	*- F
26	1		*RH FRT ,SHOCK ABSORBER (CONSISTENT)	Serviceable	310.00 F	*- F
27	1		*FRONT STABILIZER BAR (CONSISTENT)	Serviceable	390.00 F	*- F
28	1		*SET ANTI-ROLL BAR BUSHING (CONSISTENT)	Serviceable	19.40 F	*- F
29	1		*STEERING RACK ASSY (CONSISTENT)	Serviceable	1,424.00 F	*- F
30	1		*GARNISH ROCKER PANEL (CONSISTENT)	Serviceable	1,150.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part.						
Total Parts (\$)					19,884.40	10,071.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	1,014.00	400.00
2	SPRAY PAINT	New	1,486.00	400.00
3	TOWING CHARGE	New	140.00	100.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	30.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	40.00
6	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	80.00
7	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	0.00
8	TO TEST AND REFIX FRONT SENSOR SYSTEM	New	120.00	20.00
9	TO REMOVE AND REFIX UNDERCARRIAGE	New	250.00	0.00
10	TO REPLACE SUNDRY PARTS	New	100.00	20.00
11	TO WASH AND VACUUM	New	60.00	0.00
12	TO REMOVE AND REFIX CROSSMEMBER	New	250.00	150.00
Gross Labour Cost (\$\$)			3,840.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >