| 100 | | KEE 083 CTI190 | 19320/ Hof3-1 | Special fastive | them. |
|---|---|---|--|---|---------------------------------|
| From (Person) Estimated Cos | | | NMENT (Office) | 14 Third Par Claimant | |
| | spection) Evalu | SJP9625K | Insured: XE 43 | Workshop | C.L. Appruiser JEMENTAH MOTO |
| at Workshop n of | 14 Defu | JEMFNTAH WORKS lane 10 # 01- | Tel: 406 | - 3-(3 | |
| Policy No. | | | Claim No: SNM | 4D205048C02 | |
| Sum Insured: Make of Veh: (Client's Record) | | | | 12019 | |
| | | 12/02/2020 G | 01+30am | MOD Estates | |
| Date/Time: | | Person Contacted: | Vehicle IN | / OUT | atribate. |
| Date/Time: _ Date/Time: _ | 2001/20 Subm | irmed with Fin nit Final Fig £4,100 /_ | al Fig,d | ays (Red S/_ | %; Original_7 days) |
| 25/1/2020 | 6292 SE | leed with the lawyer Co | imie) will Remye | fur RI soon. | |
| | arts found no | led with the lawyer Co | | for RI SOON. B. LR, Etc.) | |
| Рага(1) : Р | arts found no | led with the lawyer Co | ghlight R or U | B _{s,} LR, Etc) | |
| Рага(1) : Р | arts found no | ot replaced (To his | ghlight R or U | B _{s,} LR, Etc) | |
| Рага(1) : Р | arts found no | ot replaced (To his | ghlight R or U | B _{s,} LR, Etc) | |
| Para(1) : P Para(2) : C | arts found no | ot replaced (To his | ghlight R or U | B _{s,} LR, Etc) | |
| Para(1) : P Para(2) : C | arts found no | ot replaced (To his | ghlight R or Un | B _{s,} LR, Etc) | Date: |
| Рага(1) : Р | arts found no | et replaced (To his | ghlight R or U | nsistent: NC) | \dd 150 |
| Рага(1) : Р | arts found no | et replaced (To his | ghlight R or Un | Fee Charged Basic & / Transport Photos Others | \dd 150 |
| Para(1) : P Para(2) : C | ett Value Market Value Salvage Value Nett Value | et replaced (To his | ghlight R or United States (Parts Not Co | Fee Charged Basic & / Transport Photos Others Total | Add 150 |
| Para(1) : P | ett Value Market Value Salvage Value Nett Value | ot replaced (To his | ghlight R or Un | Fee Charged Basic & / Transport Photos Others | 150 |

| anotox | | ENT (Office) | | | | |
|---------------------------------|--|--------------|----------|------------------|---------|---------|
| From (Person | chang burn Sen of CT | I | T | hte/Time: | 1.11.19 | 1151 ax |
| Estimated Co | | Bill to: | | Ulicada Villacia | | |
| To Inspect Vo | s/TP RES/OD RES/EVA/INV/MV/C | 28 | Insured: | χç | 42345 | |
| at Workshop | Tempha h fu Lone 10 \$01-406 | | | 9299 | | |
| Policy No. D | mcvsn18275919011 | Claim No: | Sym MI | 205 64 | 18 (02 | |
| Sum insured: | | Excess: | | | | |
| Make of Veh (Client's Record | | | 11 | .O.A. 20 | 10-19 | 1 |
| CA / REV Date/Time; | / REP. / REV 24 HRS //// 1.357 m Person Contacted: | Shaun | Ve | H.O.D. End | | |
| Date/Time | Action/Instruction (X) Estimate | | | | | |
| | XE 41195 - VA (1) MOOTE | 16/ 80 | b.o.A | - 01/0 | 6/2019 | |
| | Dismartle: 11/11/2019 | | | | | |

| STATE HAN DE COL | SSIGNMENT STORY |
|---|---|
| | |
| Front Date | Veh No. Small 73884 STATESPAY Room 20 /014/2017 |
| Estimated Cont | Type: M.Cacl M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / |
| OD / TP / WS / TP RES / OD RES / EVA / INV / MV | Truck / Trailer or |
| o Inspect Vehicle No: | Make: usurands #200h as 1796 |
| it Workshop m/s | Colour Stured / Std / NI / NA |
| d | Sp.Reading /54527/T/Radio: Insured / Std / NI / NA |
| nsured | Eng/No: |
| Policy No | CNO: WDB 21/04/26375034 |
| Chaims No. | Gen. Cond: Good / Fair / Poor / Burnt |
| Sum Insured: Excess: | Steering: [norder / Jammed / Leaked / Burnt or |
| (Client's Record) | Brake: Inerder / Jammed / Leaked / Burnt or |
| Make of Vetx. | Modi: Nil (S/Rim / STD A/Rim or |
| | Tyre Size F: 2 45 / 40/n/8 |
| (Policy Candillon) | R: 265/35/118 |
| | BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / |
| repair at the time of inspection. | TOYO / YOKO or |
| Bal. or Market Value | Front Pulsa Rear 7/ |
| IDAC Accident Rport: Consistent? : Yes or No | R/Bal. 7 Nm R/Bal 7 mm |
| GIA / PR Seen Consistent? : Yes or No | L/Ball 7 mm L/Ball 7 mm |
| Est Repairs days Res. Yes or No | DOA 20/14/m DOI 12/2/20 |
| Lum Sum: % 3 Val.: Yes or No | Survey held at Jeannt by ander |
| | Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or |
| CA / REV / REP. / 24 HRS Vehicle: IN / | |
| Date: Person Contacted: | The U/C / Chassis frame / Body Structure affected due to collision |
| Date / Time Action / Instruction + phone + lu noted over | 0/mdy -7(Smn 938+4) new manto (STP 9625K)+0/d |
| parage mayor pro- | (20/2/2020 |
| un _64000 | (57/2/2020 |
| un _64000 | (20/2/2020 |
| | (57p 7 (25 K) 70/2 / 20/2 (20/2) |
| W - 33 483 NV - 30500 | Days Of Repair: |
| W - 33 483 NV - 30500 Dane/Ime, File Page 107 : Prell. Report : Final Report | Days Of Repair: Resurvey No. of Trip: Survey Fee: |
| W - 33 483 NV - 30500 Dome/Time, File Pass 167 : Prell. Report : Final Report Design/Time, File Pass 167 | Days Of Repair: Resurvey No. of Trip: Survey Fee: Transposition |
| Inv _ 64000 V - 33483 NV - 30500 Prell. Report Final Report Code/Time, File Fadem for | Days Of Repair: Resurvey No. of Trip: Survey Fee: Trimposition Site Insp. (\$ 3 - 85 - 14 |
| Inv _ 64000 PV - 33 483 NV - 30500 Deserting, File Pass 60 : Preli. Report : Final Report Deserting, File Pass 60 : Final Report | Days Of Repair: Resurvey No. of Trip: Survey Fee: Tomposition Site Imp (\$ 3 - 88 |
| Intel/Intel. File Pass Int Delie/Time, File Pass Int Delie/Time, File Pass Int Delie/Time, File Pass Int Acted Acted | Days Of Repair: Resurvey No. of Trip: Survey Fee: Trimpolition Site Insp. (\$ 3 - 85 - 14 |



Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time :

13 Nov 2019 / 15:47:15

Receipt Date/Time:

13 Nov 2019 / 15:47:14


Tax Invoice/Receipt

Receipt No.: ITNET-00000-191113-002199

| Receipt No.: ITNET-00000-191113-002199 | | Owi | w Ext | My Nuch | - de |
|--|--------------------------|-------------------------------|-----------------------|--------------------|------|
| Previous Receipt No. : | | | | Amount | 1 |
| S/N Item Description/ Business Transaction Reference No. | | Amount Before GST (S\$) | GST Amount (SS) | After GST (S\$) | |
| Replaced Vehicle No. SJP9625K 1 Replacement of Veh Reg No SMN9388t Replacement Fee 20191113154428627647 | J | 300.00 | 21.00 | 321.00 | |
| | Sub-Total | 300.00 | 21.00 | 321.00 | |
| | Total Before Rounding | 300.00 | 21.00 | 321.00 | |
| | Rounding Difference | | | 0.00 | |
| | Total Amount Payable | | | 321.00 | |
| | Paid By | | | | |
| | хххххххххххххххххххх | Credit Car /Master | | 321.00 | |
| | Total | | | 321.00 | |
| | Cash Change | | | 0.00 | |
| | Tendered Amount | | | 321.00 | |
| | Excess Refundable Amount | | | 0.00 | |
| | | | | | |

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



JEMENTAH MOTOR WORKS

Blk 14 Defu Lane 10 #01-406 Singapore 539195 H/P: 9299 6636 Fax: 6285 7054

Date of accident : 22-Oct-19

Name

: Woon Ming Hwa

Address

: C/o: Blk 14 Defu Lane 10 #01-406

Singapore 539195

Final repair cost of SJP 9625 K

Lump Sum Repair Costs

11,200.00

Singapore Dollars : Twelve Thousand And Two Hundred Only.



CL APPRAISER PTE LTD

Vehicle Registration No: SJP 9625 K

Our Ref No: JMW/11/1903/TP

| Qty | Description Conditions | | | tepairer's Estimate | | Revised Amount | |
|-----|--|-----------|----|------------------------|----|-------------------|-----|
| | SPARE PARTS - LIST ITEMS | | | | | | |
| î | Front o/s door × repair | Repair | S | 2,235.00 | | | |
| 1 | Rear o/s door V replace | Damage | S | 2,235.00 | S | 2235.0015 | |
| 1 | Rear o/s lock / replace | Damage | S | 445,00 | S | 145.00 € | 19 |
| 1 | Rear o/s chrome protector / replace | Damage | S | 175.00 | S | 175.00 ∪ | 1 |
| 1 | Rear o/s door regulator Peplace | Damage | S | 358.00 | S | 358.00 21 | |
| 1 | Rear o/s regulator motor / replace is | Damage | S | 485.00 | S | 485.00 3 | |
| 1 | Rear o/s door weatherstrip / replace | Damage | S | 280.00 | S | 195.00 ~ | |
| 1 | Rear windscreen repair kit × (500) | Necessary | S | 195.00 | S | 195.00 | |
| 1 | Rear bumper × (reperr) | Repair | S | 2,094.00 | | | |
| 1 | Rear bumper side retainer × (svc) | Intact | 5 | _48.00 | | | |
| 1 | Rear o/s fender × repair | Damage | \$ | 2,185.00 | \$ | 2,185.00 | |
| 1 | Rear o/s sport rim V replace | Damage | S | 1,200.00 | S | 1200.00 5 | - 4 |
| 1 | Rear o/s wheel bearing with hub Replace | - Damage | S | 316.00 | 5 | 316.00 ₩ | |
| 1 | Rear o/s shock absorbers | Damage | \$ | 520.00 | \$ | 520.00 | |
| 1 | Rear o/s knuckle arm | Damage | S | 1,265.00 | S | 1,265.00 | |
| 1 | Rear o/s control arm | Damage | S | 530.00 | S | _530.00 | |
| 1 | Rear o/s lower arm (x (50 c) | Damage | 5 | 520.00 | 5 | 520.00 | |
| 1 | Rear o/s stay arm | Damage | S | 608.00 | 5 | 608.00 | |
| i | Rear o/s top arm | Damage | S | 435.00 | S | 435.00 | |
| 1 | Rear o/s tailing arm | Damage | \$ | 440.00 | S | 440.00 | |
| *: | Actual of the state of the stat | | S | 16,569.00 | \$ | 12,107.00 | |
| | | Less 10% | S | 1,656.90 | 8 | 1,210.70 | |
| | Total Cost - List Items | | S | 14,912.10 | S | 10,896.30 | |
| | SPECIAL NETT ITEMS | | | | | | |
| î | Rear o/s tyre (Depreciation) X (50 c) | Damage | S | 550.00 | 5 | 275:00 | |
| | Total Cost - Special Nett items | | \$ | 550.00 | S | 275.00 | |

Total cost of parts

| S | 15,462.10 | \$ 11,171.30 |
|---|-----------|-----------------|
| - | 20100000 | |



C L APPRAISER PTE LTD

Our Ref No: JMW/11/1903/TP

| S/No | Description | | epairer's Estimate | Revised Amount | |
|------|---|------------------|-----------------------|-------------------|-----------|
| | Total cost of parts c/f | S | 15,462.10 | S | 11,171.30 |
| | <u>LABOUR</u> | | | | |
| 1 | To remove, refit, replaced damaged lamps and check up rear electrical wiring | S | 80.00 | \$ | 58.00 |
| 2 | To remove and refit inner garnishes, inner trim to X assist repair. | \$ | 150.00 | \$ | 120.00 |
| 3 | To remove and refit rear undercarriage. | \$ | 350.00 | S | 300.0 |
| 4 | To conduct wheel alignment. | \$ | 150.00 | \$ | 120.0 |
| 5 | To remove and refit rear windscreen glass. | \$ | 180.00 | \$ | 120:0 |
| 6 | To remove and refit doors complete fittings and replace damaged parts, transfer all fittings to new door. | \$ | 150.00 | S | 120:0 |
| 7 | To apply undercoating on repaired and replaced panel. | s | 100.00 | S | 50.0 |
| 8 | To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damaged consistent to the accident. | / _N S | 1,200.00 | s | 1,000.0 |
| 9 | To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident. | S | 1,000.00 |) \$ | 880. |
| | 37/9.10 - GRAND TOTAL Suffer | -\$ | 18,822.1 | 0 5 | 13,941. |
| | 10% Gainsplan 11:300 | | | | |
| | 17.80 met 100 |) | | | |
| | TO SONN | + | | | |





Vehicle Registration No: SJP 9625 K

Our Ref No: JMW/11/1903/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of: \$ 11,200.00

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notifed the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD

Cheong K. H

Automotive Appraiser

CL APPRAISER PTE LTD

24 Penshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

INVOICE

Invoice No:

CL/191329

Woon Ming Hwa C/o: Jementah Motor Works Blk 14 Defu Lane 10 #01-406 Singapore 539195

Ref No:

JMW/11/1903/TP

Date:

15 November 2019

DESCRIPTION

AMOUNT

OUR SERVICE FEE CHARGES:

- SURVEY INSPECTION FOR VEHICLE NO. SJP 9625 K
- RESURVEY INSPECTION
- DIGITAL PHOTOGRAPHS SERVICES
 (INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)
- TRANSPORTATION

GRAND TOTAL

S\$ 819.00

E & O. E

All cheque payment should be "Crossed" and made payable to " C L APPRAISER PTE LTD "

We shall be grateful if you could forward our payment at your early convenience.

CL Appraiser Pte Ltd



Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Woon Ming Hwa

Date

: 15 November 2019

C/o: Jementah Motor Works

Our ref

: JMW/11/1903/TP

Blk 14 Defu Lane 10

#01-406 Singapore 539195

Accident Date

: 22 October 2019

Type of Survey

: Third Party

Inspection Date : 4 November 2019

Repairer Name

: Jementah Motor Works

Blk 14 Defu Lane 10

#01-406 Singapore 539195

PARTICULARS OF VEHICLE

Registration No : SJP 9625 K

Year / Capacity

: 2009 / 1796 cc

Make / Model

: Mercedes Benz E200

Colour

: Black

Chassis No

: WDB2110412B395034

Mileage

: 149225

Engine No

: 27195631124758

CONDITION OF TYRES

| | | Make | Size | Thread Balance | Rim |
|----------------|----|----------|------------|----------------|-------|
| Front Nearside | | Michelin | 245/40 R18 | 5 mm | Sport |
| Front Offside | 12 | Michelin | 245/40 R18 | 5 mm | Sport |
| Rear Nearside | | Michelin | 245/40 R18 | 5 mm | Sport |
| Rear Offside | 3 | Michelin | 245/40 R18 | 5 mm | Sport |

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the o/s portion. (Details refer to the photographs attached)

Enclosed number of photographs:

74

copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a Lump Sum of \$ 11,200.00 on a contractual basis.

Under normal circumstances, the repair period would be about 7 (Seven) working days.



JEMENTAH MOTOR WORKS

Blk 14 Defu Lane 10 #01-406 Singapore 539195 H/P: 9299 6636 Fax: 6285 7054

Date of accident : 22-Oct-19

Name

: Woon Ming Hwa

Address

: C/o: Blk 14 Defu Lane 10 #01-406

Singapore 539195

Final repair cost of SJP 9625 K

Lump Sum Repair Costs

11,200.00

Singapore Dollars: Twelve Thousand And Two Hundred Only.

CL APPRAISER PTE LTD

24 Penshurst Place, Singapore 556440 Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783 Reg No: 201000228E

INVOICE

Invoice No:

CL/191329

Woon Ming Hwa C/o: Jementah Motor Works

Blk 14 Defu Lane 10

#01-406 Singapore 539195

Ref No:

JMW/11/1903/TP

Date:

15 November 2019

DESCRIPTION

AMOUNT

OUR SERVICE FEE CHARGES:

- SURVEY INSPECTION FOR VEHICLE NO. SJP 9625 K
- RESURVEY INSPECTION
- DIGITAL PHOTOGRAPHS SERVICES
 (INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)
- TRANSPORTATION

GRAND TOTAL

S\$ 819.00

E&O.E

All cheque payment should be "Crossed" and made payable to " C L APPRAISER PTE LTD "

We shall be grateful if you could forward our payment at your early convenience.

CL Appraiser Pte Ltd



Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783 Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Woon Ming Hwa

Date

: 15 November 2019

C/o: Jementah Motor Works

Our ref

: JMW/11/1903/TP

Blk 14 Defu Lane 10

#01-406 Singapore 539195

Accident Date

: 22 October 2019

Type of Survey : Third Party

Inspection Date

: 4 November 2019

Repairer Name

: Jementah Motor Works

Blk 14 Defu Lane 10

#01-406 Singapore 539195

PARTICULARS OF VEHICLE

Registration No

: SJP 9625 K

Year / Capacity

: 2009 / 1796 cc

Make / Model

: Mercedes Benz E200

Colour

: Black

Chassis No

: WDB2110412B395034

Mileage

: 149225

Engine No

: 27195631124758

CONDITION OF TYRES

| | | Make | Size | Thread Balance | Rim |
|----------------|----|----------|------------|----------------|-------|
| Front Nearside | | Michelin | 245/40 R18 | 5 mm | Sport |
| Front Offside | 1 | Michelin | 245/40 R18 | 5 mm | Sport |
| Rear Nearside | 1 | Michelin | 245/40 R18 | 5 mm | Sport |
| Rear Offside | 12 | Michelin | 245/40 R18 | 5 mm | Sport |

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the o/s portion. (Details refer to the photographs attached)

Enclosed number of photographs:

74

copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a Lump Sum of \$ 11,200.00 on a contractual basis.

Under normal circumstances, the repair period would be about 7 (Seven) working days.



CL APPRAISER PTE LTD

Vehicle Registration No: SJP 9625 K

Our Ref No: JMW/11/1903/TP

| Qty | Description Conditions Repairer's Estimate | | | Revised Amount | | |
|-----|--|-----------|----|-------------------|----|-----------|
| | SPARE PARTS - LIST ITEMS | | | 15 | 4 | |
| 1 | Front o/s door | Repair | S | 2,235.00 | | |
| 1 | Rear o/s door | Damage | S | 2,235.00 | S | 2,235.00 |
| 1 | Rear o/s lock | Damage | S | 445.00 | S | 445.00 |
| 1 | Rear o/s chrome protector | Damage | S | 175.00 | \$ | 175.00 |
| 1 | Rear o/s door regulator | Damage | S | 358.00 | \$ | 358.00 |
| 1 | Rear o/s regulator motor | Damage | S | 485.00 | S | 485.00 |
| 1 | Rear o/s door weatherstrip | Damage | S | 280.00 | S | 195.00 |
| 1 | Rear windscreen repair kit | Necessary | S | 195.00 | S | 195.00 |
| 1 | Rear bumper | Repair | S | 2,094.00 | | |
| 1 | Rear bumper side retainer | Intact | \$ | 48.00 | | |
| 1 | Rear o/s fender | Damage | S | 2,185.00 | S | 2,185.00 |
| 1 | Rear o/s sport rim | Damage | \$ | 1,200.00 | S | 1,200.00 |
| 1 | Rear o/s wheel bearing with hub | Damage | S | 316.00 | \$ | 316.00 |
| 1 | Rear o/s shock absorber | Damage | S | 520.00 | S | 520.00 |
| 1 | Rear o/s knuckle arm | Damage | \$ | 1,265.00 | S | 1,265.00 |
| 1 | Rear o/s control arm | Damage | S | 530.00 | \$ | 530.00 |
| 1 | Rear o/s lower arm | Damage | S | 520.00 | S | 520.00 |
| 1 | Rear o/s stay arm | Damage | \$ | 608.00 | S | 608.00 |
| 1 | Rear o/s top arm | Damage | S | 435.00 | S | 435.00 |
| i | Rear o/s tailing arm | Damage | S | 440.00 | \$ | 440.00 |
| • | Treat of a time and | | \$ | 16,569.00 | \$ | 12,107.00 |
| | | Less 10% | S | 1,656.90 | \$ | 1,210.70 |
| | Total Cost - List Items | | S | 14,912.10 | \$ | 10,896.30 |
| | SPECIAL NETT ITEMS | | | | | |
| 1 | Rear o/s tyre (Depreciation) | Damage | S | 550.00 | S | 275.00 |
| 1.5 | Total Cost - Special Nett items | | S | 550.00 | 5 | 275.00 |

Total cost of parts

| S | 15,462.10 | S | 11,171.30 |
|---|-----------|---|-----------|





Vehicle Registration No: SJP 9625 K

Our Ref No: JMW/11/1903/TP

| S/No | Description | 1954 | epairer's Estimate | Revised Amount | | |
|------|--|------|-----------------------|-------------------|-----------|--|
| | Total cost of parts c/f | s | 15,462.10 | S | 11,171.30 | |
| | <u>LABOUR</u> | | | | | |
| 1 | To remove, refit, replaced damaged lamps and check up rear electrical wiring | S | 80.00 | S | 50.00 | |
| 2 | To remove and refit inner garnishes, inner trim to assist repair. | S | 150.00 | \$ | 120.00 | |
| 3 | To remove and refit rear undercarriage. | S | 350.00 | S | 300.00 | |
| 4 | To conduct wheel alignment. | S | 150.00 | S | 120.00 | |
| 5 | To remove and refit rear windscreen glass. | 5 | 180.00 | S | 120.00 | |
| 6 | To remove and refit doors complete fittings and replace damaged parts, transfer all fittings to new door. | \$ | 150.00 | S | 120.00 | |
| 7 | To apply undercoating on repaired and replaced panel. | S | 100.00 | S | 60,00 | |
| 8 | To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damaged consistent to the accident. | S | 1,200.00 | S | 1,000.00 | |
| 9 | To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident. | S | 1,000.00 | 5 | 880,00 | |
| | GRAND TOTAL | 5 | 18,822.10 | S | 13,941.30 | |





Vehicle Registration No: SJP 9625 K

Our Ref No: JMW/11/1903/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of: \$ 11,200.00

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notifed the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.


Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD

Cheong K. H

Automotive Appraiser



ASSIGNMENT SJP 9625/ YIROGA: 21/94/2019 Estimates Cost: Type M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / OD/TRIWS/TRRES/OD RES/EVA/INV/MV Truck / Trailer or To inspect Vehicle Na: MBCORPS E200 C Mickey at Workstop m/s Colput BILL 14 Dofu live 10 #01-460 ROSSING AJC: _. Insured / Std / NI / NA 149225 Lu TRadio: Insured / Std / NI / NA fisund: EngiNo. Patier No. Citio WD821104128395034 Claims No Gen Cont Foot | Fair / Poor / Burnt Sym Imperca Sivering Forder I Jammed I Leaked I Burnt or Excess (Client's Firecord) norder I Jammed I Leaked I Burnt or More of Volc. MIL SIRIN I STD AIRIN OF 245/40/2019 Time Sign: (Policy Condition) 265/35/n18 Remove The yell had commenced its 105 OIS ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / repair at the time of inspection. TOYO/YOKO or Bail of Manual Value Erora L Rear (DAC Assert Rport Consistent? Tex or for RIBal GIA / PR Son Consistent? : Yes or No Est Propriy dovs Esst Yes of A-D.D.). Lim Son I Wat I Yes or he CA | REV | REP. | 24 HRS an of Demages : Frt / Rear (0/9) I N/S I U/C I Rooffop or WILL INTOUT Ferent Consolec 100 U/C / Chassis frame / Body Structure affected due to coffision. 5TP 9625K 0064 MV - 64000 13/12/2019 12 V-33483 30500 S DEC 2019 Des Bertreres P. Report Days Of Repair: Final Report Resurvey No. of Trip: Survey Fee: 140 Designation of the Later Transportation. rid Fee: Site Into (\$ 3 . RS_SI interview (5 Physical PRS. Festi Inve 19 Day 19 14-14-16 E

109.00

Nivitha (LKK Auto)

From:

Irene Tay <irene.tay@sg.cntaiping.com>

Sent:

Friday, 27 December 2019 5:01 PM

To:

winnie@yoga-legal.com 'assignments'; Admin A

Cc: Subject:

FW: CTP REF NO. SNM19D205048C02 CY REF NO. CY.10709.19.PD.JM(HW).WP(PT) -

ACCIDENT INVOLVING SJP9625K & XE4239S ON 22 OCTOBER 2019

Importance:

Hìgh

Dear Sir/Mdm (LKK),

We refer to the above matter.

Please get your surveyor to liaise with JEMEMTAH MOTOR WORKS to conduct REINSPECTION.

Regards,

Irene Tay

Executive

Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896192 | F:(65) 62247478/62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: winnie@yoga-legal.com [mailto:winnie@yoga-legal.com]

Sent: Thursday, December 26, 2019 12:21 PM To: Irene Tay <irene.tay@sg.cntaiping.com>

Subject: RE: CTP REF NO. SNM19D205048C02 CY REF NO. CY.10709.19.PD.JM(HW).WP(PT) - ACCIDENT INVOLVING

SJP9625K & XE4239S ON 22 OCTOBER 2019

Importance: High

Dear Irene

We refer to your email on 18 December 2019.

Our client's vehicle SJP 9625K is available for resurvey on 2 January 2020, 11.30a.m. at 14 Defu lane 10 #01-406 Singapore 539195.

Kindly let us have your confirmation and details of your appointed surveyor.

Thank you.

Regards,

Winnie Phee

M/s C. YOGARAJAH LLC

883 North Bridge Road

#11-03 Southbank

Singapore 198785

Tel

: (65) 6292 5838

Fax : (65) 6292 5938

Email: winnie@yoga-legal.com

(UEN No. 201333127N) (GST Reg No. 201333127N)

Important Note: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6292 5838, if you have received this message in error. Thank you.

From: Keline Tung < keline@yoga-legal.com> Sent: Thursday, 19 December 2019 9:36 am To: Winnie < winnie@yoga-legal.com> Cc: Irene Tay < irene.tay@sg.cntaiping.com>

Subject: Fwd: CTP REF NO. SNM19D205048C02 CY REF NO. CY.10709.19.PD.JM(HW).WP(PT) - ACCIDENT INVOLVING

SJP9625K & XE4239S ON 22 OCTOBER 2019

FYA

----- Forwarded message ------

From: Irene Tay < irene.tay@sg.cntaiping.com>

Date: Wed, Dec 18, 2019 at 8:17 PM

Subject: CTP REF NO. SNM19D205048C02 CY REF NO. CY.10709.19.PD.JM(HW).WP(PT) - ACCIDENT INVOLVING

SJP9625K & XE4239S ON 22 OCTOBER 2019

To: Keline <keline@yoga-legal.com> Cc: Keline <keline@yoga-legal.com>

WITHOUT PREJUDICE

Dear Sir/Mam.

We refer to the above captioned matter and your letter dated 29 November 2019.

We will want to conduct a REINSPECTION on your client's vehicle.

Please let us have the DATE, TIME & VENUE before we inform our surveyor.

Meanwhile, please let us have a copy of the TRAFFIC POLICE RESULT & WITNESS STATEMENT if any.

| Kindly, please withhold any further legal proceedings. |
|---|
| Thank You. |
| |
| Regards, |
| Irene Tay |
| Executive |
| |
| Claims Department (Motor Division) |
| |
| China Taiping Insurance (Singapore) Pte. Ltd. |
| 3 Anson Road #16-00 Springleaf Tower Singapore 079909 |
| Direct (65) 6389 6192 Fax (65) 62247478/62247175 |
| Email: claimsdept@sg.cntaiping.com |
| www.sg.cntaiping.com |
| |
| |
| Disclaimer: |
| This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately. |
| |
| |
| |
| |
| |
| |
| Regards |
| Keline Tung (Ms) |
| · · · · · · · · · · · · · · · · · · · |

M/s C. YOGARAJAH LLC

883 North Bridge Road

#11-03 Southbank

Singapore 198785

(UEN No. 201333127N)

(GST Reg No. 201333127N)

Tel

: (65) 6292 5838

Fax

: (65) 6292 5938

Email

: keline@yoga-legal.com

Important Note: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6292 5838, if you have received this message in error. Thank you.

Nivitha (LKK Auto)

From:

Nivitha (LKK Auto) <admin-d@lkkauto.com>

Sent:

Monday, 30 December 2019 10:35 AM

To:

'Irene Tay'

Cc:

'assignments'; 'sur@lkkauto.com'

Subject:

RE: CTP REF NO. SNM19D205048C02 CY REF NO. CY.10709.19.PD.JM(HW).WP(PT) -

ACCIDENT INVOLVING SJP9625K & XE4239S ON 22 OCTOBER 2019

Dear Irene,

Thank you for the assignment.

I have called and confirmed that date and time for the re-inspection.

We have confirmed on the 02nd of January 2020 @11.30am.

Thus kindly assist to provide us the TP survey report, and coloured photographs in order to proceed for the Reinspection.



Wishes you a Merry Christmas & Happy New Year 2020

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Irene Tay [mailto:irene.tay@sg.cntaiping.com]

Sent: Friday, 27 December 2019 5:01 PM

To: winnie@yoga-legal.com

Cc: 'assignments' <assignments@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: FW: CTP REF NO. SNM19D205048C02 CY REF NO. CY.10709.19.PD.JM(HW).WP(PT) - ACCIDENT INVOLVING

SJP9625K & XE4239S ON 22 OCTOBER 2019

Importance: High

Dear Sir/Mdm (LKK).

We refer to the above matter.

Please get your surveyor to liaise with JEMEMTAH MOTOR WORKS to conduct REINSPECTION.

Regards.

Irene Tay

Executive

Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.

MSUU19140793 / Success United Pte Ltd - HQ ENTRY DATE & TIME: 20/10/2019 16:30 SUBMITTED BY: Teo Wee Keong

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation,
- 5. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 23/10/2019 16:30

Date Of Accident 22/10/2019 18:20

Exact Location Of Accident BARTLEY ROAD EAST

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJP9625K

Insured/Policyholder

Name Of Registered Owner WOON MING HWA

NRIC No S1392759F

Email Address WMHWA@YAHOO.COM

Mobile Phone No (LOCAL) +65-98587723

Alternative Phone No Others-98587723

Vehicle Particulars

Manufacturer MERCEDES-BENZ

Model E200K

Exact Purpose for which vehicle was being used at time of accident

SINCEOTO CHITATE DE C

Are you claiming under your own insurance policy for N

repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company HL ASSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number MP306862

Cover Note Number

Driver

Name of Driver WOON MING HWA

NRIC No S1392759F

Date Of Birth 07/03/1959

Occupation INDOOR

Date Of Driving Pass 11/06/1979

Driving Experience 40 YEARS AND 4 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-98587723

Fax Number

Contact Number OTHERS-98587723

EMail Address WMHWA@YAHOO.COM

Address BLK 28 CHOA CHU KANG STREET 64 #03-01

SINGAPORE

Postcode 689097

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

soliciang content dame assistance.

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN AND ATTACHMENT.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

1

Vehicle Registration Number XE4239S

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

GOODS VEHICLE BOSE KANNAN F7960529T 93714961 Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- There was a property the professional management to sever up the court property
- The Part of the Completed by the Policyholder and/or the Authorised Origin
- In the matter property must be an truthful and accurate as possible. Any north-membrane are extraording of material facts may allow could according to property application.
- The base and increasing of this form by character companies a risk to left-cover of purish lighted on the part of the insulation companies.
- Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurans of the QN Records Management Centra assabletion by the Serious I insurance Association of Engapore (GIA) for archiving and that sopressit this report will for a fee be made evaluation by interested parties.
- By the longment of this report to the insurers you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesoid.
- E. Content under the Parsonal Data Protection Act (PDPA)

sunderstand, authomorph, agree and content that

- (a) Malmore, my workshop and the General Inturance Association of Engapore | 'GIA' | may are permitted to collect, use, disclose and/or process my perional data/personal information set but in this [form] and any other personal information provided by my or possessed by my inturer ((ellectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers", the insurers' lawyers/law forms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposals) of
 - processing, handling and/or dealing with my colors including the settlement of the Items and any necessary investigations relating to the claims:
 - (ii) Investigating the atcident and/or my claims.
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - I'v) administering my claims limituding the mailing of correspondence, statements, involves, reports or notices to me, which could involve distincture of certain personal data about me to bring about delivery of the same as well as on the external cover of anyelopes/mail packages; and/or
 - (ii) complying with approach law in administering, processing, handling and/or dealing with my claims. Instrument the "Purposes";
- (b) all mouver's justo have insured vehicle(s) involved in this account and the insurer's lawyers/law forms, may are permitted to collect, use, disclose and/or process, my Personal information for one or more of the above Purposes, and
- (ii) my Record Information may can be exclused by any of the insurers and/or GiA to their third party service providers or agents/lincluding their lawyers/law firm(), which may be stied outside of Singapore, for one or more of the above Purposes.
- [3] The Personal Intermentation will also be collected and used to simple plants history for the purpose of travel detection, messagation and management in present and all future course.
- (#) the information up collected under (d) above may be insired / disclosed.
 - 10 Willinstrang and/or any other trief patters that assist in evaluating, investigating, controlling or managing frame regulation, less arthrophent and government agencies at resonably required for the surposes states, or
 - in forcementing with requirements under any regulations, fawcon countriesers

and

Down Sparce Score Legisland 1.0

ALC: U

Sketch Plan #2

SKETCH PLAN

| | | | CIDENT | |
|--|--|--|--------|--|
| | | | | |
| | | | | |

| Refer to affaction and (4 pages) | |
|------------------------------------|--|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| CLARATION | |


We drive the foregoing performing the true in every project

MA

23 Oct 19 1515 hr Congres Signature This was a few the composition This deliver

Reducing Colone Persons, 1 Syllabore Higher Historica

ACCIDENT LOCATION



ACCIDENT DESCRIPTION

Report - Accident along Sertley Board Exet other Upper Paya Labor Road towards Sertley Road on 22 Oct 2019 at about 6.20 pm

OH 22 DH 2019 at smoot 5.20 cm. I was driving in my venicle MD 5.210 SUP 9225K, plany the site road after Lipper Pays Lanux Road. I was mavelling on the left time of the site road business factors Road. The site road was bonde Santley Road Eject Byover. The site road is a Z-lane road. merging into one time covards the end of Bartley East Rood.

The weather was over. The day was sold tright and visiting was good. Evening traffic was very nearly. Along the site road, supedially towards the 2-lifes 1 maged lane, the vehicle were crisiving, theying stooly into one lane.

east moving behind a set and was oppositiving the entource of the marged 1 lane. The car in front of me was precedy in the marged single land. The post aims on the right was filled with vehicle contrag from the Bartley Wood bast his/weet. From my darried minor I save a Marcades lager laws. (XB42325) behind the There was precidedly not enough room on the right beside of my car for another subtice to move in Through my right was interest I save the Marcades to persect moving over and inching lowers the rear of my car. As I confirme to roll saring the silphoid to my surprise, the folial continued to move even shall be foliate in realized in the lace of my car. As I confirme the movement of the laced entour continues and the foliate of the laced entour continues along the lace of my car was deep analyzed digitary to the lace to the lapse basis continues in overview to well as

got our of my currions the front passanger over locause the right contrained be opened to see the effective. The types truck where was on the very edge of the right sere marking of the origing land, indicaling that it was someoning into the left of the reeignd lank than counting my our right sale. The hyper truck onserve an indust national foreign sector.

- As a result of the muck carleding making car, the distrages on my sur set.

 1) Right hand side of the car from right side of rear burniar to driver door was elemeged. Distraction in opening the rear right soor.

 2) Rear right sport rat has damage. Can feel slight vibration while thinking.

 3) Rear right yet side canage. Can have about while driving.

 4) Rear right sets accesses at the fest side front and rear doors became not working.

Three was apparently no namego on the apper suck

Photographs of the accident and my car stamages employed

Wood Ming Tries

After consumer



Touch againstrip in way to the left. The trace right phends have on udge of larger in a cog. It such the partition the near size deplaced our reconstruction and





Darrages























CHASSIS NUMBER





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to | Federation | Internationale | Des Experts | En Automobile | |
|---------------|------------|----------------|-------------|---------------|--|
|---------------|------------|----------------|-------------|---------------|--|

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI19019320/Hsf3e2-1

| | ISON ROAD #16-0 INGLEAF TOWER | 00 SINGAPORE 079909 | Date : 24-02-2020 Code : CTI | | |
|--|--|---|----------------------------------|------------------------|--|
| 1. | Po | licy Particulars :- THIRD PA | ARTY CLAIM (RESURVEY INSPECTION) | | |
| | Insured Veh. | XE 4239S | Veh. Inspected | SJP 9625K | |
| | Policy No. | DMCVSN18275919011 | Coverage (\$) | 0.00 | |
| Claim No. SNM19D205048C02 | | Excess (\$) | 0.00 | | |
| | Assign From | IRENE TAY | Assign Date | 27/12/2019 | |
| 2. | in the same | Vehicle Pa | rticulars & Condition | | |
| | Make & Model | MERCEDES BENZ E200 K | c.c | 1796 | |
| Engine No. HIDDEN Chassis No. WDB2110412B395034 Odometer 154527 | | Year of Reg. | 2009 | | |
| | | Colour | BLUE | | |
| | | Steering | IN ORDER | | |
| | Brakes IN ORDER | | Modification | SPORTS RIM | |
| | General | GOOD | | | |
| 3. | The state of the s | Cond | litions of Tyres | I - Market I I I I I I | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 245/40 R18 | PIRELLI | 7 mm | |
| | L/H Front Tyre | 245/40 R18 | PIRELLI | 7 mm | |
| R/H Rear Tyre 265/35 R18 | | 265/35 R18 | PIRELLI | 7 mm | |
| | L/H Rear Tyre | 265/35 R18 | PIRELLI | 7 mm | |
| 4. | 181-19 | Descrip | otion of Damages | | |
| THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS. | | | | | |
| 5. Gen | | ral Information | | | |
| | Accident Date | 22/10/2019 | Inspection Date | 12/02/2020 | |
| | Survey held at JEMENTAH MOTOR WORK | | 3 | | |
| | | BLK 14 DEFU LANE 10 #01-406 SINGAPORE 539195 | | | |
| 5a. | | and seeing the p | Remarks | | |
| | A)THE INSPECTION B)IN ACCORDANG | ON WAS CONDUCTED ON A'V CE TO YOUR INSTRUCTIONS, | WE HAVE NOT AUTHORI | SIS. SED REPAIRS. | |
| 5b. | The State of the Land | Estima | te Days of Repair | | |
| | ESTIMATED NOR | MAL PERIOD FOR REPAIR: | 5 Working Day | ys | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 9625K

| у | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|--|------------------------|------------------------------|----------------------|
| П | REPLACEMENT OF PARTS | | | |
| 1 | FRONT O/S DOOR | REPAIRED SEE LABOUR | 2,235.00 | 1.0 |
| 1 | REAR O/S DOOR | REPLACED | 2,235.00 | 1,520.80 |
| 1 | REAR O/S LOCK | REPLACED | 445.00 | 298.80 |
| 1 | REAR O/S CHROME PROTECTOR | REPLACED | 175.00 | 175.00 |
| 1 | REAR O/S DOOR REGULATOR | REPLACED | 358.00 | 280.50 |
| 1 | REAR O/S REGULATOR MOTOR | REPLACED | 485.00 | 380.50 |
| 1 | REAR O/S DOOR WEATHERSTRIP | REPLACED | 280.00 | 195.00 |
| 1 | REAR WINDSCREEN REPAIR KIT | SERVICEABLE | 195.00 | |
| 1 | REAR BUMPER | REPAIRED SEE LABOUR | 2,094.00 | |
| 1 | REAR BUMPER SIDE RETAINER | SERVICEABLE | 48.00 | - |
| 1 | REAR O/S FENDER | REPAIRED SEE LABOUR | 2,185.00 | - |
| 1 | REAR O/S SPORT RIM | REPLACED | 1,200.00 | 552.50 |
| 1 | REAR O/S WHEEL BEARING WITH HUB | REPLACED | 316.00 | 316.00 |
| 1 | REAR O/S SHOCK ABSORBER | SERVICEABLE | 520.00 | |
| 1 | REAR O/S KNUCKLE ARM | SERVICEABLE | 1,265.00 | |
| 1 | REAR O/S CONTROL ARM | SERVICEABLE | 530.00 | - |
| 1 | REAR O/S LOWER ARM | SERVICEABLE | 520.00 | 19 |
| 1 | REAR O/S STAY ARM | SERVICEABLE | 608.00 | - |
| 1 | REAR O/S TOP ARM | SERVICEABLE | 435.00 | - |
| 1 | REAR O/S TAILING ARM | SERVICEABLE | 440.00 | |
| | LESS 10% DISCOUNT | | -1,656.90 | -371.91 |
| | Service Supplier Control Contr | | 14,912.10 | 3,347.19 |
| | SPECIAL NETT ITEMS | | | |
| 1 | REAR O/S TYRE (SN) | SERVICEABLE | 550.00 | |
| | | | 550.00 | |
| | LABOUR | | | |
| | TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING. | | 80.00 | 30.00 |
| | TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR. | NOT NECESSARY | 150,00 | - |
| | TO REMOVE AND REFIT REAR UNDERCARRIAGE. | | 350.00 | 100.00 |
| | TO CONDUCT WHEEL ALIGNMENT. | | 150.00 | 60.00 |

Report Ref No. CS3/CTI19019320/Hsf3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|--|------------------------------|----------------------|
| | TO REMOVE AND REFIT REAR WINDSCREEN GLASS. | NOT NECESSARY | 180.00 | |
| | TO REMOVE AND REFIT DOORS COMPLETE FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR. | The second of th | 150.00 | 60.00 |
| | TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL | | 100.00 | 30.00 |
| | TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT O/S DOOR, REAR BUMPER AND REAR O/S FENDER. | | 1,200.00 | 700.00 |
| | TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT. | | 1,000.00 | 800.00 |
| | | | 3,360.00 | 1,780.00 |
| | GRAND TOTAL | | 18,822.10 | 5,127.19 |

| 4,100.00 |
|----------|
| |
| |

Report Ref No. CS3/CTI19019320/Hsf3e2-1

LEE HOCK ANN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No. liability of responsibility whatsoeyer. In contact or text, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.