Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000045/FHA3Q2

Date: 08/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant SH8072Y Insured Vehicle No: SKG3333C

Vehicle No:

Date of Loss: Nature of Claim: TP 20/12/2019 Claim No: 3450120236SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SH8072Y Reg No:

Make & Model: HYUNDAI 140, 1.7 D (A) Engine No: **HIDDEN**

Reg. Date: 16/07/2015 (Man. Year: 2015) Chassis No: KMHLB41UMGU075274

Colour: Odometer: 902997 km Blue

Engine Capacity: 1685 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm Front Right Side: Rear Right Side: Hankook 6 mm Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,035.06	660.00	375.06	36.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	730.00	520.00	210.00	28.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,765.06	1,180.00	585.06	33.15
Approved Total (Overridden) (S\$)		950.00		
(S\$)	1,765.06	950.00	815.06	46.18
+ GST 7.00/7.00% (S\$)	123.55	66.50	57.05	46.18
Nett Amount (S\$)	1,888.61	1,016.50	872.11	46.18
+ Loss of Use (1.5 x S\$	50.00/day) (S\$)	75.00		
+ Car Rental (1.5 x S\$1	10.67/day) (S\$)	166.01		
+ Doc/S	earch Fee (S\$)	7.49		
Ne	tt Liability (S\$)	1,265.00		
Global Sum S	Settlement (S\$)	1,260.00		

INSPECTION

Date of Assignment: 30/12/2019

Date Inspected: 30/12/2019 Inspected At: ComfortDelGro Engineering Pte Ltd

> (Loyang) 59 Loyang Drive Singapore 508969

Adjuster Report Page 2 of 4

Estimated Period of Repair: 2.0 days

Adjuster: PARASURAM SHANMUGAM Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	553.00 FL	*553.00 FL
2	1		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
3	2		*REAR BUMPER BRACKET	Not Necessary	71.20 FL	*- FL
4	1		*REAR BUMPER UNDER COVER	Not Necessary	228.00 FL	*- FL
5	1		*REAR BUMPER REVERSE SENSOR	Serviceable	135.70 FS	*-FS
6	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS
F=Fra	ınchise	part. S=Spc	Nett. L=ListItemDisc.			
				Sub Total (S\$)	1,209.90	775.00
- List Item Discount on L Items 20.00/20.00% (S\$)				174.84	115.00	
				Total Parts (S\$)	1,035.06	660.00
Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	350.00	240.00
2	SPRAY PAINTING CHARGE	New	250.00	200.00
3	WIRING CHARGE	New	50.00	30.00
4	REMOVE/REFIX REVERSE SENSOR	New	80.00	50.00
		Gross Labour Cost (S\$)	730.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >