

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/III20000046/UGS3Q2

**Date:** 15/05/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SKE1071G	<b>Insured Vehicle No :</b>	SHB4175Y
Date of Loss: 24/12/2019	Nature of Claim: TP	Claim No: MCT19120618

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE1071G	Engine No:	CAV361423
Make & Model:	VOLKSWAGEN SCIROCCO, 1.4 TSI (A)	Chassis No:	WVWZZZ13ZCV017859
Reg. Date:	06/02/2012 (Man. Year: 2011)	Odometer:	97553 km
Colour:	Black		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,627.70	610.99	4,016.71	86.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,870.00	960.00	910.00	48.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,497.70</b>	<b>1,570.99</b>	<b>4,926.71</b>	<b>75.82</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,250.00</b>		
<b>(S\$)</b>	6,497.70	1,250.00	5,247.70	80.76
<b>+ GST 7.00/7.00% (S\$)</b>	454.84	87.50	367.34	80.76
<b>Nett Amount (S\$)</b>	<b>6,952.54</b>	<b>1,337.50</b>	<b>5,615.04</b>	<b>80.76</b>
<b>+ Loss of Use (3.0 x S\$60.00/day) (S\$)</b>		180.00		
<b>Nett Liability (S\$)</b>		<b>1,517.50</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,500.00</b>		

### INSPECTION

Date of Assignment: 11/02/2020

Date Inspected: 11/02/2020 Inspected At:

Hock Wah Motor Workshop Pte Ltd  
(Bedok)  
Blk 3011, Bedok Industrial Park E.,  
#01-2008/2010/2012  
Singapore 489977

Estimated Period of Repair: 3.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 May 2020)
<b>Parts:</b>	144	VOLKSWAGEN SCIROCCO 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKE1071G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER RETAINER LH	Not Necessary	32.55 F	*- FL
2	1		*HEADLAMP LH	Not Necessary	741.95 F	*- FL
3	1		*FRONT FENDER LH	Dented	643.15 F	*643.15 FL
4	1		*FRONT LOWER ARM LH	Not Necessary	357.25 F	*- FL
5	1		*FRONT KNUCKLE ARM LH	Not Necessary	631.60 F	*- FL
6	1		*FRONT SHOCK ABSORBER LH	Not Necessary	325.50 F	*- FL
7	1		*FRONT WHEEL BEARING LH	Not Necessary	491.60 F	*- FL
8	1		*FRONT WHEEL RIM LH (CUT)	Not Consistent With The Impact	1,404.10 F	*- FL
9	1		*FRONT BUMPER (NPA)	Repair	0.00 FS	*- FS
10	1		*BONNET (NPA)	Not Necessary	0.00 FS	*- FS
11	1		*FRT DOOR (NPA)	Repair	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,627.70</b>	<b>643.15</b>
<b>- List Item Discount on L Items 0.00/5.00% (\$\$)</b>	0.00	32.16
<b>Total Parts (\$\$)</b>	<b>4,627.70</b>	<b>610.99</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	500.00	250.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	800.00	600.00
3	ANTI-RUST COATING	New	100.00	30.00
4	TO REMOVE & REFIT UNDERCARRIAGE	New	350.00	0.00
5	TWO WHEEL ALIGNMENT	New	80.00	60.00
6	WIRING	New	40.00	20.00
<b>Gross Labour Cost (\$)</b>			<b>1,870.00</b>	<b>960.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >