Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000058/T1KA3Q2

Date: 29/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800091878-01 Claimant SHA2500K

Insured Vehicle No: SMD1916B Vehicle No:

Date of Loss: TP 26/12/2019 Nature of Claim: Claim No: 5824251678SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SHA2500K Reg No:

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2ZRS060706

Chassis No: Reg. Date: 10/08/2017 (Man. Year: 2017) JTDKB3FU503563154

Colour: Odometer: 371530 km Blue

Engine Capacity: 1798 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Davanti 6 mm Front Left Side: Rear Left Side: Davanti 6 mm Front Right Side: Rear Right Side: Davanti 6 mm Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,198.72	180.00	1,018.72	84.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,020.00	550.00	470.00	46.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,218.72	730.00	1,488.72	67.10
+ GST 7.00/7.00% (S\$)	155.31	51.10	104.21	67.10
Nett Amount (S\$)	2,374.03	781.10	1,592.93	67.10

0.00 Global Sum Settlement (S\$)

INSPECTION

Date of Assignment: 27/12/2019

Date Inspected: 27/12/2019 Inspected At: ComfortDelGro Engineering Pte Ltd

(Loyang) 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Manager: Khanchna Pothuraj Adjuster: MOHD TAUFIKH BIN HAMID

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 4

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount		
1	1		*PANEL SUB-ASSY ,REAR DOOR, RH	Repair	1,258.30 FL	*- FL		
2	1		*REAR DOOR ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS		
3	1		*FRONT DOOR COMFORT LOGO	Not Necessary	75.00 FS	*- FS		
4	1		*REAR DOOR COMFORT & APPS STICKER	Necessary	80.00 FS	*80.00 FS		
F=Franchise part. S=SpcNett. L=ListItemDisc.								
				Sub Total (S\$)	1,513.30	180.00		
- List Item Discount on L Items 25.00/25.00% (S\$)					314.58	0.00		
				Total Parts (S\$)	1,198.72	180.00		
Report was unsubmitted during this print-out.								

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	350.00	320.00
2	SPRAY PAINTING CHARGE	New	500.00	200.00
3	TUFF KOTE	New	50.00	30.00
4	TRANSFER OF DOOR	New	120.00	0.00
		Gross Labour Cost (S\$)	1,020.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >