

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000064/FDS3Q2

Date: 19/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100491409

Claimant
Vehicle No : SHD3897T **Insured Vehicle No :** SLJ2546J

Date of Loss: 28/12/2019 Nature of Claim: TP Claim No: 6866933976SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3897T		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2B83988
Reg. Date:	13/12/2018 (Man. Year: 2018)	Chassis No:	JTDKB3FU203077725
Colour:	Blue	Odometer:	96030 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Davanti 8 mm	Rear Left Side:	Davanti 8 mm
Front Right Side:	Davanti 8 mm	Rear Right Side:	Davanti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,064.00	1,064.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	440.00	440.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	1,504.00	1,504.00	0.00	0.00
+ GST 7.00/7.00% (\$\$)	105.28	105.28	0.00	0.00
Nett Amount (\$\$)	1,609.28	1,609.28	0.00	0.00
+ Loss of Use (3.0 x S\$50.00/day) (\$\$)		150.00		
+ Car Rental (\$\$)		389.95		
+ Doc/Search Fee (\$\$)		7.49		
Nett Liability (\$\$)		2,156.72		
Global Sum Settlement (\$\$)		2,150.00		

INSPECTION

Date of Assignment: 30/12/2019

Date Inspected: 31/12/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Braddell)
205 Braddell Road
Singapore 579701

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PRIG4 COVER REAR BUMPER	Deformed	458.60 FL	*458.60 FL
2	1		*PRIG4 GUARD-REAR BUMPER C	Scratched	552.60 FL	*552.60 FL
3	10		*PRIVC BUMPER PIECE	Necessary	22.00 FL	*22.00 FL
4	1		*PRIG4 REINFORCEMENT SUB-A	Bent	318.80 FL	*318.80 FL
5	1		*PRIG4 BUMPER PROTECTOR MA	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,402.00	1,402.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	338.00	338.00

Total Parts (\$\$)	1,064.00	1,064.00
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	240.00	240.00
2	SPRAYPAINT CHARGE	New	200.00	200.00
Gross Labour Cost (\$)			440.00	440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >