

AB PTE LTD

ESTIMATE*

VEHICLE NO : SHA 8660S

DATE 26/1

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type
	Rear Bumper <i>cra</i>	
	Rear Bumper Reinforcement <i>2 xnn</i>	
	Rear Bumper Reinforcement Bracket (LH/RH) <i>2 xnn</i>	\$
	Rear Bumper Clip 10 pcs <i>nec</i>	
	Rear Bumper Bracket <i>2 xnn</i>	\$
	Rear Bumper Sponge <i>2 xnn</i>	
	Rear Bumper Under Cover <i>xnn</i>	
	SUB TOTAL	
	LESS 20%	
	DISCOUNTED TOTAL	
	Rear Bumper Reverse Sensor <i>xnn</i>	
	Rear Bumper Advertisement Logo <i>nec</i>	
	Rear Bumper Rubber Mat <i>nec</i>	
	Rear Fender Advertisement Logo (LH/RH) <i>nec</i>	\$
	Labour Charge	
	Panel Beating	
	Spray Painting Charge	
	Wiring Charge	
	Remove/Refix Reverse Sensor	
	<i>TOWING</i>	
	TOTAL LABOUR	
	ESTIMATE TOTAL	

LKK Auto Consultants hence not the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during res
- Parts prices are subject to confirmation
- Third party survey is on a "Without Pre
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurv
- is subject to final approval from Insura

Acknowledged by Repairer

Signature:

Date:

0 • c

553 • +

22 • =

575 • *

575 • x

80 • %

460 • *

0 • c

50 • +

50 • +

200 • =

300 • *

0 • c

240 • +

200 • +

60 • +

(Towing) - 60 • =

560 • *

0 • c

460 • +

300 • +

560 • =

1,320 • *

1,320 • x

80 • %

1,056 • *

0 • c

\$ 250.00

\$ 50.00

\$ 80.00

\$ 60.00

\$ 730.00

\$ 2,419.06

Ram (LKK)
26/12/19 1440hrs
Perduman @ LKK auto.com
28622778
(LIS) aft repair (2x repair day)
photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.