

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000071/KBS3Q2

Date: 04/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : GBB3711C **Insured Vehicle No :** SMN4998S

Date of Loss: 27/12/2019 **Nature of Claim:** TP **Claim No:** 8379361113SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB3711C		
Make & Model:	NISSAN URVAN, 3.0 5DR 5MT ABS A/B 2WD (M)	Engine No:	ZD30206457K
Reg. Date:	17/01/2009 (Man. Year: 2008)	Chassis No:	JN1MG4E25Z0792181
Colour:	Metallic Grey	Odometer:	104172 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	OHTSU 6 mm	Rear Left Side:	OHTSU 6 mm
Front Right Side:	OHTSU 6 mm	Rear Right Side:	OHTSU 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,755.33	6,243.84	511.49	7.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	2,280.00	500.00	17.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,535.33	8,523.84	1,011.49	10.61
Approved Total (Overridden) (\$\$)		6,800.00		
(\$\$)	9,535.33	6,800.00	2,735.33	28.69
+ GST 7.00/7.00% (\$\$)	667.47	476.00	191.47	28.69
Nett Amount (\$\$)	10,202.80	7,276.00	2,926.80	28.69
+ Loss of Use (10.0 x S\$70.00/day) (\$\$)		700.00		
+ Doc/Search Fee (\$\$)		8.00		
Nett Liability (\$\$)		7,984.00		
Global Sum Settlement (\$\$)		7,770.00		

INSPECTION

Date of Assignment: 30/12/2019

Date Inspected: 30/12/2019 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun
Industrial Park A
Singapore 768761

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	734.00 FN	*734.00 FN
2	6		*REAR BUMPER CLIPS	Necessary	30.00 FN	*30.00 FN
3	1		*REAR BUMPER CENTRE STEP PANEL	Bent	189.10 FN	*189.10 FN
4	1		*REAR TAILGATE	Bent	1,998.30 FN	*1,998.30 FN
5	1		*TAILGATE LOGO	Necessary	64.90 FN	*64.90 FN
6	1		*TAILGATE OUTER HANDLE	Necessary	510.40 FN	*249.10 FN
7	1		*TAILGATE INNER LOCK	Dented	389.90 FN	*389.90 FN
8	1		*TAILGATE INNER RUBBER (50%)	Cut	171.72 FS	*95.40 FS
9	1		*LH TAILLAMP	Cracked	247.30 FN	*247.30 FN
10	1		*REAR END PANEL	Bent	161.80 FS	*161.80 FS
11	1		*REAR EXHAUST PIPE	Bent	954.30 FS	*954.30 FS
12	1		*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
13	1		*REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS
14	1		*TAILGATE INNER STAINLESS STEEL PROTECTOR	Dented	380.00 FS	*380.00 FS
15	1		*REAR STAINLESS STEEL CABINET	Necessary	1,100.00 FS	*900.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	7,171.72	6,634.10
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	416.39	390.26
Total Parts (\$\$)	6,755.33	6,243.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER ASSY ,TAILLAMPS ,TAILGATE ,LOCK ASSY ,REAR WIPER ASSY ,CUT ,WELD & RENEW REAR END PANEL OUTER ,KNOCK & REPAIR REAR END PANEL INNER ,REAR LH SIDE PANEL ,REAR END FLOOR BOARD PANEL & REALIGN THE SAME INCLUDE & REAR STAINLESS STEEL RACK	New	1,400.00	1,100.00
3	PUTTY & RESPRAY ON REAR LH SIDE PANEL ,REAR FLOOR BOARD PANEL END PANEL ,TAILGATE ,REAR STEP PANEL ,REAR BUMPER	New	1,200.00	1,000.00
4	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (\$\$)			2,780.00	2,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >