

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20000073/APA3Q2

Date: 19/11/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00005983
Claimant
Vehicle No : SMM3868X **Insured Vehicle No :** SLZ2372J
Date of Loss: 30/12/2019 **Nature of Claim:** TP **Claim No:** 1202000015896

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMM3868X
Make & Model: SUZUKI S-CROSS, 998cc 1.0T GL (A) **Engine No:** K10C1192292
Reg. Date: 27/06/2019 (Man. Year: 2019) **Chassis No:** TSMJYA02S00679136
Colour: Blue **Odometer:** 7671 km
Engine Capacity: 998 cc
Market Value/New Car Price: N/A
Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 215/55R17 **Rear Tyre Size:** 215/55R17
Front Left Side: Continental 6 mm **Rear Left Side:** Continental 6 mm
Front Right Side: Continental 6 mm **Rear Right Side:** Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,635.88	3,759.85	2,876.03	43.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,280.00	1,750.00	1,530.00	46.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	9,915.88	5,509.85	4,406.03	44.43
Approved Total (Overridden) (\$)		4,400.00		
(S\$)	9,915.88	4,400.00	5,515.88	55.63
+ GST 7.00/7.00% (S\$)	694.11	308.00	386.11	55.63
Nett Amount (\$)	10,609.99	4,708.00	5,901.99	55.63
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 31/12/2019
Date Inspected: 31/12/2019 **Inspected At:** Twincar Automotive Pte Ltd (HQ)
 2 KAKI BUKIT AVEUNE 2 #01-17
 Singapore 417921
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Nov 2020)
Parts:	M1-SUV	SUZUKI S-CROSS 998cc 1.0T GL (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM3868X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR PROTECTOR	Deformed	108.85 FL	*108.85 FL
2	1		*REAR AXLE	Not Necessary	1,520.20 FL	*- FL
3	1		*REAR BUMPER	Deformed	580.30 FL	*580.30 FL
4	1		*REAR BUMPER LH REFLECTOR	Cracked	34.30 FL	*34.30 FL
5	1		*REAR BUMPER LOWER LID	Deformed	480.70 FL	*480.70 FL
6	1		*REAR BUMPER REINFORCEMENT	Bent	305.30 FL	*305.30 FL
7	1		*REAR BUMPER SIDE RETAINER L/R	N/s Damaged	65.00 FL	*32.50 FL
8	1		*REAR END PANEL	Repair	430.60 FL	*- FL
9	1		*REAR LH DOOR	Dented	780.20 FL	*780.20 FL
10	1		*REAR LH DOOR BLACK TAPE	Necessary	42.30 FL	*42.30 FL
11	1		*REAR LH DOOR HINGE (LOWER)	Not Necessary	39.70 FL	*- FL
12	1		*REAR LH DOOR PROTECTOR	Deformed	103.70 FL	*103.70 FL
13	1		*REAR LH DOOR WEATHER STRIP	Not Necessary	128.90 FL	*- FL
14	1		*REAR LH FENDER ARCH GARNISH	Cut	138.50 FL	*138.50 FL
15	1		*REAR LH FENDER INNER SHIELD	Not Necessary	99.70 FL	*- FL
16	1		*REAR LH TAILLAMP	Cracked	495.20 FL	*325.00 FL
17	1		*REAR LH WHEEL BEARING	Damaged	283.00 FL	*283.00 FL
18	1		*ROCKER GARNISH LH	Cut	408.70 FL	*408.70 FL
19	1		*REAR LH SPORT RIM	Cut	722.50 FS	*550.00 FS
20	1		*SET FRONT LH DOOR PROTECTOR CLIPS	Necessary	40.00 FS	*20.00 FS
21	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
22	1		*REAR LH 215/55R17 TYRE	Not Necessary	450.00 FS	*- FS
23	1		*SET REAR LH DOOR PROTECTOR CLIPS	Necessary	40.00 FS	*20.00 FS
24	1		*SET REAR LH FENDER ARCH GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS
25	1		*SET REAR LH FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
26	1		*SET REAR LH TAILLAMP CLIPS	Necessary	25.00 FS	*10.00 FS
27	1		*SET ROCKER GARNISH LH CLIPS	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,542.65	4,303.35
- List Item Discount on L Items 15.00/15.00% (S\$)	906.77	543.50
Total Parts (S\$)	6,635.88	3,759.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	100.00	80.00
2	TO REMOVE,CHANGE REAR SUSPENSION PARTS,AXLE CARRIAGE,ABSORBER,LOWER ARM,TOP ARM,TRAILING ARM,KNUCKLE ARM,WHEEL BEARING,BEARING HUB AND ETC	New	400.00	80.00
3	TO ROAD TEST DRIVING,CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM	New	120.00	80.00
4	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR)	New	140.00	60.00
5	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	800.00
6	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,200.00	600.00
7	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	50.00
Gross Labour Cost (\$\$)			3,280.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >