

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20000076/AKS3Q2**Date:** 27/04/2020**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant**Vehicle No :** SGW2345M**Insured Vehicle No :** SLT6893C

Date of Loss: 27/12/2019

Nature of Claim: TP

Claim No: 9833670349SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SGW2345M**Make & Model: BMW 116I, 1.6 ABS D/AIRBAG 2WD 5DR HID
DSC (A)

Engine No: A323J542N13B16A

Reg. Date: 26/11/2013 (Man. Year: 2013)

Chassis No: WBA1A120X0J212996

Colour: Blue

Odometer: 115427 km

Engine Capacity: 1598 cc

Market Value/New Car
Price: N/ASum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18

Rear Tyre Size: 225/40 R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,312.00	7,200.20	2,111.80	22.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,330.00	2,790.00	540.00	16.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,642.00	9,990.20	2,651.80	20.98
Approved Total (Overridden) (S\$)		8,000.00		
Nett Amount (S\$)	12,642.00	8,000.00	4,642.00	36.72
+ Loss of Use (11.0 x S\$60.00/day) (S\$)		660.00		
Nett Liability (S\$)		8,660.00		

INSPECTION

Date of Assignment: 30/12/2019

Date Inspected: 30/12/2019 Inspected At:

ADVANCE AUTO GARAGE
23 KAKI BUKIT AVENUE 4 #04-01
AAS KAKI BUKIT CENTRE
SINGAPORE 415933

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
2	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
3	1		*REAR BUMPER	Distorted	1,080.00 F	*1,080.00 FL
4	1		*REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
5	1		*REAR BUMPER SIDE HOLDER	N/S Cracked	202.00 F	*101.00 FL
6	1		*REAR BUMPER INNER FRAME	Cracked	195.00 F	*195.00 FL
7	1		*REAR BUMPER REINFORCEMENT	Bent	650.00 FS	*650.00 FS
8	1		*REAR BUMPER LOWER SPOILER	Cracked	1,200.00 FS	*1,000.00 FS
9	1		*REAR END PANEL	Dented	698.00 F	*698.00 FL
10	1		*REAR END PANEL TOP GARNISH	Not Necessary	258.00 F	*- FL
11	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
12	1		*TAILLAMP LH	Cracked	560.00 F	*560.00 FL
13	1		*TAILLAMP PANEL LH	Repair	295.00 F	*- FL
14	4		*REVERSE SENSOR	Damaged (2 PCS ONLY)	1,040.00 F	*520.00 FL
15	1		*TAILGATE	Dented	1,136.00 F	*1,136.00 FL
16	1		*TAILGATE WEATHERSTRIPE	Necessary	195.00 F	*195.00 FL
17	1		*TAILGATE LOCK	Not Necessary	272.00 F	*- FL
18	1		*TAILGATE GLASS MOULDING	Necessary	95.00 F	*95.00 FL
19	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
20	1		*BMW LOGO	Necessary	98.00 F	*98.00 FL
21	1		*REAR EXHAUST PIPE	Dented	988.00 F	*988.00 FL
22	1		*REAR EXHAUST MOUNTING	Not Necessary	35.00 F	*- FL
23	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	85.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,312.00	7,486.00
- List Item Discount on L Items 0.00/5.00% (\$)	0.00	285.80
Total Parts (\$)	9,312.00	7,200.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	1,100.00
2	SPRAY PAINTING	New	1,200.00	1,100.00
3	WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	80.00
5	TO REMOVE REVERSE SENSOR	New	100.00	60.00
6	TO REMOVE UPHOLSTERY	New	150.00	100.00
7	TO TRANSFER TAILGATE FITTINGS	New	150.00	100.00
8	TO REMOVE TAILGATE GLASS	New	180.00	120.00
9	TO REMOVE EXHAUST PIPE	New	150.00	100.00
Gross Labour Cost (\$)			3,330.00	2,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >