

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: 19.27384 Date: 06th Feb 2020

Our Ref: CS3/ASM18017024/Gtd3e2-1

M/s AXA Insurance Pte Ltd

C/O: Seah Ong & Partners LLP 36 Robinson Road #12-03 City House Singapore 068877 (The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLS 9720D

INSURED VEHICLE: SFB 5166R ACCIDENT DATE: 15/09/2018

We thank you for your instruction on 11/12/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLS 9720D from M/s PAR Automotive Consultancy.
- b) Singapore Accident Statement of Vehicles SLS 9720D and SFB 5166R.
- c) Final Repair Bill of SLS 9720D from M/s Twincar Automotive Pte Ltd.
- d) Colour damaged vehicle photographs of SLS 9720D.

Pre-Repair Inspection Date: 19/09/2018 at M/s Twincar Automotive Pte Ltd, Kaki Bukit Autohub, 2 Kaki Bukit Ave 2, #01-17 / #01-18, Singapore 417921.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SJS 9720D

Make & Model : Honda CR-Z 1.5L CVT

Year of Registration : 2012

Chassis Number : JHMZF1420CS202396

Engine Capacity : 1497 cc

- 2. We recommend that the repairs of the entire damage require about <u>5 (Five)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.