Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20000080/AES3N2

**Date:** 19/08/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994047

Claimant SMO3193M Insured Vehicle No: SLR7624S

Vehicle No: SMQ3193M Insured Vehicle No: SLR7624S

Date of Loss: 27/12/2019 Nature of Claim: TP Claim No: 3553007888SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMQ3193M

 Make & Model:
 TOYOTA NOAH HYBRID, 1.8 X CVT (A)
 Engine No:
 2ZR0D98803

 Reg. Date:
 08/11/2019 (Man. Year: 2019)
 Chassis No:
 ZWR800395497

 Colour:
 Purple
 Odometer:
 8822 km

Engine Capacity: 1797 cc
Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm
Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,107.30	2,845.20	4,262.10	59.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	1,280.00	1,720.00	57.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,107.30	4,125.20	5,982.10	59.19
Approved Total (Overridden) (S\$)		3,300.00		
Nett Amount (S\$)	10,107.30	3,300.00	6,807.30	67.35
+ Loss of Use (5.0 x S\$8	30.00/day) (S\$)	400.00		
+ Doc/Se	earch Fee (S\$)	7.49		
Net	t Liability (S\$)	3,707.49		

**INSPECTION** 

Date of Assignment: 30/12/2019

Date Inspected: 30/12/2019 Inspected At: Hua Meng Spray Painting Workshop

(HQ)

No 1 Kaki Bukit Avenue 6, #01-61

Autobay@Kaki Bukit Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING Manager: Asher Sng Rong Yi

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount		
1	1		*LH CENTRE DOOR	Dented	1,883.70 FL	*1,883.70 FL		
2	1		*LH CENTRE DOOR GLASS TOP MOULDING	Not Necessary	408.60 FL	*- FL		
3	1		*LH CENTRE DOOR INNER LOCK	Not Necessary	640.10 FL	*- FL		
4	1		*LH CENTRE DOOR INNER BACK LOCK	Not Necessary	650.80 FL	*- FL		
5	1		*LH CENTRE DOOR INNER RUBBER	Not Necessary	408.60 FL	*- FL		
6	1		*LH CENTRE DOOR INNER STOPPER	Not Necessary	158.10 FL	*- FL		
7	1		*LH CENTRE DOOR INNER BOARD	Cracked	860.10 FL	*860.10 FL		
8	1		*LH CENTRE DOOR TOP HINGE	Not Necessary	188.60 FL	*- FL		
9	1		*LH CENTRE DOOR LOWER HINGE	Not Necessary	200.50 FL	*- FL		
10	1		*LH CENTRE DOOR CENTRE HINGE	Not Necessary	210.80 FL	*- FL		
11	1		*SET LH CENTRE DOOR BLACK STICKER	Necessary	189.70 FL	*189.70 FL		
12	1		*LH REAR FENDER	Repair	1,339.20 FL	*- FL		
13	1		*LH REAR FENDER QUARTER GLASS MOULDING	Not Necessary	1,068.60 FL	*-FL		
14	1		*LH REAR FENDER QUARTER OUTER MOULDING	Not Necessary	408.90 FL	*- FL		
15	1		*LH ROCKER PANEL GARNISH	Cracked	860.10 FL	*860.10 FL		
F=Fra	anchise	part. L=List	ItemDisc.					
				Sub Total (S\$)	=	3,793.60		
	- List Item Discount on L Items 25.00/25.00% (S\$)					948.40		
				Total Parts (S\$)	7,107.30	2,845.20		
	Report was unsubmitted during this print-out.							

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REMOVE & REINSTALL DOOR FITTINGS	New	150.00	80.00
2	REMOVE & REINSTALL QUARTER GLASS	New	150.00	0.00
3	REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,400.00	600.00
4	RESPRAY PAINTING	New	1,300.00	600.00
	Gross Labo	our Cost (S\$)	3,000.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >