



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

INV No. AC2207938

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV Date 23/12/2022
Reference CC4/EQI20000086/Bpa3q2
Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SMM 575K
Insured Veh. FBK 4699B
Claim No. DM19HO03377/JT
Policy No. DMMPHQ19-001273
Accident Date 24/12/2019
Inspection Date 30/12/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Ref: CC4/EQI20000086/Bpa3q2 Date: 23/12/2022 Code: EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBK 4699B	Veh. Inspected	SMM 575K
Policy No.	DMMPHQ19-001273	Coverage (\$)	0.00
Claim No.	DM19HO03377/JT	Excess (\$)	0.00
Assign From	JAIME TAY	Assign Date	30/12/2019
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI AVANTE	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMHD841CMKU907518	Colour	SILVER
Odometer	10434 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	KUMHO	6 mm
L/H Front Tyre	205/55 R16	KUMHO	6 mm
R/H Rear Tyre	205/55 R16	KUMHO	6 mm
L/H Rear Tyre	205/55 R16	KUMHO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	24/12/2019	Inspection Date	30/12/2019
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMM 575K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOTLID	NOT DAMAGED	1,864.20	-
1	BOOTLID LOGO	NOT NECESSARY	105.20	-
1	BOOTLID INNER TRIM	NOT DAMAGED	158.10	-
2	BOOTLID TAILLAMP @ \$854.20	NOT DAMAGED	1,708.40	-
1	BOOTLID LOCK	NOT DAMAGED	453.60	-
1	BOOTLID WEATHERSTRIP	NOT DAMAGED	265.40	-
1	REAR BUMPER	BROKEN	1,154.30	700.00
1	REAR BUMPER LOWER GARNISH	CUT	581.60	335.10
1	REAR BUMPER SIDE LOWER COVER RH	BROKEN	163.40	163.40
1	REAR BUMPER INNER SPONGE	BROKEN	235.40	195.00
1	REAR BUMPER REINFORCEMENT	BROKEN	453.01	453.01
2	REAR BUMPER RETAINER @ \$198.20	NECESSARY	396.40	137.80
2	REAR BUMPER REFLECTOR @ \$267.50	BROKEN	535.00	300.00
2	TAILLAMP @ \$1054.00	NOT DAMAGED	2,108.00	-
1	EXHAUST ASSY	NOT NECESSARY	879.00	-
1	EXHAUST MOUNTING	NOT NECESSARY	238.00	-
1	REAR END PANEL	DENTED	935.40	523.40
1	REAR END PANEL GARNISH	BROKEN	342.10	145.80
	LESS 20% DISCOUNT		-2,515.30	-590.70
			10,061.21	2,362.81
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER CLIP (SN)	NECESSARY	60.00	30.00
1	REAR BUMPER LOWER GARNISH CLIP (SN)	NECESSARY	80.00	30.00
1	REAR BUMPER LOWER COVER CLIP (SN)	NOT NECESSARY	60.00	-
2	BOOTLID TAILLAMP SEAL @ \$60.00 (SN)	NOT NECESSARY	120.00	-
1	BOOTLID INNER TRIM CLIP (SN)	NOT NECESSARY	60.00	-
2	TAILLAMP SEAL @ \$60.00 (SN)	NOT NECESSARY	120.00	-
1	REAR END PANEL SEALANT (SN)	NECESSARY	100.00	40.00
1	REAR END PANEL TOP GARNISH CLIP (SN)	NECESSARY	60.00	30.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	80.00	-

Report Ref No. CC4/EQI20000086/Bpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REVERSE CAMERA (SN)	NOT DAMAGED	400.00	-
2	REVERSE SENSOR @ \$200.00 (SN)	SHORT CIRCUIT	400.00	200.00
			1,540.00	330.00
	<u>LABOUR</u>			
	CHECK WIRING.		100.00	30.00
	PANEL BEATING.		1,200.00	600.00
	TO DRILL HOLES ON REPLACED REAR BUMPER AND INSTALL REVERSE SENSOR.		80.00	60.00
	R&R EXHAUST.	NOT NECESSARY	180.00	-
	SPRAY PAINT.		1,400.00	600.00
			2,960.00	1,290.00
GRAND TOTAL			14,561.21	3,982.81
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,100.00

Report Ref No. CC4/EQ120000086/Bpa3q2

LIM TEOW GUAN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMM 575K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMM 575K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

