

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20000093/AGS3Q2

**Date:** 20/11/2020

#### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SKV5309G	<b>Insured Vehicle No :</b>	SHC3981M
Date of Loss: 25/12/2019	Nature of Claim: TP	Claim No: MCT19120619

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKV5309G</b>	
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Engine No: HRA2178304A
Reg. Date:	22/09/2015 (Man. Year: 2015)	Chassis No: SJNFEAJ11U1468350
Colour:	Bronze	Odometer: 37409 km
Engine Capacity:	1197 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	<b>Market Value/New Car Price</b>	

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	23,369.79	12,630.78	10,739.01	45.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	2,400.00	1,200.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>26,969.79</b>	<b>15,030.78</b>	<b>11,939.01</b>	<b>44.27</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>12,000.00</b>		
<b>(S\$)</b>	26,969.79	12,000.00	14,969.79	55.51
<b>+ GST 7.00/7.00% (S\$)</b>	1,887.89	840.00	1,047.89	55.51
<b>Nett Amount (S\$)</b>	<b>28,857.68</b>	<b>12,840.00</b>	<b>16,017.68</b>	<b>55.51</b>
<b>+ Loss of Use (12.0 x S\$60.00/day) (S\$)</b>		720.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>+ Other Costs (S\$)</b>		170.00		
<b>Nett Liability (S\$)</b>		<b>13,737.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>13,700.00</b>		

#### INSPECTION

Date of Assignment: 30/12/2019

Date Inspected: 30/12/2019 Inspected At:

N-51 Automotive Pte Ltd (HQ)  
BLK 2 KAKI BUKIT, #01-17/18 KAKI

BUKIT AUTOHUB  
Singapore 417921

Estimated Period of Repair: 8.0 days

---

**Adjuster:** ADRIAN LING

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 13 Jul 2020)
<b>Parts:</b> M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKV5309G)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AIRCON ALUMINIUM PIPE	Bent	85.20 FL	*85.20 FL
2	1		*ENGINE UNDER COVER	Torn	285.00 FL	*285.00 FL
3	1		*FRONT BONNET	Not Necessary	961.40 FL	*- FL
4	2		*FRONT BONNET HINGES L/R	Not Necessary	112.20 FL	*- FL
5	1		*FRONT BONNET INNER RUBBER	Not Necessary	89.00 FL	*- FL
6	1		*FRONT BONNET INNER SAFETY LOCK CATCH	Not Necessary	82.80 FL	*- FL
7	2		*FRONT BONNET INNER SIDE STOPPER L/R	Not Necessary	15.00 FL	*- FL
8	1		*FRONT BONNET INNER STAND BRACKET HOLDER	Not Necessary	8.10 FL	*- FL
9	1		*FRONT BONNET INNER TOP RUBBER	Not Necessary	89.00 FL	*- FL
10	1		*FRONT BONNET INSULATOR	Not Necessary	185.50 FL	*- FL
11	1		*FRONT BONNET MECHANISM LOCK	Not Necessary	67.60 FL	*- FL
12	1		*FRONT BUMPER	Distorted	717.00 FL	*717.00 FL
13	1		*FRONT BUMPER FOGLAMP GARNISH L/R	O/S Cut	204.00 FL	*102.00 FL
14	1		*FRONT BUMPER LOWER REINFORCEMENT	Bent	337.30 FL	*337.30 FL
15	1		*FRONT BUMPER REINFORCEMENT	Bent	675.40 FL	*675.40 FL
16	1		*FRONT BUMPER REINFORCEMENT BRACKET L/R	O/S Bent	290.00 FL	*145.00 FL
17	2		*FRONT BUMPER SIDE RETAINER L/R	Necessary	51.80 FL	*51.80 FL
18	2		*FRONT BUMPER SPONGE (LOWER) L/R	Torn	195.80 FL	*195.80 FL
19	1		*FRONT BUMPER SPONGE (TOP)	Cracked	195.70 FL	*195.70 FL
20	1		*FRONT BUMPER TOW HOOK COVER	Cut	21.20 FL	*21.20 FL
21	2		*FRONT FENDER ARCH GARNISH L/R	N/S Cracked / O/S Cut	966.00 FL	*966.00 FL
22	2		*FRONT FENDER INNER SHIELD L/R	Torn	175.00 FL	*175.00 FL
23	1		*FRONT FENDER L/R	O/S Dented / N/S Repair	1,245.40 FL	*622.70 FL
24	1		*FRONT GRILLE	Missing	461.20 FL	*461.20 FL
25	1		*FRONT GRILLE LOGO EMBLEM	Necessary	109.20 FL	*109.20 FL
26	2		*FRONT HEADLAMP L/R	Cracked	1,224.40 FL	*1,224.40 FL
27	2		*FRONT HEADLAMP LOWER BRACKET L/R	Not Necessary	30.60 FL	*- FL
28	2		*FRONT HEADLAMP TOP PANEL L/R	Repair	290.60 FL	*- FL
29	1		*FRONT SUPPORT PANEL	Buckled	617.50 FL	*617.50 FL
30	2		*FRONT SUPPORT PANEL SIDE GUIDE STOPPE L/R	Not Necessary	15.00 FL	*- FL
31	2		*OIL COOLANT RUBBER HOSE	Not Necessary	84.00 FL	*- FL
32	2		*RADIATOR SIDE GUIDE L/R	Cracked	179.20 FL	*179.20 FL
33	1		*AIR DUCT	Deformed	95.90 F	*95.90 FN
34	1		*AIRCON CONDENSER	Dented	658.20 F	*658.20 FN
35	1		*AIRCON DISCHARGE PIPE	Bent	197.80 F	*197.80 FN
36	1		*AIRCON SUCTION PIPE	Bent	140.00 F	*140.00 FN
37	1		*ENGINE MOUNTING (FRONT)	Not Necessary	74.90 F	*- FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*ENGINE MOUNTING (REAR)	Not Necessary	91.60 F	*- FN
39	1		*FAN MOTOR ASSY	Cracked	621.70 F	*621.70 FN
40	1		*SET FRONT BONNET INSULATOR CLIPS	Not Necessary	80.00 F	*- FN
41	1		*FRONT BONNET MECHANISM LOCK CABLE	Not Necessary	43.40 F	*- FN
42	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 F	*30.00 FN
43	1		*FRONT BUMPER FOGLAMP L/R	O/S Cracked	643.20 F	*321.60 FN
44	1		*FRONT BUMPER NUMBER PLATE	Bent	25.00 F	*25.00 FN
45	1		*FRONT BUMPER NUMBER PLATE HOLDER	Deformed	50.00 F	*30.00 FN
46	1		*FRONT ENGINE CROSSMEMBER	Bent	674.10 F	*674.10 FN
47	2		*SET FRONT FENDER ARCH GARNISH CLIPS L/R	Necessary	60.00 F	*60.00 FN
48	2		*SET FRONT FENDER INNER SHIELD CLIPS L/R	Necessary	80.00 F	*60.00 FN
49	1		*SET FRONT GRILLE CLIPS	Missing	40.00 F	*20.00 FN
50	1		*FRONT GRILLE TOP COVER	Missing	81.00 F	*81.00 FN
51	1		*FRONT HORN L/R	O/S Cracked	179.20 F	*89.60 FN
52	2		*FRONT LOWER ARM L/R	Not Necessary	499.60 F	*- FN
53	1		*FRONT OUTSIDE TEMPERATURE SENSOR	Not Necessary	114.60 F	*- FN
54	2		*FRONT SHOCK ABSORBER L/R	Not Necessary	1,120.60 F	*- FN
55	2		*FRONT SPORT RIM L/R	Not Necessary	2,463.80 F	*- FN
56	1		*FRONT WASHER TANK NICK	Not Necessary	25.00 F	*- FN
57	1		*FRONT WASHER TANK WITH MOTOR	Cracked	171.30 F	*171.30 FN
58	1		*OIL COOLER	Dented	567.20 F	*567.20 FN
59	1		*OIL COOLER RETURN PIPE	Dented	80.70 F	*80.70 FN
60	1		*RADIATOR (AUTO)	Dented	687.40 F	*687.40 FN
61	1		*RADIATOR COOLANT	Necessary	60.00 F	*40.00 FN
62	1		*RADIATOR LOWER GARNISH	Cracked	94.50 F	*94.50 FN
63	1		*RADIATOR LOWER HOSE	Not Necessary	185.30 F	*- FN
64	1		*RADIATOR TOP HOSE	Not Necessary	103.60 F	*- FN
65	1		*RADIATOR TOP SUPPORT	Not Necessary	81.00 F	*- FN
66	1		*REAR AXLE	Not Necessary	1,322.80 F	*- FN
67	1		*TURBO INTERCOOLER	Dented	2,121.60 F	*2,121.60 FN
68	1		*TURBO INTERCOOLER LOWER HOSE	Not Necessary	417.00 F	*- FN
69	2		*TURBO INTERCOOLER MOUNTING	Not Necessary	35.20 F	*- FN
70	1		*TURBO INTERCOOLER TOP HOSE	Not Necessary	242.20 F	*- FN

F=Franchise part. L=ListItemDisc. N=NettItemDisc.

<b>Sub Total (\$)</b>	<b>24,376.50</b>	<b>14,034.20</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	1,006.71	716.66
<b>- Nett Item Discount on N Items 0.00/10.00% (\$)</b>	0.00	686.76
<b>Total Parts (\$)</b>	<b>23,369.79</b>	<b>12,630.78</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ,CHARGE AIR CON PARTS ,VACUUMS ,REFILL AIR CON GAS	New	140.00	120.00
2	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING (TO FR)	New	100.00	30.00
3	TO REMOVE,CHARGE FRONT SUSPENSION PARTS ,ABSORBER ,LOWER ARM ,KNUCKLE ARM ,WHEEL BEARING ,BEARING HUB ,DRIVE SHAFT ,ANTI-ROLL BAR ,TOP -ARM AND STEERING RACK AND PINION	New	400.00	320.00
4	TO REMOVE,CHARGE REAR SUSPENSION PARTS ,AXLE CARRIAGE ABSORBER ,LOWER ARM ,TOP ARM,TRAILING ARM,KNOCKLE ARM ,WHEEL BEARING ,BEATING HUB AND ETC	New	380.00	0.00
5	TO ROAD TEST DRIVING ,CHECK AND RESETTING WHEEL ALIGNMENT SYSTEM	New	140.00	80.00
6	TO RE-SPRAY PAINTING ON THE FRONT BONNET ,FRONT SUPPORT PANEL ,FRONT FENDER (L/R) AN FRONT BUMPER	New	1,200.00	900.00
7	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND REALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,100.00	900.00
8	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	140.00	50.00
<b>Gross Labour Cost (S\$)</b>			<b>3,600.00</b>	<b>2,400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >