

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20000095/KTF3E2

Date: 30/04/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MK000527

Claimant Vehicle No : SHC5660B

Insured Vehicle No : SKJ7885J

Date of Loss: 22/12/2019

Nature of Claim: TP Claim No: M1909989

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC5660B**

Make & Model: RENAULT LATITUDE, 2.0 L (A)

Engine No: M9R8839C002402

Reg. Date: 24/12/2014 (Man. Year: 2014)

Chassis No: VF1ABL15AUC281153

Colour: Metallic White/Red

Odometer: 577301 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Sailun 9 mm

Rear Left Side: Sailun 9 mm

Front Right Side: Sailun 9 mm

Rear Right Side: Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,547.83	1,122.83	21,425.00	95.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,650.00	1,430.00	17,220.00	92.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	41,197.83	2,552.83	38,645.00	93.80
Approved Total (Overridden) (S\$)		2,050.00		
(S\$)	41,197.83	2,050.00	39,147.83	95.02
+ GST 7.00/7.00% (S\$)	2,883.85	143.50	2,740.35	95.02
Nett Amount (S\$)	44,081.68	2,193.50	41,888.18	95.02

INSPECTION

Date of Assignment: 16/04/2020

Date Inspected: 31/12/2019 Inspected At:

TRANS-CAB AUTO SERVICES PTE LTD
NO.2 ANG MO KIO ST 63
SINGAPORE 569111

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Apr 2020)
Parts:	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC5660B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*DOOR PANEL REAR RH	Bent	758.70 FL	-	*758.70 FL
2	1		*DOOR GUIDE REAR RH	Serviceable	136.40 FL	-	*- FL
3	1		*DOOR SEAL REAR RH	Serviceable	119.80 FL	-	*- FL
4	1		*DOOR WHEATHERSTRIP REAR RH	Serviceable	311.60 FL	-	*- FL
5	1		*DOOR HANDLE OUTER REAR RH L70Y	Serviceable	42.10 FL	-	*- FL
6	1		*DOOR HANDLE CAP REAR RH L70Y	Serviceable	57.90 FL	-	*- FL
7	1		*DOOR HANDLE MODULE REAR RH L70Y	Serviceable	111.00 FL	-	*- FL
8	1		*DOOR LOCK REAR RH L70Y	Repair	467.30 FL	-	*- FL
9	1		*DOOR REGULATOR REAR RH L70Y	Serviceable	758.10 FL	-	*- FL
10	1		*DOOR REGULATOR MOTOR REAR RH L70Y	Serviceable	450.60 FL	-	*- FL
11	1		*DOOR GLASS RUNNER SEAL REAR RH L70Y	Serviceable	116.10 FL	-	*- FL
12	1		*DOOR WAIST SEAL OUTER REAR RH L70Y	Serviceable	99.40 FL	-	*- FL
13	1		*DOOR HARNESS WIRE RH	Serviceable	2,670.00 FL	-	*- FL
14	1		*ROCKER PANEL INNER GARNISH RH	Serviceable	466.51 FL	-	*- FL
15	1		*ROCKER PANEL INNER RH	Repair	1,024.79 FL	-	*- FL
16	1		*ROCKER PANEL OUTER RH	Repair	1,184.99 FL	-	*- FL
17	1		*ROCKER PANEL CENTER RH	Repair	990.25 FL	-	*- FL
18	1		*FENDER PANEL REAR RH	Repair	1,933.20 FL	-	*- FL
19	1		*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	-	*- FL
20	1		*WHEELARCH REAR RH	Serviceable	275.40 FL	-	*- FL
21	1		*BUMPER COVER REAR	Serviceable	561.70 FL	-	*- FL
22	1		*BUMPER LOWER REAR	Serviceable	411.90 FL	-	*- FL
23	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	-	*- FL
24	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	-	*- FL
25	1		*BUMPER REFLECTOR RH	Serviceable	16.60 FL	-	*- FL
26	1		*TAILLAMP RH	Serviceable	313.10 FL	-	*- FL
27	1		*TAILLAMP PANEL RH	Repair	401.40 FL	-	*- FL
28	1		*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	-	*- FL
29	1		*EXHAUST CAP REAR	Repair	125.40 FL	-	*- FL
30	1		*KNUCKLE ARM REAR RH	Serviceable	472.10 FL	-	*- FL
31	1		*BRAKE DISC REAR	Serviceable	266.50 FL	-	*- FL
32	1		*KNUCKLE HUB + BEARING RH	Serviceable	272.30 FL	-	*- FL
33	1		*ABSORBER REAR	Serviceable	217.30 FL	-	*- FL
34	1		*LOWER ARM REAR RH	Serviceable	543.50 FL	-	*- FL
35	1		*AXLE SPRING ARM RH	Serviceable	220.60 FL	-	*- FL
36	1		*SUBFRAME ARM REAR	Serviceable	198.33 FL	-	*- FL
37	1		*RODE - LONG REAR	Serviceable	120.16 FL	-	*- FL
38	1		*WHEEL HUB NUT	Serviceable	41.80 FL	-	*- FL
39	1		*WHEEL HUB CAP	Serviceable	30.50 FL	-	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
40	1		*REAR AXLE	Serviceable	3,469.00 FL	-	*- FL
41	1		*ABS SENSOR REAR RH	Serviceable	190.50 FL	-	*- FL
42	1		*STABILIZER BAR REAR	Serviceable	427.90 FL	-	*- FL
43	1		*STABILIZER LINK REAR	Serviceable	55.20 FL	-	*- FL
44	1		*BRAKE CALIPER REAR RH	Serviceable	659.10 FL	-	*- FL
45	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	-	*- FS
46	1		*DOOR GUIDE SCREW	Not Necessary	10.85 FS	-	*- FS
47	1		*DOOR HINGE BOLT	Not Necessary	10.85 FS	-	*- FS
48	1		*DOOR HINGE NUT RH	Not Necessary	14.60 FS	-	*- FS
49	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	-	*- FS
50	1		*DOOR CHECK NUT	Not Necessary	3.75 FS	-	*- FS
51	1		*DOOR LOCK SCREW L70Y	Not Necessary	6.12 FS	-	*- FS
52	1		*REAR RIGHT TYRE	Serviceable	300.00 FS	-	*- FS
53	1		*REAR RIGHT TYRE RIM	Dented	380.00 FS	-	*380.00 FS
54	1		*REAR DOOR STICKER 6555-3333	Necessary	100.00 FS	-	*60.00 FS
55	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	-	*- FS
56	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	-	*- FS
57	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	-	*- FS
58	1		*FENDER INNER TRIM CLIP RH	Not Necessary	28.00 FS	-	*- FS
59	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	-	*- FS
60	1		*SET PARKING AID	Serviceable	700.00 FS	-	*- FS
61	1		*SET REAR BUMPER CLIP	Not Necessary	66.00 FS	-	*- FS
62	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	-	*- FS
63	1		*SET BUMPER RETAINER CLIP RH RR	Not Necessary	20.00 FS	-	*- FS
64	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	-	*- FS
65	1		*SET BUMPER LOWER REAR CLIP	Not Necessary	66.00 FS	-	*- FS
66	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	-	*- FS
67	1		*EXHAUST MOUNTING REAR	Serviceable	16.00 FS	-	*- FS
68	1		*REAR BUMPER PROTECTOR	Not Necessary	100.00 FS	-	*- FS
69	1		*DOOR BLIND REAR RH	Serviceable	506.90 FL	-	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 24,806.53 1,198.70
- List Item Discount on L Items 10.00/10.00% (\$\$) 2,258.70 75.87

Total Parts (\$\$) 22,547.83 1,122.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	7,500.00	500.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	80.00
3	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
4	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	20.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
6	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
8	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR	New	380.00	0.00
9	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
10	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
11	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
12	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
13	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING	New	380.00	0.00
14	TO DISMANTLE AND REFIT REAR AXLE ASSY, REMOVE AND RENEWAL OF PARTS, FINAL CHECKING AND TESTING	New	380.00	0.00
15	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
16	TO CHECK ABS AND BRAKE EFFICIENCY, FINAL CHECKING AND TESTING	New	380.00	0.00
17	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	7,500.00	660.00
Gross Labour Cost (\$\$)			18,650.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >