

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000102/BDA3Q2

Date: 25/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994153

Claimant
Vehicle No : JRF5218 **Insured Vehicle No :** SJT3936G

Date of Loss: 31/12/2019 Nature of Claim: TP Claim No: 7659304502SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JRF5218	Engine No:	1NZZ340730
Make & Model:	TOYOTA VIOS, 1.5 (A)	Chassis No:	PN153HYF005082489
Reg. Date:	28/12/2015 (Man. Year: 2015)	Odometer:	84815 km
Colour:	White		
Engine Capacity:	1492 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Toyo 6 mm	Rear Left Side:	Continental 3 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Continental 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,636.12	7,130.57	6,505.55	47.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,190.00	2,710.00	1,480.00	35.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,826.12	9,840.57	7,985.55	44.80
Approved Total (Overridden) (\$\$)		7,850.00		
Nett Amount (\$\$)	17,826.12	7,850.00	9,976.12	55.96
+ Loss of Use (13.0 x S\$60.00/day) (\$\$)		780.00		
+ Doc/Search Fee (\$\$)		7.45		
+ Other Costs (\$\$)		50.00		
Nett Liability (\$\$)		8,687.45		

INSPECTION

Date of Assignment: 02/01/2020

Date Inspected: 03/01/2020 Inspected At:

Team Autopro Pte Ltd (sin Ming) (HQ)
160 SIN MING DRIVE, #01-14 SIN
MING AUTOCITY
Singapore 575722

Estimated Period of Repair: 10.0 days

Adjuster: Lim Teow Guan**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	1,483.20 FL	*655.10 FL
2	1		*BOOTLID LOGO	Necessary	108.90 FL	*48.00 FL
3	1		*BOOTLID EMBLEM VIOS	Necessary	118.60 FL	*52.00 FL
4	1		*BOOTLID EMBLEM G	Necessary	86.00 FL	*46.00 FL
5	1		*BOOTLID OUTER CHROME GARNISH	Broken	486.20 FL	*162.10 FL
6	1		*BOOTLID INNER TRIM BOARD	Broken	359.20 FL	*189.70 FL
7	2		*BOOTLID NUMBER PLATE LAMP	Not Damaged	172.80 FL	*- FL
8	1		*BOOTLID WEATHERSTRIP	Torn	286.30 FL	*192.20 FL
9	1		*BOOTLID HINGE	O/S Bent	373.80 FL	*186.90 FL
10	1		*BOOTLID LOCK	Jammed	356.10 FL	*356.10 FL
11	1		*BOOTLID STRIKER	Bent	96.40 FL	*45.20 FL
12	1		*REAR BUMPER	Broken	1,058.60 FL	*769.80 FL
13	2		*REAR BUMPER SIDE RETAINER	Necessary	417.40 FL	*161.40 FL
14	1		*REAR BUMPER REINFORCEMENT	Bent	354.20 FL	*354.20 FL
15	2		*REAR BUMPER REFLECTOR	Broken	958.40 FL	*326.00 FL
16	1		*REAR END PANEL	Dented	753.90 FL	*719.20 FL
17	1		*REAR END PANEL TOP GARNISH	Dislodged	196.50 FL	*196.50 FL
18	1		*REAR FENDER RH	Dented	1,086.30 FL	*897.60 FL
19	2		*REAR FENDER INNER TRIM BOARD	Distorted	851.40 FL	*530.20 FL
20	1		*REAR FENDER AIR VENTS RH	Not Damaged	276.50 FL	*- FL
21	1		*SPARE TYRE PANEL	Not Damaged	795.30 FL	*- FL
22	1		*SPARE TYRE TOP BOARD	Not Damaged	486.20 FL	*- FL
23	2		*TAILLAMP	Broken	1,952.40 FL	*1,561.40 FL
24	2		*TAILLAMP BASE PANEL	Dented	972.40 FL	*230.00 FL
25	1		*EXHAUST PIPE	Broken	855.00 FL	*855.00 FL
26	1		*EXHAUST MOUNTIGN	Bent	79.50 FL	*79.50 FL
27	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
28	1		*BOOTLID SEALANT	Necessary	100.00 FS	*30.00 FS
29	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
30	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
31	1		*SPARE TYRE PANEL SEALANT	Not Necessary	100.00 FS	*- FS
32	1		*REAR FENDER SEALANT RH	Necessary	100.00 FS	*30.00 FS
33	2		*REVERSE SENSOR WITH MODULE	Necessary	300.00 FS	*200.00 FS
34	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
35	2		*TAILLAMP CLIPS	No such part	100.00 FS	*- FS
36	1		*TAILLAMP BASE PANEL SEALANT	Necessary	800.00 FS	*30.00 FS
37	1		*BOOTLID OUTER CHROME GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
38	1		*REVERSE CAMERA	Cut	380.00 FS	*200.00 FS
39	2		*TAILLAMP PANEL	Necessary	160.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,391.50	9,284.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,755.38	2,153.53
Total Parts (\$\$)	13,636.12	7,130.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R BOOTLID COMPONENT	New	100.00	60.00
2	R&R UPHOLSTERY	New	200.00	0.00
3	R&R REVERSE SENSOR AND SPRAY PAINT	New	100.00	60.00
4	R&R EXHAUST PIPE ASSY	New	250.00	80.00
5	TO DISCONNECT WIRE HARNESS TO FACILITATE REPAIR ,RECONNECT AND TEST FUNCTION	New	80.00	50.00
6	CONDUCT WATER LEAKAGE TEST	New	60.00	0.00
7	RUST PROOFING	New	200.00	60.00
8	REAR SPRAY PAINTING	New	1,600.00	1,200.00
9	REAR PANEL BEAT	New	1,600.00	1,200.00
Gross Labour Cost (\$\$)			4,190.00	2,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >