

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHB 3234S

DATE : 20.12.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI IONIQ

FAX : 6542 6039

FCL

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet <i>bnc</i>			\$ 2,253.80
	Bonnet Hinge (LH/RH) <i>1st</i>	\$	118.70	\$ 237.40
	Bonnet Lock <i>1st</i>			\$ 127.30
	Bonnet Insulator <i>crumpled</i>			\$ 230.10
	Bonnet Insulator Clips <i>new</i>			\$ 8.40
	Radiator Grille <i>broken</i>			\$ 1,409.10
	Unit Assy-SMART CRU (Radar Sensor) <i>broken</i>			\$ 2,910.90
	Front Bumper Cover <i>for</i>			\$ 418.30
	Front Bumper Sponge <i>firm / dislodged</i>			\$ 86.90
	Front Bumper Reinforcement <i>Detached</i>			\$ 1,075.10
	Front Bumper Absorber <i>Detached</i>			\$ 86.90
	Front Bumper Grille (LH/RH) <i>new</i>	\$	186.90	\$ 373.80
	Front Bumper Centre Moulding <i>broken</i>			\$ 188.00
	Front Bumper Moulding (LH/RH) <i>new</i>	\$	93.60	\$ 187.20
	Front Bumper Lower Stiffener <i>new</i>			\$ 85.10
	Front Bumper Lip <i>new</i>			\$ 35.10
	Front Bumper Bracket Top (LH/RH) <i>new</i>	\$	35.00	\$ 70.00
	Front Bumper Bracket (LH/RH) <i>new</i>	\$	28.00	\$ 56.00
	Front Bumper Clips 10 pcs <i>new</i>			\$ 22.00
	Headlamp Support Top Cover <i>broken</i>			\$ 398.00
	Headlamp Support Panel Assy <i>broken</i>			\$ 949.30
	Headlamp (LH/RH) <i>broken / mucky broken</i>	\$	1,198.80	\$ 2,397.60
	Day Light, LH <i>new</i>			\$ 642.50
	Day Light, RH <i>new</i>			\$ 642.50
	Radiator Inverter <i>1st / punctured</i>			\$ 884.80
	Radiator <i>1st / punctured</i>			\$ 510.50
	Radiator Blower Motor <i>broken Down</i>			\$ 576.00
	Radiator Fan <i>Down</i>			\$ 375.10
	Radiator Shroud <i>broken</i>			\$ 275.50
	Radiator Air Guard (LH/RH) <i>new</i>	\$	26.40	\$ 52.80
	Radiator Air Guard, Upr(LH/RH) <i>new</i>	\$	27.50	\$ 55.00
	Hose & Tube Assy <i>new</i>			\$ 245.70
	Horn Unit (LH/RH) <i>new</i>	\$	72.80	\$ 145.60
	Horn Wire <i>new</i>			\$ 156.50
	Front Fender (RH) <i>Damage</i>			\$ 490.70
	Front Fender Shield (RH) <i>new</i>			\$ 114.70
	Emblem-Blue Drive (RH) <i>new</i>			\$ 26.60
	Air Cleaner Assy <i>broken</i>			\$ 282.70
	Air Duct <i>new</i>			\$ 96.80
	Air Duct B <i>new</i>			\$ 68.70
	Aircon Condenser <i>1st / punctured</i>			\$ 663.60
	Aircon Suction & Liquid Hose <i>2nd</i>			\$ 679.60
	Aircon Discharge Hose <i>2nd</i>			\$ 148.50
	Frnt Safety Belt (Assy) (LH/RH) <i>actived</i>	\$	448.90	\$ 897.80
	Wiper Panel Top Garnish <i>new</i>			\$ 181.20
	Wiper Container <i>new</i>			\$ 210.00
	Wiper Container Motor <i>new</i>			\$ 75.00

SHB 3234S

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Engine Under Cover <i>HH</i>			\$ 469.40
	Dashboard Complete <i>Done HH</i>			
	Airbag Control Module <i>actintd</i>			\$ 1,243.70
	Curtain Airbag Module, LH <i>HH</i>			\$ 1,344.50
	Curtain Airbag Module, RH <i>HH</i>			\$ 1,344.50
	Steering Wheel Air Bag <i>actintd</i>			\$ 1,090.90
	Module Assy -Knee Air Bag <i>actintd</i>			\$ 578.60
	Air Bag Assy - Passenger <i>actintd</i>			\$ 1,951.20
	Air Bag Sensor (LH/RH) <i>actintd</i>		\$ 330.00	\$ 660.00
	SUB TOTAL		24134.90	\$ 30,787.50
	LESS 20%		19307.92	\$ 6,157.50
	DISCOUNTED TOTAL			\$ 24,630.00
	Front Number Plate <i>broken</i>			\$ 25.00
	Front No Plate Trim Cover <i>broken</i>			\$ 30.00
	Front Fender Advertisement Logo (RH) <i>HH</i>			\$ 100.00
				\$ 155.00
	Labour Charge			
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 1,000.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 100.00
	Towing Charge			\$ 90.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
	R/Refix Air Bag/Steering Wheel/Dashboard/Seat			\$ 550.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
	TOTAL LABOUR			\$ 3,420.00
	ESTIMATE TOTAL			\$ 28,205.00
	<i>24/12/19 @ 11:00am</i>			
	<i>Not Actintd</i>			
	<i>2/Jan 9 days.</i>			
	<i>Tyger</i>			
	<i>LKK Auto</i>			
		Supp	11894.72	
			33767.64	
		L/S	25000/-	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHB 3234S (Supplementary)

DATE : 26.12.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI IONIQ

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Speaker Assy- VESS <i>Dental</i>			\$ 354.40
	Radiator Spare Tank <i>crack</i>			\$ 258.00
	Radiator Bottom Hose <i>turn</i>			\$ 168.00
	Flap Assy Active Air Upper, (LH/RH) <i>broken / Dam</i>	\$	712.00	\$ 1,424.00
	A/C Tube -Liquid "A" <i>vert</i>			\$ 165.00
	A/C Tube -Liquid "B" <i>wt</i>			\$ 275.00
	Air Duct "B" Assy <i>broken</i>			\$ 152.00
	Electric Clutch Pump <i>crack</i>			\$ 4,130.20
	Intake Manifold <i>Dam</i>			\$ 1,382.00
	Generator HSG Assy <i>broken</i>			\$ 2,420.10
	Rear Seat Side Garnish Cover (LH/RH) <i>broken / money</i>	\$	438.00	\$ 876.00
	Front Windscreen Moulding <i>Nec</i>			\$ 57.30
	Engine Mounting <i>broken</i>			\$ 483.00
			12145.00	
			9716.00	
	SUB TOTAL			\$ 12,145.00
	LESS 20%			\$ 2,429.00
	DISCOUNTED TOTAL			\$ 9,716.00
	Front Number Plate Garnish <i>broken</i>			\$ 88.00
	Front Windscreen Sealant <i>Nec</i>			\$ 46.00
			134.00	
				\$ 134.00
	Labour Charge			
	Remove/Refix Front Windscreen Glass			\$ 120.00
	Remove/Refix Cushion & Upholstery Front			\$ 90.00
			80.00	
				\$ 210.00
				\$ 10,060.00
			9930.00	
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

REPAIR ESTIMATE

FAX : 6483 6015

Parts Description/Labour	Qty	Unit Price	Amount
REAR SAFETY BELT (ASSY)(LH/RH) <i>actual</i>		\$ 448.90	\$ 897.80
SUB-TOTAL			\$ 897.80
LESS 20%			\$ 179.56
DISCOUNTED TOTAL			\$ 718.24

Ryan
2 kkk And

9

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19008103MFSH
Our ref: CC4/FCI20000107/Dea3

Date: 02/01/2020

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHB 3234S


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24/12/2019 at the premises of M/s Chunni Motor Work Pte Ltd - Ang Mo Kio and have the following to report:-

Workshop Estimate Amount	: S\$	39,511.48
Revised Estimate Amount	: S\$	33,059.40
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	33,059.40
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 9.0 day

Yours faithfully,

ANG BRYAN TANI
Licensed Appraiser