

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20000110/KDS3Q2

**Date:** 28/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900141744

**Claimant**  
**Vehicle No :** SKE9417R **Insured Vehicle No :** GBJ7425K

Date of Loss: 26/12/2019 Nature of Claim: TP Claim No: 6127657455SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE9417R		
Make & Model:	HONDA FIT, 1.3 (A)	Engine No:	L13A4250817
Reg. Date:	24/09/2009 (Man. Year: 2009)	Chassis No:	GE61228599
Colour:	White	Odometer:	126896 km
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/45 R16	Rear Tyre Size:	205/45 R16
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,860.48	1,750.16	1,110.32	38.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,435.00	820.00	615.00	42.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,295.48</b>	<b>2,570.16</b>	<b>1,725.32</b>	<b>40.17</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,050.00</b>		
<b>Nett Amount (S\$)</b>	<b>4,295.48</b>	<b>2,050.00</b>	<b>2,245.48</b>	<b>52.28</b>
<b>+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		428.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,480.00</b>		

### INSPECTION

Date of Assignment: 02/01/2020

Date Inspected: 13/01/2020 Inspected At:

Autoworx House - Sin Ming (HQ)  
176 SIN MING DRIVE #02-01  
Singapore 575721

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Bent	498.40 FL	*412.00 FL
2	1		*FRONT FENDER DUST COVER	Serviceable	213.50 FL	*- FL
3	7		*FRONT FENDER DUST COVER CLIP	Not Necessary	25.90 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINERS	Distorted	65.70 FL	*65.70 FL
5	1		*FRONT HEAD LAMP ASSY	Cut	647.10 FL	*585.00 FL
6	1		*FRONT BUMPER -FIBERGLASS CUSTOMED	Cracked	1,200.00 FS	*900.00 FS
7	1		*ALLOY RIM	Serviceable	500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>3,150.60</b>	<b>1,962.70</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	290.12	212.54
<b>Total Parts (\$)</b>	<b>2,860.48</b>	<b>1,750.16</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE ,KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS	New	800.00	400.00
2	COMPUTERISED 4 WHEEL ALIGNMENT	New	85.00	0.00
3	TO FIT TYRES INTO ALLOY RIMS AND BALANCE	New	50.00	0.00
4	TO CHECK WIRING SYSTEM	New	50.00	20.00
5	TO SPRAY PAINTING ON AFFECTED AREAS	New	450.00	400.00
<b>Gross Labour Cost (S\$)</b>			<b>1,435.00</b>	<b>820.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >