

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20000111/R1PS3Q2

Date: 15/10/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549
Claimant Vehicle No :	SLQ2487J	Insured Vehicle No :	GBJ5799U
Date of Loss:	26/12/2019	Nature of Claim:	TP
		Claim No:	MFL2020D0000044

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ2487J	Engine No:	10JBHX3006928
Make & Model:	CITROEN DS4, 1.6 (A)	Chassis No:	VF7NXBHZTGY541058
Reg. Date:	30/06/2017 (Man. Year: 2016)	Odometer:	56583 km
Colour:	Grey		
Engine Capacity:	1560 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,652.00	11,828.00	5,824.00	32.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,920.00	6,130.00	4,790.00	43.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	28,572.00	17,958.00	10,614.00	37.15
+ GST 7.00/7.00% (S\$)	2,000.04	1,257.06	742.98	37.15
Nett Amount (S\$)	30,572.04	19,215.06	11,356.98	37.15
+ Car Rental (12.0 x S\$100.00/day + 7.00% GST) (S\$)		1,284.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		20,506.51		

INSPECTION

Date of Assignment:	02/01/2020	
Date Inspected:	02/01/2020 Inspected At:	Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ) 209 PANDAN GARDENS Singapore 609339
Estimated Period of Repair:	9.0 days	

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Oct 2020)
Parts:	143	CITROEN DS4 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ2487J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE WITH FRAME	Not Necessary	50.00 FS	*- FS
2	1		*C&C LOGO	Necessary	50.00 FS	*50.00 FS
3	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
4	1		*REAR BUMPER	Deformed	843.00 FS	*843.00 FS
5	1		*RECESS DOOR	Deformed	59.00 FS	*59.00 FS
6	1		*RR SKIRT PANEL	Deformed	562.00 FS	*562.00 FS
7	1		*BUMPER MOULDING	Deformed	305.00 FS	*305.00 FS
8	1		*SET REINFORCEMENT	Bent	64.00 FS	*64.00 FS
9	1		*SET BRACKET	Necessary	120.00 FS	*120.00 FS
10	1		*BUMPER BRACKET	Necessary	131.00 FS	*131.00 FS
11	1		*STIFFENER	Necessary	24.00 FS	*24.00 FS
12	10		*RIVET 4.8X20	Necessary	80.00 FS	*80.00 FS
13	1		*LOW RR PAN FIX	Necessary	80.00 FS	*80.00 FS
14	1		*LOAD FLOOR ASS	Serviceable	687.00 FS	*- FS
15	1		*BULKHEAD	Bent	467.00 FS	*467.00 FS
16	1		*REAR PANEL ASS	Bent	559.00 FS	*559.00 FS
17	1		*BADGE AV	Necessary	52.00 FS	*52.00 FS
18	1		*BADGE	Necessary	65.00 FS	*65.00 FS
19	1		*BADGE DS4	Necessary	61.00 FS	*61.00 FS
20	1		*BADGE CROSSBACK	Necessary	126.00 FS	*126.00 FS
21	1		*TAILGATE ASS	Bent	1,240.00 FS	*1,240.00 FS
22	1		*TLGT EXT PANEL	Serviceable	641.00 FS	*- FS
23	2		*TAILGATE HINGE	Serviceable	174.00 FS	*- FS
24	1		*WEATHERSTRIP	Serviceable	147.00 FS	*- FS
25	1		*TAILGATE GLASS	Not Necessary	523.00 FS	*- FS
26	1		*TAILGATE PROP LH	Service item	104.00 FS	*- FS
27	1		*TAILGATE PROP RH	Serviceable	104.00 FS	*- FS
28	1		*MOULDING	Deformed	345.00 FS	*345.00 FS
29	1		*SPOILER FLAP	Serviceable	816.00 FS	*- FS
30	1		*SPOILER SEAL	Serviceable	38.00 FS	*- FS
31	1		*TAILGATE FIX	Necessary	85.00 FS	*85.00 FS
32	1		*WING REAR LIGHT RH	Cracked	354.00 FS	*354.00 FS
33	1		*WING REAR LIGHT LH	Serviceable	354.00 FS	*- FS
34	1		*TAILGATE LIGHT RH	Broken	165.00 FS	*165.00 FS
35	1		*TAILGATE LIGHT LH	Broken	165.00 FS	*165.00 FS
36	1		*REAR FOG LIGHT RH	Serviceable	124.00 FS	*- FS
37	1		*REAR FOG LIGHT LH	Cracked	117.00 FS	*117.00 FS
38	1		*WDW WIPER MOTOR	Serviceable	256.00 FS	*- FS
39	1		*MOTOR SPACER	Not Necessary	10.00 FS	*- FS
40	1		*SENSOR	Not Working	231.00 FS	*231.00 FS
41	1		*SENSOR	Not Working	231.00 FS	*231.00 FS
42	1		*SENSOR	Not Working	231.00 FS	*231.00 FS
43	1		*SENSOR	Serviceable	231.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	4		*SENSOR SUPPORT	Necessary	548.00 FS	*548.00 FS
45	1		*ASSIST CAMERA ASS	Serviceable	473.00 FS	*- FS
46	1		*ASSIST CAMERA	Serviceable	384.00 FS	*- FS
47	1		*EXHAUST PIPE	Buckled	323.00 FS	*323.00 FS
48	1		*REAR SILENCER PSA 3382	Bent	356.00 FS	*356.00 FS
49	1		*FIXING CLAMP DIAM 61	Necessary	13.00 FS	*13.00 FS
50	1		*FRT PIPE SLEEVE DIAM 50	Necessary	139.00 FS	*139.00 FS
51	1		*FR RETRACK STAL LH	Not Working	502.00 FS	*502.00 FS
52	1		*FR RETRACK STAL RH	Not Working	502.00 FS	*502.00 FS
53	2		*BELT BUCKLE	Serviceable	286.00 FS	*- FS
54	2		*ADJUSTMENT	Bent	260.00 FS	*260.00 FS
55	1		*TRUNK MAT	Deformed	290.00 FS	*290.00 FS
56	1		*LINING	Deformed	322.00 FS	*322.00 FS
57	1		*ELECTRO UNIT	Serviceable	392.00 FS	*- FS
58	1		*BUMPER MOULDING RH	Necessary	258.00 FS	*258.00 FS
59	1		*BOX CDE S/G	Not Working	756.00 FS	*756.00 FS
60	1		*AIR PULLER	Necessary	50.00 FS	*50.00 FS
61	1		*BUMPER HARNESS	Cut	507.00 FS	*507.00 FS
62	1		*JACK BOX	Deformed	170.00 FS	*170.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	17,652.00	11,828.00
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WO:1228696 ACCIDNET TOWED BY KINGDOLLEY FROM FLYOVER LENTOR TO CNC PG	New	180.00	180.00
2	RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER,REAR TAILGATE,CUT/WELD REAR FLOOR PANEL ,REAR END PANEL ,REPAIR BOTH REAR FENDER	New	3,600.00	2,100.00
3	REMOVE AND REPLACE REAR WINDSCREEN GLASS	New	300.00	300.00
4	SUPPLY REAR WINDSCREEN SEALANT	New	100.00	80.00
5	REMOVE AND INSTALL PARKING ASSIST	New	100.00	80.00
6	REMOVE AND TRANSFER REAR TAILGATE TRIM ,MECHANISM TO NEW PANEL	New	600.00	300.00
7	PAINT WORK SPRAY REAR FLOOR PANEL,REAR END PANEL,REAR TAILGATE ,REAR BUMPER ,RH REAR FENDER ,LH REAR FENDER AND AFFECTED PORTION	New	2,940.00	1,260.00
8	SUPPLY BODY SEALANT	New	320.00	80.00
9	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	80.00	50.00
10	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	300.00	300.00
11	PERFORM RUST PREVENTION	New	180.00	80.00
12	RENEW FRONT BOTH SEALT BELT AND BUCKLE AND OTHERS ATTACHMENT	New	600.00	300.00
13	REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIR WORK	New	600.00	300.00
14	REMOVE AND REPLACE REAR EXHAUST SYSTEM	New	600.00	300.00
15	SPRAY PAINT LH REAR FENDER	New	420.00	420.00
Gross Labour Cost (\$\$)			10,920.00	6,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >