

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000116/T1ES3N2

Date: 20/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SFB923E

Insured Vehicle No : SLK8328C

Date of Loss: 27/12/2019

Nature of Claim: TP

Claim No: 2832149136SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFB923E**

Make & Model: SUBARU FORESTER, 2.0 (A)

Engine No: FA20J865180

Reg. Date: 29/11/2014 (Man. Year: 2014)

Chassis No: JF1SJGK85EG035446

Colour: Silver

Odometer: 106701 km

Engine Capacity: 1998 cc

Market Value/New Car

Price: N/A

Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18

Rear Tyre Size: 225/55 R18

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,271.34	2,511.23	3,760.11	59.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,200.00	2,000.00	62.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,471.34	3,711.23	5,760.11	60.82
Approved Total (Overridden) (\$\$)		3,000.00		
(\$\$)	9,471.34	3,000.00	6,471.34	68.33
+ GST 7.00/7.00% (\$\$)	662.99	210.00	452.99	68.33
Nett Amount (\$\$)	10,134.33	3,210.00	6,924.33	68.33
+ Car Rental (3.0 x S\$100.00/day) (\$\$)		300.00		
+ Doc/Search Fee (\$\$)		36.45		
Nett Liability (\$\$)		3,546.45		

INSPECTION

Date of Assignment: 02/01/2020

Date Inspected: 02/01/2020 Inspected At:

Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi
Industrial Park
Singapore 408934

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	890.00 FL	*794.00 FL
2	1		*REAR BUMPER SIDE RETAINER	O/S Necessary	87.40 FL	*43.70 FL
3	1		*REAR BUMPER REFLECTOR	O/S Necessary	114.40 FL	*57.20 FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	331.20 FL	*331.20 FL
5	1		*TAILGATE	Repair	1,370.80 FL	*- FL
6	1		*TAILGATE EMBLEM -LOGO	Necessary	91.08 FL	*91.08 FL
7	1		*TAILGATE EMBLEM -FORESTER	Necessary	74.52 FL	*74.52 FL
8	1		*TAILGATE EMBLEM -XT	Necessary	74.52 FL	*74.52 FL
9	1		*TAILGATE EMBLEM -SUBARU	Necessary	74.52 FL	*74.52 FL
10	1		*TAILGATE WEATHERSTRIP	Cut	124.20 FL	*124.20 FL
11	1		*TAILGATE INNER TRIM BOARD	Not Necessary	415.05 FL	*- FL
12	1		*TAILGATE WINDSCREEN MOULDING	Not Necessary	224.00 FL	*- FL
13	1		*TAILLAMP RH	Cracked	518.40 FL	*518.40 FL
14	1		*TAILLAMP PANEL RH	Not Necessary	345.60 FL	*- FL
15	1		*REAR EXHAUST SILENCER	Bent	722.16 FL	*668.20 FL
16	2		*REAR EXHAUST MOUNTING	Not Necessary	88.40 FL	*- FL
17	1		*REAR EXHAUST HEATSHIELD	Not Necessary	105.30 FL	*- FL
18	1		*REAR END PANEL	Repair	589.63 FL	*- FL
19	1		*REAR END PANEL TOP GARNISH	Not Necessary	260.50 FL	*- FL
20	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
21	1		*SET END PANEL TOP GARNISH CLIP	Not Necessary	40.00 FS	*- FS
22	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
23	1		*SET REVERSE SENSOR	Not Working	600.00 FS	*200.00 FS
24	1		*JOINT SEALANT	Not Necessary	150.00 FS	*- FS
25	1		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,571.68	3,081.54
- List Item Discount on L Items 20.00/20.00% (\$)	1,300.34	570.31
Total Parts (\$)	6,271.34	2,511.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	REMOVE,REFIT LINING ,TRIM AND GARNISH	New	200.00	50.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	120.00	30.00
4	REMOVE AND NEW REAR EXHAUST ASSY	New	120.00	60.00
5	REMOVE,REFIT AND RENEW NEW TAILGATE	New	150.00	0.00
6	PANEL BEATING ON AFFECTED AREAS	New	1,200.00	500.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	500.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	30.00
Gross Labour Cost (\$\$)			3,200.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >