

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20000118/R1GS3Q2

Date: 15/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SMN3761P	Insured Vehicle No :	SH8603R
Date of Loss: 30/12/2019	Nature of Claim: TP	Claim No: MCT19120729

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN3761P		
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Engine No:	2ZR2E10601
Reg. Date:	05/08/2019 (Man. Year: 2019)	Chassis No:	ZWR800396466
Colour:	Black	Odometer:	49111 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,897.00	1,610.50	2,286.50	58.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,080.00	820.00	260.00	24.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,977.00	2,430.50	2,546.50	51.17
+ GST 7.00/7.00% (\$\$)	348.39	170.14	178.25	51.16
Nett Amount (\$\$)	5,325.39	2,600.64	2,724.75	51.17
+ Loss of Use (3.0 x S\$95.00/day) (\$\$)		285.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		2,893.09		

INSPECTION

Date of Assignment:	31/12/2019		
Date Inspected:	07/01/2020	Inspected At:	Allswell Motor Traders (HQ) 25 Defu Lane 9 Singapore 539266
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD RASUL

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Apr 2020)
Parts:	M1-MPV	TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN3761P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,919.00 F	*1,919.00 FL
2	1		*REAR BUMPER	Repair	1,718.00 F	*- FL
3	1		*WINDSCREEN MOULDING (3 PCS)	Necessary	155.00 F	*155.00 FL
4	1		*WINDSCREEN SEALANT	Necessary	55.00 FS	*55.00 FS
5	1		*CLIPS/STUDS FOR BUMPER	Not Necessary	50.00 FS	*- FS
					Sub Total (\$)	3,897.00 2,129.00
					- List Item Discount on L Items 0.00/25.00% (\$)	0.00 518.50
					Total Parts (\$)	3,897.00 1,610.50

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	INSTALL WINDSCREEN	New	180.00	120.00
2	DISMANTLE /ASSEMBLY OF AFFECTED PARTS	New	400.00	300.00
3	SPRAY PAINTING OF AFFECTED PARTS INCLUDING POLISH AND WASH	New	500.00	400.00
Gross Labour Cost (S\$)			1,080.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >