

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20000128/KSF3E2

Date: 17/04/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28688949

Claimant Vehicle No : YP495A

Insured Vehicle No : GX2196X

Date of Loss: 23/12/2019

Nature of Claim: TP Claim No: 615721

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YP495A

Make & Model: MITSUBISHI CANTER, 3.0 D FEB21ER4SDEB (CBU) (M)

Engine No: 4P10B98425

Reg. Date: 11/12/2015 (Man. Year: 2015)

Chassis No: FEB21EA20115

Colour: White

Odometer: 284608 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/85 R15

Rear Tyre Size: 195/85 R15 (D)

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 8/8 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,920.38	15,962.67	1,957.71	10.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,080.00	4,130.00	950.00	18.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	23,000.38	20,092.67	2,907.71	12.64
Approved Total (Overridden) (\$\$)		16,050.00		
(\$\$)	23,000.38	16,050.00	6,950.38	30.22
+ GST 7.00/7.00% (\$\$)	1,610.03	1,123.50	486.53	30.22
Nett Amount (\$\$)	24,610.41	17,173.50	7,436.91	30.22

INSPECTION

Date of Assignment: 02/01/2020

Date Inspected: 14/01/2020 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial
Park A
Singapore 768761

Estimated Period of Repair: 10.0 days

Adjuster: KENNETH KONG**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 17 Apr 2020)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEB21ER4SDEB (CBU) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP495A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	1,010.33 FL	*1,010.33 FL
2	1		*FRONT BUMPER LH BRACKET	Bent	196.24 FL	*196.24 FL
3	1		*FRONT BUMPER LH STAY	Distorted	163.56 FL	*163.56 FL
4	2		*FRONT BUMPER SIDE PADS	Dented / Cut	835.44 FL	*835.44 FL
5	1		*FRONT GRILLE	Cracked	1,053.14 FL	*1,053.14 FL
6	6		*FRONT GRILLE CLIPS	Necessary	41.40 FL	*41.40 FL
7	2		*SIGNAL LAMPS	Broken	532.72 FL	*532.72 FL
8	2		*SIDE LAMPS	O/S Mtg Cracked / N/S Cracked	910.12 FL	*910.12 FL
9	1		*FRONT PANEL	Bent	2,521.83 FL	*2,521.83 FL
10	1		*FRONT PANEL EMBLEM (FUSO)	Necessary	154.69 FL	*154.69 FL
11	1		*FRONT LH CORNAL PANEL	Mtg Cracked	506.76 FL	*506.76 FL
12	1		*FRONT WINDSCREEN GLASS	Cracked	1,312.96 FL	*1,312.96 FL
13	1		*FRONT WINDSCREEN GLASS RUBBER (\$492.05)(50%)	Necessary	369.04 FS	*246.03 FS
14	1		*AIR-CON GAS DISCHARGE HOSE	Dented	444.43 FL	*444.43 FL
15	1		*SET HEATER PIPIES	Dented	175.86 FL	*175.86 FL
16	1		*HORN	Dented	145.41 FL	*145.41 FL
17	1		*FRONT LH WIPER ARM COVER	Cracked	29.10 FL	*29.10 FL
18	2		*CABIN FRONT MOUNTINGS	Buckled / Distorted	460.82 FL	*460.82 FL
19	1		*CABIN FRONT MOUNTING CROSS BAR	Bent	898.76 FL	*898.76 FL
20	1		*AIR-CON EVAPORATOR UNIT	Mtg Cracked	2,303.12 FL	*2,303.12 FL
21	1		*FRONT LH DOOR INNER LOCK	Dented	402.84 FL	*402.84 FL
22	1		*DASHBOARD	Serviceable	2,208.05 FL	*- FL
23	1		*DASHBOARD LH SIDE GARNISH	Cracked	116.42 FL	*116.42 FL
24	1		*DASHBOARD CENTRE LOWER GARNISH	Mtg Cracked	501.64 FL	*501.64 FL
25	1		*DASHBOARD LH LOWER GARNISH	Mtg Cracked	673.71 FL	*673.71 FL
26	1		*TAILLAMPS	N/S Cracked / O/S Serviceable	388.44 FL	*194.22 FL
27	1		*REAR TAILGATE	Bent	2,402.15 FL	*2,402.15 FL
28	1		*TAILGATE STICKER (MITSUBISHI)	Necessary	101.55 FL	*101.55 FL
29	1		*REAR NUMBER PLATE LAMP	Cracked	79.82 FL	*79.82 FL
30	1		*REAR NUMBER PLATE	Bent	18.00 FS	*15.00 FS
31	1		*STICKER - 60KM/H	Necessary	10.00 FS	*10.00 FS
32	1		*STICKER - 21 PAX	Necessary	10.00 FS	*10.00 FS
33	1		*REAR STEP PANEL ASSY	Bent	480.00 FS	*480.00 FS
34	1		*ERP BRACKET	Necessary	25.00 FS	*25.00 FS
35	1		*FRONT BODY STICKER	Necessary	150.00 FS	*120.00 FS
36	2		*CABIN FRONT MOUNTING BRACKETS	Bent	1,906.48 FL	*1,906.48 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (S\$)	23,539.83
					20,981.55	
					- List Item Discount on L Items 25.00/25.00% (S\$)	5,619.45
						5,018.88
					Total Parts (S\$)	17,920.38
						15,962.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REFIX FRONT WINDSCREEN GLASS	New	100.00	80.00
2	PUTTY & RESPRAY DASHBOARD, METER ASSY, REPAIR DASHBOARD REINFORCEMENT & REALIGN THE SAME	New	280.00	250.00
3	REMOVE AND REFIX AIRCON, CHECK, VACUUM & REFILL GAS	New	100.00	100.00
4	PUTTY & RESPRAY FRT BUMPER ASSY, GRILLE, HEADLAMPS, SIDE LAMPS, FRT WIPER ASSY, CUT, WELD & RENEW FRT PANEL, KNOCK & REPAIR FRT INNER PANEL, FRT RH DOOR & REALIGN THE SAME	New	1,200.00	1,000.00
5	REMOVE & REFIX FRT CABIN, REPLACE MOUNTINGS, FRT CROSS BAR & REALIGN POSITION	New	800.00	600.00
6	REMOVE & REFIX TAILGATE ASSY, TAILLAMPS, REAR STEP BAR, KNOCK & REPAIR TAILGATE LOWER MEMBER, REAR BOTH MAIN CHASSISS, LH SIDE GATE & REALIGN THE SAME	New	1,000.00	700.00
7	PUTTY & RESPRAY ON FRT BUMPER, CORNAL PANEL, FRT GRILLE, FRT PANEL, WIPER GARNISHES, FRT RH DOOR, TAILGATE, TAILGATE LOWER PANEL	New	1,600.00	1,400.00
Gross Labour Cost (S\$)			5,080.00	4,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >