



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2100348

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 15/01/2021
Reference CC4/FCI20000129/Upa3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SJB 8875K
Insured Veh. SHA 1388A
Claim No. D19006354MFSH
Policy No. D-19092580MFSH
Accident Date 02/10/2019
Inspection Date 02/09/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20000129/Upa3q2	
			Date: 15/01/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1388A	Veh. Inspected	SJB 8875K	
Policy No.	D-19092580MFSH	Coverage (\$)	0.00	
Claim No.	D19006354MFSH	Excess (\$)	0.00	
Assign From	RACHEL WU	Assign Date	02/01/2020	
2. Vehicle Particulars & Condition				
Make & Model	KIA CERATO (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	KNAFE227385528201	Colour	BLUE	
Odometer	242007 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	GOODYEAR	6 mm	
L/H Front Tyre	215/45 R17	GOODYEAR	6 mm	
R/H Rear Tyre	215/45 R17	GOODYEAR	6 mm	
L/H Rear Tyre	215/45 R17	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/10/2019	Inspection Date	02/09/2020	
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD BLK 8 KAKI BUKIT AVENUE 4 PREMIER @ KAKI BUKIT (GATE 1) #02-54/55 SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJB 8875K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED / TORN	416.00	416.00
1	FRONT BUMPER RETAINER LH	NOT NECESSARY	17.00	-
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	257.00	-
1	HEADLAMP LH	CRACKED	404.00	404.00
1	FRONT BUMPER FOG LAMP LH	NOT NECESSARY	155.00	-
	LESS 10% DISCOUNT		-124.90	-82.00
			1,124.10	738.00
	<u>LABOUR</u>			
	LABOUR TO REMOVE & REFIT NECESSARY PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER LH .		400.00	200.00
	SPRAY PAINT ON THE AFFECTED AREAS.		400.00	350.00
	ANTI-RUST COATING.	NOT NECESSARY	50.00	-
	WIRING .		40.00	20.00
			890.00	570.00
	GRAND TOTAL		2,014.10	1,308.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,000.00
-----------------------------------------------------------------------------	--	--	-----------------

Report Ref No. CC4/FCI20000129/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJB 8875K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJB 8875K

RE-INSPECTION

