



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20000129/Upa3q2	
			Date: 15/10/2020	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 1388A	Veh. Inspected	SJB 8875K
	Policy No.	D-19092580MFSH	Coverage (\$)	0.00
	Claim No.	D19006354MFSH	Excess (\$)	0.00
	Assign From		Assign Date	03/01/2020
2. Vehicle Particulars & Condition				
	Make & Model	KIA CERATO (A)	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	KNAFE227385528201	Colour	BLUE
	Odometer	242007 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/45 R17	GOODYEAR	6 mm
	L/H Front Tyre	215/45 R17	GOODYEAR	6 mm
	R/H Rear Tyre	215/45 R17	GOODYEAR	6 mm
	L/H Rear Tyre	215/45 R17	GOODYEAR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	02/10/2019	Inspection Date	02/09/2020
	Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD BLK 8 KAKI BUKIT AVENUE 4 PREMIER @ KAKI BUKIT (GATE 1) #02-54/55 SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJB 8875K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED / TORN	416.00	416.00
1	FRONT BUMPER RETAINER LH	NOT NECESSARY	17.00	-
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	257.00	-
1	HEADLAMP LH	CRACKED	404.00	404.00
1	FRONT BUMPER FOG LAMP LH	NOT NECESSARY	155.00	-
	LESS 10% DISCOUNT		-124.90	-82.00
			1,124.10	738.00
	<u>LABOUR</u>			
	LABOUR TO REMOVE & REFIT NECESSARY PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER LH .		400.00	200.00
	SPRAY PAINT ON THE AFFECTED AREAS.		400.00	350.00
	ANTI-RUST COATING.	NOT NECESSARY	50.00	-
	WIRING .		40.00	20.00
			890.00	570.00
	GRAND TOTAL		2,014.10	1,308.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,000.00

Report Ref No. CC4/FCI20000129/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJB 8875K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJB 8875K

RE-INSPECTION

