



SLX 55 Z, Porsche Panamera

S/NO.	Parts Description	QTY	SGD \$
40-1	Bumper Front	1	3,570.00
13-2	Sponge	1	60.00
14-3	Left Bump Bracket	1	60.00
25-4	Disc Upper	1	140.00
30-5	Disc Lower	1	140.00
11-6	Left Lower Retainer	1	104.00
X 7 X	Additional Headlamp	1	700.00
22-8	Headlamp Bracket	1	340.00
1-9	Headlamp	1	4,300.00
5-10	Bonnet	1	4,200.00
27-11	Left Side Bonnet Actuator	1	320.00
28-12	Right Side Bonnet Actuator	1	320.00
X 13 X	Bonnet Lock	1	150.00
3-14	Fender Left No Eta	1	2,500.00
27-15	Support Panel	1	1,200.00
X 16 X	Bracket Centre Bumper	1	540.00
16-17	Centre Inner Air Duct	1	490.00
39-18	Radiator OEM, Nissens	1	800.00
X 19 X	Fan Cowling And Fan	1	2,100.00
X 20 X	Radiator Frame	1	180.00
40-21	Return Tube Left	1	180.00
22-22	Return Tube Right	1	140.00
23-23	Radiator Upper Bracket	1	44.00
8-24	Radiator Upper Bracket Rubber Isolator	1	40.00
44-25	Radiator Lower Bracket Rubber Isolator	1	56.00
X 26 X	Radiator Lower Bracket	1	44.00
X 27 X	Top Hose	1	90.00
X 28 X	Bottom Hose	1	90.00
24-29	Intake air Duct Left	1	170.00
25-30	Intake air Duct Right	1	170.00
73-31	Air Filter Housing	1	700.00
17-32	Air Duct Left	1	90.00
18-33	Air Duct Right	1	110.00
X 34 X	Hose	1	36.00
X 35 X	Lock Cable Right Upper	1	54.00
X 36 X	Lock Cable Right Lower	1	32.00
15-37	Bonnet Gasket	1	270.00
12-38	Wheel Housing Left Front	1	330.00
X 39 X	Wheel Housing Left Rear	1	430.00
X 40 X	A/C Suction Suction Pipe	1	660.00
X 41 X	A/C Pressure Pipe	1	960.00
X 42 X	A/C Pressure Pipe	1	720.00
41-43	Radiator Bracket	1	180.00

Parts Total: \$ 27,810.00

Take note of 2 unidentified parts, will re-submit again after remove and confirm

Vehicle No : SLX 55 Z

Car Model : Porsche Panamera

S/NO.	Labour Description	Repairer's Estimate (\$\$)
1	Towing from accident scene to workshop - Invoice	\$ 150.00 <i>120</i>
2	To straighten, repair, realign on affected area and replace damaged parts for front bumper	\$ 3,200.00 <i>1000</i>
3	To spary painting , blending on affected and adjacent area including right hand fender	\$ 4,000.00 <i>800</i>
4	To check electrical system and repair wire hardness for front bumper	\$ 750.00 <i>100</i>
5	To remove , replace and/or transfer parking sensor and control unit	\$ 300.00 <i>40</i>
6	To conduct chassiss alignment NN	\$ 850.00 <i>X</i>
Labour Total : <i>1940</i>		\$ 9,250.00
		<i>79820</i>

7 Days

Excess \$ 2000

Not Authorised.

Guo Qi any - 82880282

03/01/2020.

Unsump Repair.

After repair photos.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total = 21324.17
+120 = 21,444.17