

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INV No.

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE

SINGAPORE 068877

INV Date Reference AC2005954

01/09/2020

eference CC4/FCI20000137/Fka3q2

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SHC 6576E

Insured Veh. SHD 8593L

Claim No. D20000049MFSH

Policy No. D-19092579MFSH

Accident Date 26/12/2019

Inspection Date 06/01/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

MS FIRST CAPITAL INSURANCE LTD	Affiliated to Federation Internationale Des Experts En Automobile					
#16-01 CITY HOUSESINGAPORE 068877 Code: FCI2 1.	MS F	MS FIRST CAPITAL INSURANCE LTD Ref : CC4/FCI20000137/Fka3q2				
Insured Veh. SHD 8593L Veh. Inspected SHC 6576E		#16-01 CITY HOUSESINGAPORE 068877				
Policy No. D-19092579MFSH Coverage (\$) 0.00	1.		Policy Particulars	:- THIRD PARTY CLAIM		
Claim No. D20000049MFSH Excess (\$) 0.00 Assign From MERINA CHIA Assign Date 31/12/2019 2.		Insured Veh.	SHD 8593L	Veh. Inspected	SHC 6576E	
Assign From MERINA CHIA Assign Date 31/12/2019		Policy No.	D-19092579MFSH	Coverage (\$)	0.00	
2. Vehicle Particulars & Condition Make & Model KIA OPTIMA 1.7 (A) c.c. 1685 Engine No. HIDDEN Year of Reg. 2015 Chassis No. KNAGM414MF5578297 Colour SILVER Odometer 451215 Steering IN ORDER Brakes IN ORDER Modification STANDARD ALLOY RIM General FAIR FAIR 3. Conditions of Tyres R/H Front Tyre 205/65 R16 ACHILLES 7 mm L/H Front Tyre 205/65 R16 ACHILLES 7 mm R/H Rear Tyre 205/65 R16 ACHILLES 7 mm L/H Rear Tyre 205/65 R16 ACHILLES 7 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 26/12/2019 Inspection Date 06/01/2020 Survey held at PREMIER AUTOMOTIVE SERVICES PTE LTD		Claim No.	D20000049MFSH	Excess (\$)	0.00	
Make & Model KIA OPTIMA 1.7 (A) C.C 1685 Engine No.		Assign From	MERINA CHIA	Assign Date	31/12/2019	
Engine No. HIDDEN Year of Reg. 2015 Chassis No. KNAGM414MF5578297 Colour SILVER Odometer 451215 Steering IN ORDER Brakes IN ORDER Modification STANDARD ALLOY RIM General FAIR 3. Conditions of Tyres Nake Balance	2.		Vehicle Partic	culars & Condition		
Chassis No. KNAGM414MF5578297 Colour SILVER Odometer 451215 Steering IN ORDER Brakes IN ORDER Modification STANDARD ALLOY RIM General FAIR		Make & Model	KIA OPTIMA 1.7 (A)	c.c	1685	
Odometer 451215 Steering IN ORDER Brakes IN ORDER Modification STANDARD ALLOY RIM General FAIR 3. Conditions of Tyres R/H Front Tyre 205/65 R16 ACHILLES 7 mm L/H Front Tyre 205/65 R16 ACHILLES 7 mm R/H Rear Tyre 205/65 R16 ACHILLES 7 mm L/H Rear Tyre 205/65 R16 ACHILLES 7 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 26/12/2019 Inspection Date 06/01/2020 Survey held at PREMIER AUTOMOTIVE SERVICES PTE LTD		Engine No.	HIDDEN	Year of Reg.	2015	
Brakes IN ORDER Modification STANDARD ALLOY RIM General FAIR 3. Conditions of Tyres Size Make Balance		Chassis No.	KNAGM414MF5578297	Colour	SILVER	
General FAIR Conditions of Tyres Size Make Balance		Odometer 451215 Steering IN ORDER				
3. Conditions of Tyres Size Make Balance		Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
Size Make Balance		General	FAIR			
R/H Front Tyre 205/65 R16 ACHILLES 7 mm L/H Front Tyre 205/65 R16 ACHILLES 7 mm R/H Rear Tyre 205/65 R16 ACHILLES 7 mm L/H Rear Tyre 205/65 R16 ACHILLES 7 mm L/H Rear Tyre 205/65 R16 ACHILLES 7 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 26/12/2019 Inspection Date 06/01/2020 Survey held at PREMIER AUTOMOTIVE SERVICES PTE LTD	3.	3. Conditions of Tyres				
L/H Front Tyre 205/65 R16 ACHILLES 7 mm R/H Rear Tyre 205/65 R16 ACHILLES 7 mm L/H Rear Tyre 205/65 R16 ACHILLES 7 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 26/12/2019 Inspection Date 06/01/2020 Survey held at PREMIER AUTOMOTIVE SERVICES PTE LTD						
R/H Rear Tyre 205/65 R16 ACHILLES 7 mm L/H Rear Tyre 205/65 R16 ACHILLES 7 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 26/12/2019 Inspection Date 06/01/2020 Survey held at PREMIER AUTOMOTIVE SERVICES PTE LTD		R/H Front Tyre 205/65 R16 ACHILLES 7 mm				
L/H Rear Tyre 205/65 R16 ACHILLES 7 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 26/12/2019 Inspection Date 06/01/2020 Survey held at PREMIER AUTOMOTIVE SERVICES PTE LTD		L/H Front Tyre	t Tyre 205/65 R16 ACHILLES 7 mm			
4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 26/12/2019 Inspection Date 06/01/2020 Survey held at PREMIER AUTOMOTIVE SERVICES PTE LTD		R/H Rear Tyre	205/65 R16		7 mm	
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 26/12/2019 Inspection Date 06/01/2020 Survey held at PREMIER AUTOMOTIVE SERVICES PTE LTD		L/H Rear Tyre			7 mm	
DAMAGES SEE DETAILS. 5. General Information Accident Date 26/12/2019 Inspection Date 06/01/2020 Survey held at PREMIER AUTOMOTIVE SERVICES PTE LTD	4.	r	•			
5. General Information Accident Date 26/12/2019 Inspection Date 06/01/2020 Survey held at PREMIER AUTOMOTIVE SERVICES PTE LTD		THE VEHICLE SU	STAINED DAMAGES AT THE FRO	ONT PORTION.		
Accident Date 26/12/2019 Inspection Date 06/01/2020 Survey held at PREMIER AUTOMOTIVE SERVICES PTE LTD		DAMAGES SEE DETAILS.				
Survey held at PREMIER AUTOMOTIVE SERVICES PTE LTD	5.	General Information				
		Accident Date	26/12/2019	Inspection Date	06/01/2020	
OO OUANIOLOGUITU AVENUE C "OA OO OUAO BOBE 400440		Survey held at PREMIER AUTOMOTIVE SERVICES PTE LTD				
23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443						
5a. Remarks	5a.					
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
5b. Estimate Days of Repair	5b.	,				
ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days		ESTIMATED NOR	MAL PERIOD FOR REPAIR:	2 Working Days		



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6576E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	TO REPAIR SEE LABOUR	385.00	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	531.00	-
1	FRONT BUMPER EMBLEM	NOT NECESSARY	44.00	-
1	FRONT BUMPER CENTRE GRILLE	NOT NECESSARY	174.00	-
1	FRONT BUMPER LOWER STIFFER	NOT NECESSARY	134.00	-
1	FRONT BUMPER TOW HOOK COVER	NOT NECESSARY	14.00	-
1	FRONT BUMPER INNER SPONGE	NOT NECESSARY	110.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	328.00	-
2	FRONT BUMPER O/S & N/S SIDE RETAINER @\$16.00	NOT NECESSARY	32.00	-
2	FRONT BUMPER O/S & N/S UPPER BRACKET @\$16.00	NOT NECESSARY	32.00	-
2	FRONT BUMPER O/S & N/S SUPPORT BRACKET @\$16.00	NOT NECESSARY	32.00	-
	LESS 10% DISCOUNT		-181.60	-
			1,634.40	-
	SPECIAL NETT ITEMS			
1	FRONT NO PLATE WITH CASING (SN)	BENT	50.00	50.00
1	FRONT BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	SUNDRY (SN)	NECESSARY	50.00	30.00
			148.00	80.00
	LABOUR			
	TO CHECK FOR WIRING AND TO FOCUS HEADLAMPS.	NOT NECESSARY	80.00	-
	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS,KNOCK - OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE SUPPORT PANEL ETC.INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND BONNET .		750.00	300.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,BONNET GRILLE .		400.00	360.00

Report Ref No. CC4/FCI20000137/Fka3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		120.00	50.00
			1,530.00	710.00
	GRAND TOTAL		3,312.40	790.00

RECOMMENDED COST OF REPAIRS			790.00
-----------------------------	--	--	--------

Report Ref No. CC4/FCI20000137/Fka3q2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION

PHOTOGRAPHS FOR VEHICLE NO. SHC 6576E















51 Ubi Ave 1 #01-25 Paya Ubi hdustrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R TEL: 6256 3581 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Sngapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

RE-INSPECTION

PHOTOGRAPHS FOR VEHICLE NO. SHC 6576E





