

INS. CASE OWNER:

KAREN TAN

CC4/FCI20000141/Kea3

LKK:

IDAC:

ASSIGNMENT

Surveyor:

KENNETH

DOI: 06/01/2020

Date / Time: 30.12.2019

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : SHC 8266L

Name of Insured : COMFORT TRANSPORTATION P/L

Insured Tel No. : HP:

Excess Sec II : \$5

D.O.A: 24/12/2019

Is driver the owner? (YES / (NO))

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L) YES / NO)

Claim No. : D20000041MFSH

Policy No. : D-19092580MFSH

Make / Model :

Place of Accident : Braulden Rd > CTE

OI GIA REPORT YES / NO ; TP GIA REPORT YES / NO

Insured Liability : % Final ? Yes / No

SLZ 4399U

INSRS:
WSP: HUI YANG
Tel: MOTOR
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time		STAGE	DATE / PIC
	SLZ 4399U - X	Non-Reporting ltr (1st):	
	SHC 8266L - NA/LIP19022724/z4; DOA: 26.12.2019	Non-Reporting ltr (2nd):	
	OINR	Non-Reporting ltr (Final):	
14.12.20	FILE PREP TO TYPIN TO PREPARE REPORT.	Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☐
		After call ltr to OI:	☐
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☒
		Towing Invoice:	☐
		LTA / GIA :	☒
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☒
		LOD	☒
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm by:
FINALIZATION	Date/Time:	Confirm with:	Confirm by: KSL
Repair Cost:	\$5,145.00	(3 days) Reduction:	70 %
FINAL SETTLEMENT	Date/Time: 24.02.20	Confirm with B&L	Email ☒ Call ☐
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. :	21
Repair Cost:	\$5,145.00	D/O REAR EXTERIOR TP	
Loss of Rental (LOR):	\$5,246.00	(3 days) x \$172	
Loss of Use (LOU):	\$5 -	(5 x days)	
Loss of Income (LOI):	\$5 -	(5 x days)	
LOR only ☒ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐	(Tick only one)	
GIA/LTA Search	\$57.45		
Medical:	\$5 -		
Disbursement:	\$5 -	(e.g. Tow/ Independent)	
Legal Cost	\$5 -		
Total:	\$51,988.95	Global Sum \$5:	
FINAL PAYMENT	Date/Time: 24.02.20	Confirm with B&L	Email ☒ Call ☐
Payee 1:	\$51,988.95	Name 1:	HUI YANG MOTOR PTE LTD
Payee 2: (Strike if N.A.)	\$5	Name 2:	
Payee 3: (Strike if N.A.)	\$5	Name 3:	

COPY SENT 6/3/2020

ASS. REG. BY:

REF: 1021

141/e

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 875k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SL 8 43994 Yr Regn: 05, 18
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or Weapon
Make: Honda Shuttle c.c. 1496Colour: M.D. Blue AC: Insured / Std / NI / NASp. Reading: 137762 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GP7 . 1208962Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kapsen

Front

R/Bal. 7 mm

Rear

R/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 24/12/19D.O.I. 6/1/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to45: +1.000 (RED: +3.879.04 70%)

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S = RS. \$

Fuel

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Ke
輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST & Reg No. 201629438M

LKK
06/01/20
Monday

24/12/2019

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR HONDA SHUTTLE - SLZ4399U

1pc rear tailgate
1pc rear tailgate "H" logo
1pc rear tailgate "SHUTTLE" emblem
1pc rear tailgate chrome
1pc rear tailgate windscreen moulding
1pc rear tailgate inner lock
1pc rear tailgate inner rubber
1pc rear tailgate inner garnish
1pc rear bumper
2pcs rear bumper side retainer @\$38.50
10pcs rear bumper clip @\$5.00

less 20%

Not Noted
L1 Day @ \$1650h
Resony After Paint
3 days

R	\$	1,193.70	X
re	\$	58.00	—
re	\$	55.00	—
re	\$	383.10	X
re	\$	195.00	X
re	\$	289.40	X
re	\$	188.50	X
re	\$	358.50	X
re	\$	1,150.60	2
re	\$	77.00	X
re	\$	50.00	2
		\$	3,998.80
		\$	799.76
		\$	3,199.04

1set rear parking sensor
1set rear number plate & casing

2025m

re	s.nett	\$	280.00	
re	s.nett	\$	50.00	X

remove & refit rear windscreen glass
sealant
wiring
tuffkote
spray painting
labour charges
Total

re	\$	120.00	X
re	\$	80.00	X
	\$	100.00	15h
re	\$	100.00	X
	\$	800.00	400h
	\$	800.00	400h
		\$	5,529.04



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D20000041MFSH
Our ref: CC4/FCI20000141/Kea3

Date: 09/01/2020

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLZ 4399U

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 06/01/2020 at the premises of M/s Hui Yang Motor Pte Ltd - Sin Ming and have the following to report:-

Workshop Estimate Amount	: S\$	5,529.04
Revised Estimate Amount	: S\$	1,105.40
"Check" Items Amount	: S\$	960.48
Total (Including Check Items)	: S\$	2,065.88

Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 day

Yours faithfully,

KENNETH KONG
Licensed Appraiser

辉陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

24/12/2019

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR HONDA SHUTTLE - SLZ4399U

1pc	rear tailgate
1pc	rear tailgate "H" logo
1pc	rear tailgate "SHUTTLE" emblem
1pc	rear tailgate chrome
1pc	rear tailgate windscreen moulding
1pc	rear tailgate inner lock
1pc	rear tailgate inner rubber
1pc	rear tailgate inner garnish
1pc	rear bumper
2pcs	rear bumper side retainer @\$38.50
10pcs	rear bumper clip @\$5.00

less 20%

R	\$	1,193.70	X
re	\$	58.00	—
re	\$	55.00	—
re	\$	383.10	X
re	\$	195.00	X
re	\$	289.40	X
re	\$	188.50	X
re	\$	358.50	X
	\$	1,150.60	?
re	\$	77.00	X
	\$	50.00	?

\$ 3,998.80

\$ 799.76

\$ 3,199.04

1set	rear parking sensor
1set	rear number plate & casing

re	s.nett	\$	280.00	2019
re	s.nett	\$	50.00	X

	remove & refit rear windscreen glass
	sealant
	wiring
	tuffkote
	spray painting
	labour charges
	Total

re	\$	120.00	X
re	\$	80.00	X
	\$	100.00	15%
re	\$	100.00	X
	\$	800.00	4001
	\$	800.00	4001
	\$	5,529.04	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MOTOR SURVEY ASSIGNMENT

Date 27-12-2019 Our Ref No. D20000041MFSH

Accident Date 24-12-2019 Claim Type. Third Party

Insured Vehicle SHC8266L Third Party Vehicle. SLZ4399U

Survey Location BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE

Contact Person. SANDRA

Contact No. 6451 5752/ 0 Fax No. 6451 4658

Survey Type WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA Fax No. 68416315

Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop HUI YANG MOTOR PTE LTD Attention. NIL

Cc : TP Solicitor NA TP Solicitor Fax No. NA

Officer Incharge KARENT

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

P: Bel
 T: 9.00 30.12.19
 V: 04
 G. ✓

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20000141/Kea3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 11-03-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8266L	Veh. Inspected	SLZ 4399U
Policy No.	D-19092580MFSH	Coverage (\$)	0.00
Claim No.	D20000041MFSH	Excess (\$)	0.00
Assign From	KAREN TAN	Assign Date	30/12/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GP71208962	Colour	METALLIC DARK BLUE
Odometer	137762	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	KAPSEN	7 mm
L/H Front Tyre	185/60 R15	KAPSEN	7 mm
R/H Rear Tyre	185/60 R15	KAPSEN	7 mm
L/H Rear Tyre	185/60 R15	KAPSEN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/12/2019	Inspection Date	06/01/2020
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 4399U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE	TO REPAIR SEE LABOUR	1,193.70	-
1	REAR TAILGATE 'H' LOGO	NECESSARY	58.00	58.00
1	REAR TAILGATE 'SHUTTLE' EMBLEM	NECESSARY	55.00	55.00
1	REAR TAILGATE CHROME	SERVICEABLE	383.10	-
1	REAR TAILGATE WINDSCREEN MOULDING	NOT NECESSARY	195.00	-
1	REAR TAILGATE INNER LOCK	TO REPAIR SEE LABOUR	289.40	-
1	REAR TAILGATE INNER RUBBER	SERVICEABLE	188.50	-
1	REAR TAILGATE INNER GARNISH	SERVICEABLE	358.50	-
1	REAR BUMPER	MTG CRACKED	1,150.60	1,150.60
2	REAR BUMPER SIDE RETAINER @\$38.50	SERVICEABLE	77.00	-
10	REAR BUMPER CLIP @\$5.00	NECESSARY	50.00	50.00
	LESS 20% DISCOUNT		-799.76	-262.72
			3,199.04	1,050.88
SPECIAL NETT ITEMS				
1	SET REAR PARKING SENSOR (SN)	DENTED	280.00	200.00
1	SET REAR NUMBER PLATE & CASING (SN)	SERVICEABLE	50.00	-
1	SEALANT (SN)	NOT NECESSARY	80.00	-
			410.00	200.00
LABOUR				
	REMOVE & REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	WIRING .		100.00	15.00
	TUFFKOTE.	NOT NECESSARY	100.00	-
	SPRAY PAINTING.		800.00	400.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF REAR TAILGATE AND REAR TAILGATE INNER LOCK .		800.00	400.00
			1,920.00	815.00
GRAND TOTAL			5,529.04	2,065.88

Report Ref No. CC4/FCI20000141/Kea3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,650.00
---	--	--	----------

Report Ref No. CC4/FCI20000141/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.