

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20000146/T1YF3E2

Date: 21/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 0999994153
Claimant Vehicle No : SJG3134Y	Insured Vehicle No : SJN5944B
Date of Loss: 25/12/2019	Nature of Claim: TP Claim No: 6338741764SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJG3134Y		
Make & Model:	TOYOTA WISH, 1.8 X (A)	Engine No:	1ZZ3110633
Reg. Date:	26/06/2008 (Man. Year: 2008)	Chassis No:	ZNE100411186
Colour:	Maroon	Odometer:	0 km
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	03/01/2020	
Date Inspected:	03/01/2020	Inspected At: 8 Kaki Bukit Ave 4 Premier #04-20 Repairer : My Car Consultant Pte Ltd
Estimated Period of Repair:	12.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
4	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
5	1		*FRT BUMPER SPONGE	Deformed	0.00 F	*- F
6	1		*FRT RH BUMPER FOG LAMP COVER	Missing	0.00 F	*- F
7	1		*FRT GRILLE	Deformed	0.00 F	*- F
8	1		*FRT SUPPORT PANEL	Bent	0.00 F	*- F
9	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Deformed	0.00 F	*- F
10	1		*FRT BRACE PANEL	Bent	0.00 F	*- F
11	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
12	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
13	1		*BONNET	Bent	0.00 F	*- F
14	1		*BONNET EMBLEM	Necessary	0.00 F	*- F
15	1		*BONNET LOCK	Bent	0.00 F	*- F
16	1		*BONNET INSULATOR	Deformed	0.00 F	*- F
17	2		*BONNET HINGE	Bent	0.00 F	*- F
18	1		*BONNET CHROME	Cut	0.00 F	*- F
19	1		*AIR CON CONDENSER	Bent	0.00 F	*- F
20	1		*AIR CON SUCTION PIPE (LOW PRESSURE)	* Check	0.00 F	*- F
21	1		*AIR CON DISCHARGE PIPE (HIGH PRESSURE)	* Check	0.00 F	*- F
22	1		*AIR CON COMPRESSOR ASSY	Cracked	0.00 F	*- F
23	1		*AIR CON BELT	Cut	0.00 F	*- F
24	1		*RADIATOR	Bent	0.00 F	*- F
25	1		*RADIATOR COWLING	Deformed	0.00 F	*- F
26	1		*RADIATOR FAN ASSY	Cracked	0.00 F	*- F
27	1		*RADIATOR HOSE TOP	Deformed	0.00 F	*- F
28	1		*RADIATOR EXPANSION TANK	Deformed	0.00 F	*- F
29	1		*AIR CLEANER ASSY	Deformed	0.00 F	*- F
30	1		*FRT EXHAUST MANIFOLD	* Check	0.00 F	*- F
31	1		*WIPER WASHER TANK	Deformed	0.00 F	*- F
32	1		*WIPER WASHER TANK MOTOR	Distorted	0.00 F	*- F
33	1		*ALTERNATOR ASSY	* Check	0.00 F	*- F
34	1		*ABS PUMP CONTROL UNIT	Distorted	0.00 F	*- F
35	1		*ENGINE TOP COVER	Cracked	0.00 F	*- F
36	1		*ENGINE UNDER COVER	Deformed	0.00 F	*- F
37	1		*ENGINE MOUNTING FRT	Bent	0.00 F	*- F
38	1		*FRT LH CHASSIS MEMBER	Repair	0.00 F	*- F
39	1		*FRT RH CHASSIS MEMBER	Repair	0.00 F	*- F
40	1		*FRT LH FENDER	Bent	0.00 F	*- F
41	1		*FRT LH FENDER INNER SHIELD	Deformed	0.00 F	*- F
42	1		*FRT RH FENDER	Bent	0.00 F	*- F
43	1		*FRT RH FENDER INNER PANEL	Bent	0.00 F	*- F
44	1		*FRT RH FENDER INNERSHIELD	Deformed	0.00 F	*- F
45	1		*FRT WINDSCREEN GLASS	Cracked	0.00 F	*- F
46	1		*FRT WINDSCREEN MOULDING	Necessary	0.00 F	*- F
47	1		*FRT WINDSCREEN SEALANT	Necessary	0.00 F	*- F
48	1		*ERP BRACKET	Necessary	0.00 F	*- F
49	1		*WIPER PANEL GARNISH	Deformed	0.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*DASHBOARD ASSY	Deformed	0.00 F	*- F
51	1		*STEERING WHEEL AIRBAG	Activated	0.00 F	*- F
52	1		*STEERING WHEEL AIRBAG SENSOR	Activated	0.00 F	*- F
53	1		*DASHBOARD AIRBAG	Activated	0.00 F	*- F
54	1		*DASHBOARD AIRBAG SENSOR	Activated	0.00 F	*- F
55	1		*AIRBAG CONTROL UNIT	Activated	0.00 F	*- F
56	1		*FRT RH SEAT BELT ASSY	Activated	0.00 F	*- F
57	1		*FRT LH SEAT BELT ASSY	Activated	0.00 F	*- F
58	1		*WIRE HARNESS	Torn	0.00 F	*- F
F=Franchise part.						
					Total Parts (\$\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >