



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20000159/Hea3s2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 19-05-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|---------------------|----------------|-----------------------|------------|
| Insured Veh. | SHA 394M | Veh. Inspected | YQ 1543H |
| Policy No. | D-19092579MFSH | Coverage (\$) | 0.00 |
| Claim No. | D19008044MFSH | Excess (\$) | 0.00 |
| Assign From | MERINA CHIA | Assign Date | 02/01/2020 |

2. Vehicle Particulars & Condition

| | | | |
|-------------------------|-------------------|---------------------|------------|
| Make & Model | MUTSUBISHI CANTER | c.c | 2998 |
| Engine No. | HIDDEN | Year of Reg. | 2019 |
| Chassis No. | FEB21EA30218 | Colour | WHITE |
| Odometer | 14994 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | FAIR | | |

3. Conditions of Tyres

| | | | |
|-----------------------|----------------|-------------|----------------|
| | Size | Make | Balance |
| R/H Front Tyre | 195/65 R15 | DUNLOP | 5 mm |
| L/H Front Tyre | 195/65 R15 | DUNLOP | 5 mm |
| R/H Rear Tyre | 195/65 R15 (D) | DUNLOP | 5/5 mm |
| L/H Rear Tyre | 195/65 R15(D) | DUNLOP | 5/5 mm |

4. Description of Damages

| |
|---|
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, FRONT N/S PORTION AND N/S DOOR. DAMAGES SEE DETAILS. |
|---|

5. General Information

| | | | |
|-----------------------|--|------------------------|------------|
| Accident Date | 20/12/2019 | Inspection Date | 14/01/2020 |
| Survey held at | EXCLUSIVE ENTERPRISE PTE LTD 8 KAKI BUKIT AVENUE 4 #03-49 PREMIER @ KAKI BUKIT SINGAPORE 415875 | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 8 Working Days |
|-------------------------------------|-----------------------|