

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20000161/AGS3Q2

Date: 02/10/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MPC0003536
Claimant Vehicle No :	SKC6242H	Insured Vehicle No :	SLA2935S
Date of Loss:	27/12/2019	Nature of Claim:	TP
		Claim No:	MPC2019D0001727

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC6242H		
Make & Model:	KIA CERATO FORTE KOUP, 1.6 SX ABS D/AB SR (A)	Engine No:	G4FCBH356987
Reg. Date:	15/09/2011 (Man. Year: 2011)	Chassis No:	KNAFW611MB5478518
Colour:	Red	Odometer:	135640 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,661.71	12,183.97	4,477.74	26.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,000.00	4,760.00	1,240.00	20.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,661.71	16,943.97	5,717.74	25.23
Approved Total (Overridden) (S\$)		7,500.00		
Nett Amount (S\$)	22,661.71	7,500.00	15,161.71	66.90
+ Loss of Use (18.0 x S\$50.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		8,407.49		
Global Sum Settlement (S\$)		8,400.00		

INSPECTION

Date of Assignment:	30/12/2019	
Date Inspected:	30/12/2019 Inspected At:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit Singapore 417883

Estimated Period of Repair: 18.0 days

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 May 2020)
Parts:	143	KIA CERATO FORTE KOUP 1.6 SX ABS D/AB SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKC6242H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR WINDSCREEN RUBBER	Necessary	91.30 FL	*91.30 FL
2	1	*REAR BOOTLID	Distorted	968.00 FL	*968.00 FL
3	2	*REAR BOOTLID HINGES	Not Necessary	171.60 FL	*- FL
4	1	*REAR BOOTLID UPPER LOCK	Damaged	57.20 FL	*57.20 FL
5	1	*REAR BOOTLID LOWER LOCK	Not Necessary	143.00 FL	*- FL
6	1	*REAR BOOTLID WEATHER STRIP	Cut	113.10 FL	*113.10 FL
7	1	*REAR BOOTLID INSULATION	Torn	193.40 FL	*193.40 FL
8	1	*REAR BOOTLID INNER HANDLE	Not Necessary	63.80 FL	*- FL
9	1	*REAR BOOTLID CENTRE EMBLEM	Necessary	35.20 FL	*35.20 FL
10	1	*REAR BOOTLID FORTE EMBLEM	Necessary	38.50 FL	*38.50 FL
11	1	*REAR BOOTLID COUP EMBLEM	Necessary	41.80 FL	*41.80 FL
12	2	*REAR BOOTLID REFLECTOR	Not Necessary	261.00 FL	*- FL
13	1	*REAR BOOTLID TOP SPOILER	Not Necessary	550.00 FL	*- FL
14	2	*REAR LAMP	N/S Cut / O/S Cracked	633.60 FL	*633.60 FL
15	1	*REAR LAMP HOUSING	O/S Buckled	215.60 FL	*107.80 FL
16	1	*REAR END PANEL	Distorted	321.20 FL	*321.20 FL
17	1	*REAR END PANEL TOP GARNISH	Deformed	90.20 FL	*90.20 FL
18	1	*REAR BUMPER	Distorted	613.80 FL	*613.80 FL
19	2	*REAR BUMPER SIDE HOLDER	Necessary	63.80 FL	*63.80 FL
20	2	*REAR BUMPER LOWER SIDE GARNISH	Not Necessary	215.00 FL	*- FL
21	1	*REAR BUMPER LOWER GARNISH	Distorted	115.50 FL	*115.50 FL
22	2	*REAR BUMPER LOWER REFLECTOR	Cracked	109.00 FL	*109.00 FL
23	1	*REAR RH FENDER	Buckled	921.60 FL	*921.60 FL
24	2	*REAR FENDER INNER GARNISH	Torn	303.60 FL	*303.60 FL
25	2	*REAR FENDER INNER SHIELD	Not Necessary	106.80 FL	*- FL
26	1	*REAR SPARE TYRE TOP BOARD	Deformed	176.00 FL	*176.00 FL
27	1	*REAR SPARE TYRE WELL	Distorted	715.00 FL	*715.00 FL
28	1	*REAR SPARE TYRE WELL INSULATION (3 PCS)	Necessary	490.05 FS	*200.00 FS
29	1	*REAR NUMBER PLATE LAMP	Cracked	69.10 FL	*69.10 FL
30	2	*REAR EXHAUST PIPE CHROME	Not Necessary	130.00 FL	*- FL
31	1	*REAR EXHAUST PIPE	Not Necessary	711.70 FL	*- FL
32	1	*REAR EXHAUST PIPE MOUNTING	Not Necessary	68.20 FL	*- FL
33	1	*REAR BUMPER REINFORCEMENT	Distorted	267.30 FL	*267.30 FL
34	1	*REAR BUMPER SPONGE	Cracked	140.60 FL	*140.60 FL
35	2	*REAR BUMPER BRACKET	Bent	98.60 FL	*98.60 FL
36	1	*FRONT BONNET	Distorted	1,075.80 FL	*1,075.80 FL
37	2	*FRONT BONNET HINGES	Not Necessary	136.20 FL	*- FL
38	1	*FRONT BONNET RUBBER	Not Necessary	31.40 FL	*- FL
39	1	*FRONT BONNET INSULATOR	Not Necessary	193.20 FL	*- FL
40	1	*FRONT SUPPORT	Distorted	594.70 FL	*594.70 FL
41	1	*FRONT GRILLE	Cracked	215.60 FL	*215.60 FL
42	1	*FRONT GRILLE EMBLEM	Necessary	35.20 FL	*35.20 FL
43	4	*FRONT GRILLE CLIPS	Necessary	30.80 FL	*30.80 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*FRONT BONNET LOCK	Damaged	58.10 FL	*58.10 FL
45	1		*FRONT BONNET LOCK BRACKET	Not Necessary	25.30 FL	*- FL
46	2		*FRONT HEADLAMP	Cracked	1,067.00 FL	*1,067.00 FL
47	2		*FRONT HEADLAMP LOWER BRACKET	Not Necessary	63.80 FL	*- FL
48	1		*FRONT BUMPER	Distorted	614.50 FL	*614.50 FL
49	2		*FRONT BUMPER SIDE HOLDER	Necessary	70.40 FL	*70.40 FL
50	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	68.20 FL	*- FL
51	1		*FRONT BUMPER CENTRE LOWER GRILLE	Not Necessary	31.90 FL	*- FL
52	2		*FRONT BUMPER FOD LAMP COVER	Cracked	55.00 FL	*55.00 FL
53	2		*FRONT BUMPER FOG LAMP	Cracked	312.00 FL	*312.00 FL
54	1		*FRONT BUMPER REINFORCEMENT	Bent	268.20 FL	*268.20 FL
55	2		*FRONT BUMPER BRACKET	Not Necessary	98.60 FL	*- FL
56	1		*FRONT BUMPER SPONGE	Cracked	114.20 FL	*114.20 FL
57	1		*SET FRONT BUMPER CLIPS	Necessary	66.00 FL	*30.00 FL
58	1		*FRONT AIR DUCT	Not Necessary	75.00 FL	*- FL
59	2		*FRONT FENDER	Repair	642.40 FL	*- FL
60	2		*FRONT FENDER INNER SHIELD	Not Necessary	127.60 FL	*- FL
61	1		*AIR COND CONDENSER	Bent	748.00 FL	*748.00 FL
62	2		*AIR COND SIDE GARNISH	Deformed	61.60 FL	*61.60 FL
63	1		*RADIATOR	Bent	662.00 FL	*662.00 FL
64	1		*RADIATOR FAN ASSY	Cracked	495.00 FL	*495.00 FL
65	1		*FRONT RADIATOR TOP HOSE	Not Necessary	52.80 FL	*- FL
66	1		*FRONT RADIATOR HOSE	Not Necessary	52.80 FL	*- FL
67	4		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	760.00 FS	*380.00 FS
68	1		*REAR NUMBER PLATE HOLDER	Bent	50.00 FS	*30.00 FS
69	1		*REAR NUMBER PLATE	Bent	50.00 FS	*30.00 FS
70	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,357.45	13,463.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,695.74	1,279.33
Total Parts (\$\$)	16,661.71	12,183.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO SUPPLY REAR WINDSCREEN SEALANT	New	50.00	50.00
2	TO SUPPLY REAR END PANEL SEALANT	New	200.00	60.00
3	REMOVE & REINSTALL REAR WINDSCREEN	New	150.00	120.00
4	REMOVE & REINSTALL REVERSE SENSOR	New	150.00	50.00
5	REMOVE & REINSTALL EXHAUST PIPE	New	200.00	0.00
6	REMOVE & REINSTALL ROOF LINING+CUSHION	New	200.00	80.00
7	REMOVE & REINSTALL PETROL TANK	New	150.00	80.00
8	REMOVE & REINSTALL AIR COND FILL IN GAS	New	150.00	120.00
9	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	2,800.00	2,400.00
10	RESPRAY PAINTING	New	1,800.00	1,700.00
11	TUFF KOTE	New	150.00	100.00
Gross Labour Cost (S\$)			6,000.00	4,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >