

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20000169/APS3Q2

Date: 14/04/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MCV0000130_01
Claimant Vehicle No :	SMH8787P	Insured Vehicle No :	YM6084D
Date of Loss:	31/12/2019	Nature of Claim:	TP
		Claim No:	MCV2020D0000069

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH8787P		
Make & Model:	BMW 316I, 1.6 AT D/AB 4DR ABS HID (A)	Engine No:	A968J432N13B16A
Reg. Date:	25/04/2013 (Man. Year: 2013)	Chassis No:	WBA3A120X0J720104
Colour:	Red	Odometer:	135129 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/35 R19	Rear Tyre Size:	235/35 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,301.05	6,993.09	6,307.96	47.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,110.00	1,250.00	1,860.00	59.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,411.05	8,243.09	8,167.96	49.77
Approved Total (Overridden) (S\$)		6,600.00		
(S\$)	16,411.05	6,600.00	9,811.05	59.78
+ GST 7.00/7.00% (S\$)	1,148.77	462.00	686.77	59.78
Nett Amount (S\$)	17,559.82	7,062.00	10,497.82	59.78
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,424.00		
Global Sum Settlement (S\$)		7,400.00		

INSPECTION

Date of Assignment: 03/01/2020

Date Inspected: 03/01/2020 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)
1 Kaki Bukit Ave 6, Blk C #01-43

Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Mar 2020)
Parts:	143	BMW 316I 1.6 AT D/AB 4DR ABS HID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH8787P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	1,281.20 F	*- FL
2	2		*FRONT BONNET HINGE	Not Necessary	150.20 F	*- FL
3	1		*FRONT BONNET SHOCK ABSORBER	Not Necessary	237.40 F	*- FL
4	1		*FRONT BONNET LOCK	Not Necessary	128.40 F	*- FL
5	1		*FRONT BONNET INNER RUBBER	Not Necessary	69.10 F	*- FL
6	2		*FRONT HEAD LAMP	Cracked	4,260.80 F	*4,260.80 FL
7	2		*FRONT HEAD LAMP LOWER BRACKET	Not fitted	264.40 F	*- FL
8	1		*FRONT BUMPER	Deformed	1,244.45 F	*1,244.45 FL
9	1		*FRONT BUMPER LOWER	Not Necessary	1,307.90 F	*- FL
10	10		*FRONT BUMPER CLIP	Necessary	65.00 F	*30.00 FL
11	2		*FRONT BUMPER SIDE RETAINER	Necessary	120.40 F	*120.40 FL
12	2		*FRONT BUMPER FOG LAMP	Not Necessary	600.60 F	*- FL
13	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	221.00 F	*- FL
14	1		*FRONT BUMPER EMBLEM LOGO	Necessary	71.60 F	*71.60 FL
15	1		*FRONT BUMPER CENTER GARNISH	Deformed	158.00 F	*158.00 FL
16	1		*FRONT BUMPER TOWING COVER	Not Necessary	52.20 F	*- FL
17	2		*FRONT BUMPER WASHER COVER	Not Necessary	125.60 F	*- FL
18	1		*FRONT BUMPER NUMBER PLATE	Not Necessary	50.00 F	*- FL
19	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	390.00 F	*- FL
20	1		*FRONT BUMPER INNER FOAM	Not Necessary	74.50 F	*- FL
21	4		*FRONT BUMPER SENSOR	Not Necessary	952.40 F	*- FL
22	2		*FRONT GRILLE ASSY	Cracked	410.60 F	*410.60 FL
23	1		*FRONT SUPPORT PANEL	Cracked	899.30 F	*899.30 FL
24	1		*FRONT AIR DUCT COWLING	Cracked	166.00 F	*166.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	13,301.05	7,361.15
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	368.06

Total Parts (\$\$)	13,301.05	6,993.09
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT AIR-CON CONDENSER ,RADIATOR ,FAN MOTOR & TOP UP GAS	New	280.00	120.00
2	TO RESET COMPUTER	New	180.00	0.00
3	TO CHECK WIRING	New	100.00	30.00
4	TUFF KOTE	New	150.00	0.00
5	PANEL BEATING	New	1,000.00	600.00
6	SPRAY PAINTING	New	1,400.00	500.00
Gross Labour Cost (\$\$)			3,110.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >