Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20000172/APS3Q2

Date: 03/02/2021

REFERENCE

Price:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant SLM6565L Insured Vehicle No: SMP4559R

Date of Loss: 21/12/2019 Nature of Claim: TP Claim No: 8593500763SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLM6565L

 Make & Model:
 BMW X6 XDRIVE 35I ABS D/AB, 3.0 (A)
 Engine No:
 09448036N55B30A

 Reg. Date:
 27/06/2012 (Man. Year: 2012)
 Chassis No:
 WBAFG22050L596572

Colour: White Odometer: 103626 km

Engine Capacity: 2979 cc Market Value/New Car

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/40R20 Rear Tyre Size: 275/40R20
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,138.51	2,645.94	3,492.57	56.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,520.00	1,030.00	1,490.00	59.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,658.51	3,675.94	4,982.57	57.55
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	8,658.51	2,900.00	5,758.51	66.51
+ GST 7.00/7.00% (S\$)	606.10	203.00	403.10	66.51
Nett Amount (S\$)	9,264.61	3,103.00	6,161.61	66.51
+ Loss of Use (4.0 x S\$15	50.00/day) (S\$)	600.00		
	(S\$)	3,703.00		
Liable Amount (50.00%) (S\$) + Doc/Search Fee (S\$) Nett Liability (S\$) Global Sum Settlement (S\$)		1,851.50		
		2.00		
		1,853.50		
		1,850.00		

INSPECTION

Date of Assignment: 03/01/2020

Date Inspected: 03/01/2020 Inspected At: Success United Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=ge... 3/2/2021

Adjuster Report Page 2 of 4

AutoHub Singapore 417921

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount		
1	1		*REAR DOOR LH	Dented	2,527.20 FL	*2,527.20 FL		
2	1		*REAR DOOR MECHANISM LOCK LH	Not Necessary	798.00 FL	*- FL		
3	1		*REAR DOOR WEATHERSTRIP LH	Necessary	258.00 FL	*258.00 FL		
4	1		*REAR FENDER GUARD LH	Repair	980.50 FL	*- FL		
5	1		*REAR DOOR GUARD LH	Repair	1,018.00 FS	*-FS		
6	1		*SIDE ROCKER SKIRT LH	Repair	785.00 FS	*-FS		
F=Franchise part. S=SpcNett. L=ListItemDisc.								
				Sub Total (S\$)	6,366.70	2,785.20		
- List Item Discount on L Items 5.00/5.00% (S\$)				228.19	139.26			
				Total Parts (S\$)	6,138.51	2,645.94		
			Report was unsubmitted durir	ng this print-out.				

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	<u>Labour Items</u>							
1	TO REMOVE, REARRANGE ELECTRICAL WIRINGS, CHECKLIGHTING	(New	120.00	30.00				
2	TO REMOVE,REPAIR AND REPLACED DAMAGED BODYPARTS,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	400.00				
3	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	1,200.00	600.00				
	Gross Labour Cost (S\$)		2,520.00	1,030.00				
	Report was unsubmitted during this print-out.							

< END OF ESTIMATES >