

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III20000187/FVD3E2

Date: 03/02/2020

REFERENCE

Insured/Claimant: PAN PACIFIC VAN & TRUCK LEASING
PTE LTD

Policy No: D19MFL0005549

Date of Loss: 26/12/2019

Nature of
Claim:

OD

Claim
No:

MFL2020D0000044

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ5799U**

Make & Model: TOYOTA HIACE, 2.8 D (A)

Engine No: 1GD8372804

Reg. Date: 31/05/2019 (Man. Year: 2018)

Chassis No: GDH2012004541

Colour: Black

Odometer: 14106 km

Engine Capacity: 2754 cc

Market Value/New Car Price: S\$61,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/80 R15

Rear Tyre Size:

195/80 R15

Front Left Side: Dunlop 8 mm

Rear Left Side:

Dunlop 8 mm

Front Right Side: Dunlop 8 mm

Rear Right Side:

Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,995.90	3,455.90	540.00	13.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,010.00	1,380.00	630.00	31.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,005.90	4,835.90	1,170.00	19.48
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	4,505.90	3,335.90	1,170.00	25.97
+ GST 7.00/7.00% (S\$)	315.41	233.51	81.90	25.97
Nett Amount (S\$)	4,821.31	3,569.41	1,251.90	25.97

INSPECTION

Date of Assignment: 03/01/2020

Date Inspected: 03/01/2020 Inspected At:

Efficient Motor & Engineering Works Pte
Ltd (HQ)
56 Loyang Way #06-07, Loyang Enterprise
Building
Singapore 508775

Estimated Period of Repair: 5.0 days

Adjuster: PARASURAM SHANMUGAM**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 03 Feb 2020)	
Parts:	N/A	TOYOTA HIACE 2.8 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ5799U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (WCP)	Buckled	90.00 F	*90.00 F
2	1		*BONNET LOGO (WCP)	Necessary	28.00 F	*28.00 F
3	1		*FRONT GRILLE (WCP)	Scratched	90.00 F	*90.00 F
4	1		*FRONT BUMPER (WCP)	Cracked	90.00 F	*90.00 F
5	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	90.00 F	*90.00 F
6	1		*FRONT BUMPER BEAM (WCP)	Bent	85.00 F	*75.00 F
7	1		*FRONT BUMPER BRACKET LH (WCP)	Broken	35.00 F	*30.00 F
8	1		*FRONT BUMPER BRACKET RH (WCP)	Broken	35.00 F	*30.00 F
9	1		*FRONT BUMPER SIDE RETAINER RH (WCP)	Not Necessary	55.00 F	*- F
10	1		*FRONT BUMPER SIDE RETAINER LH (WCP)	Broken	55.00 F	*55.00 F
11	10		*FRONT BUMPER CLIPS (WCP)	Necessary	45.00 F	*45.00 F
12	1		*FRONT BUMPER LOWER GRILLE (WCP)	Cracked	65.00 F	*40.00 F
13	1		*HEADLAMP LH (WCP)	Cracked	320.00 F	*320.00 F
14	1		*HEADLAMP ECU LH (WCP)	Necessary	240.00 F	*220.00 F
15	1		*HEADLAMP RH (WCP)	Cracked	320.00 F	*320.00 F
16	1		*HEADLAMP ECU RH (WCP)	Necessary	240.00 F	*220.00 F
17	1		*AIR FILTER HOUSING (WCP)	Broken	450.00 F	*350.00 F
18	1		*AIR CON CONDENSER (WCP)	Bent	180.00 F	*120.00 F
19	1		*RADIATOR (WCP)	Bent	600.00 F	*600.00 F
20	1		*FRONT SUPPORT PANEL TOP (WCP)	Dented	50.00 F	*50.00 F
21	1		*FRONT SUPPORT PANEL LH (WCP)	Not Necessary	75.00 F	*- F
22	1		*FRONT SUPPORT PANEL RH (WCP)	Not Necessary	75.00 F	*- F
23	1		*FRONT NUMBER PLATE	Not Necessary	45.00 FS	*- FS
24	4		*COOLANT	Necessary	36.00 FS	*36.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
25	1		*RADIATOR COWLING (WCP)	Broken	95.00 F	*95.00 F
26	1		*FRONT SUPPORT PANEL EXTENSION (WCP)	Dented	140.00 F	*140.00 F
27	1		*FRONT NUMBER PLATE (WCP)	Missing	11.00 F	*11.00 F
					Sub Total (S\$)	3,640.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	355.90
					Total Parts (S\$)	3,995.90

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR PANEL BEATING	New	1,000.00	800.00
2	LABOUR FOR SPRAYPAINTING	New	800.00	450.00
3	WIRING	New	60.00	30.00
4	LABOUR FOR REMOVE & REFIX AIR CON CONDENSER. TOP UP AND VACUUM AIR CON GAS	New	150.00	100.00
Gross Labour Cost (S\$)			2,010.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >