



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

INV No. AC2005578
INV Date 13/08/2020
Reference CS/SMO20000189/T1sf3n2
Code SMO



PROFESSIONAL SERVICE FEE

Vehicle No. GV 8395J
Insured Veh. SKE 2398H
Claim No. CMTD2000030/IJH
Policy No.
Accident Date 30/12/2019
Inspection Date 30/06/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO20000189/T1sf3n2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 13-08-2020		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKE 2398H	Veh. Inspected	GV 8395J	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2000030/IJH	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	03/01/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA 150 D	c.c	2986	
Engine No.	HIDDEN	Year of Reg.	2002	
Chassis No.	JTFUF34Y503000583	Colour	BLUE	
Odometer	369730	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185 R14	LINAM	6 mm	
L/H Front Tyre	185 R14	LINAM	6 mm	
R/H Rear Tyre	155 R12 (D)	LINAM	6/6 mm	
L/H Rear Tyre	155 R12 (D)	LINAM	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/12/2019	Inspection Date	30/06/2020	
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GV 8395J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE	TO REPAIR SEE LABOUR	1,910.80	-
1	TAILGATE LOWER SIDE BRACKET LH	TO REPAIR SEE LABOUR	304.70	-
1	TAILGATE LOWER SIDE BRACKET RH	TO REPAIR SEE LABOUR	304.70	-
2	TAILGATE STOPPER	N/S MISSING / O/S NOT NECESSARY	55.00	27.50
4	TAILGATE LOWER HINGE	TO REPAIR SEE LABOUR	305.00	-
1	TAILLAMP PANEL LH	BENT	242.65	242.65
1	TAILLAMP PANEL RH	NOT NECESSARY	242.65	-
1	TAILLAMP LH	CRACKED	253.00	253.00
1	TAILLAMP RH	NOT NECESSARY	253.00	-
1	REAR STEP BRACKET	BENT	311.65	311.65
1	REAR TAILGATE LOWER MEMBER	TO REPAIR SEE LABOUR	485.90	-
1	REAR NUMBER PLATE BRACKET	NOT NECESSARY	196.90	-
2	REAR NUMBER PLATE LAMP	NOT NECESSARY	97.00	-
1	SPARE TYRE CARRIER	TO REPAIR SEE LABOUR	443.00	-
	LESS 25% DISCOUNT		-1,351.49	-208.70
			4,054.46	626.10
<u>SPECIAL NETT ITEMS</u>				
1	STICKER-70 KM/H (SN)	NECESSARY	70.00	20.00
1	STICKER-13 PAX (SN)	NECESSARY	70.00	20.00
1	STICKER (SN)	NECESSARY	250.00	150.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	80.00	-
			470.00	190.00
<u>LABOUR</u>				
	CHECK REAR WIRING AND LIGHTING SYSTEM.		60.00	30.00
	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW.	NOT NECESSARY	200.00	-

Report Ref No. CS/SMO20000189/T1sf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REFIT STICKER ON AFFECTED AREAS.		400.00	150.00
	PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF TAILGATE, TAILGATE LOWER SIDE BRACKET LH, TAILGATE LOWER SIDE BRACKET RH, TAILGATE LOWER HINGE, REAR TAILGATE LOWER MEMBER AND SPARE TYRE CARRIER.		1,200.00	600.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,200.00	600.00
	APPLY ANTI RUST ON AFFECTED AREAS.		150.00	30.00
			3,210.00	1,410.00
GRAND TOTAL			7,734.46	2,226.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,800.00

Report Ref No. CS/SMO20000189/T1sf3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GV 8395J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GV 8395J

RE-INSPECTION

