



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2004736
INV Date 06/07/2020
Reference CC4/LPC20000190/Uba3n2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SFD 9420U
Insured Veh. XE 2610R
Claim No. 19/19/20/VC06/022820
Policy No. Z/19/VC06/104965
Accident Date 23/12/2019
Inspection Date 03/01/2020

| Description | Total |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00 |
| Subtotal | 400.00 |
| GST (7%) | 28.00 |
| Grand Total | 428.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|-----------------------|------------------------------|---|
| LONPAC INSURANCE BHD | | | Ref : CC4/LPC20000190/Uba3n2 | |
| 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555 | | | Date : 06-07-2020 |  |
| | | | Code : LPC2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | XE 2610R | Veh. Inspected | SFD 9420U | |
| Policy No. | Z/19/VC06/104965 | Coverage (\$) | 0.00 | |
| Claim No. | 19/19/20/VC06/022820 | Excess (\$) | 0.00 | |
| Assign From | ONG LI LI | Assign Date | 31/12/2019 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | MAZDA 6 (A) | c.c | 1998 | |
| Engine No. | HIDDEN | Year of Reg. | 2018 | |
| Chassis No. | JM6GL1071J0136932 | Colour | BLUE | |
| Odometer | 52992 | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 225/55 ZR17 | TOYO | 7 mm | |
| L/H Front Tyre | 225/55 ZR17 | TOYO | 7 mm | |
| R/H Rear Tyre | 225/55 ZR17 | TOYO | 7 mm | |
| L/H Rear Tyre | 225/55 ZR17 | TOYO | 7 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 23/12/2019 | Inspection Date | 03/01/2020 | |
| Survey held at | TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 3 Working Days | | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFD 9420U

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|----------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | REAR BUMPER | DENTED / DEFORMED | 1,266.60 | 1,266.60 |
| 4 | TAPE ,PROTECTOR | NECESSARY | 34.40 | 34.40 |
| 2 | SENSOR ,ULTRASONIC KE/BN | SERVICEABLE | 363.40 | - |
| 2 | SENSOR ULTRASONIC | NOT NECESSARY | 407.20 | - |
| 2 | RETAINER | NOT NECESSARY | 36.40 | - |
| 2 | RETAINER | NOT NECESSARY | 36.40 | - |
| 1 | GROMMET ,SCREW | NECESSARY | 2.70 | 2.70 |
| 1 | BRACKET ,BUMPER SKYACTIV | NECESSARY | 5.40 | 5.40 |
| 1 | RETAINER RHR BUMPE GJ | NOT NECESSARY | 41.00 | - |
| 1 | RETAINER LHR BUMPE | NOT NECESSARY | 41.00 | - |
| 1 | SHIELD (R) ,SPLASH -R.B GJ | NOT NECESSARY | 53.90 | - |
| 1 | MGHP9-50-350C/SHIELD (L) ,SPLASH -R.B GJ | NOT NECESSARY | 45.60 | - |
| 4 | CLIPS | NECESSARY | 14.80 | 14.80 |
| 2 | CAP DRIP MOULD | NECESSARY | 31.80 | 31.80 |
| 2 | FASTENER | NECESSARY | 6.00 | 6.00 |
| 1 | MGJR9-50-EK1A13/COVER (R),TOWING HOOK | NOT NECESSARY | 24.90 | - |
| 1 | MGJR9-50-EK1A13/COVER (L),TOWING HOOK | NOT NECESSARY | 24.90 | - |
| 1 | REFLECTOR LHR REFLEX | NOT NECESSARY | 53.00 | - |
| 1 | REFLECTOR RHR REFLEX | NOT NECESSARY | 53.00 | - |
| 1 | REINF,REAR BUMPER GJ/GL | NOT NECESSARY | 538.30 | - |
| 6 | FASTENER | NECESSARY | 18.00 | 18.00 |
| 1 | CLIPS | NECESSARY | 3.00 | 3.00 |
| 1 | PANEL ,REAR END GJ | TO REPAIR SEE LABOUR | 700.10 | - |
| | | | 3,801.80 | 1,382.70 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | NUMBER PLATE (REAR) (SN) | NOT NECESSARY | 70.00 | - |
| 1 | SUNDRIES (SN) | NECESSARY | 100.00 | 20.00 |
| | | | 170.00 | 20.00 |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---|---------------|---------------------------|-------------------|
| | LABOUR | | | |
| | TO REPLACE REAR BUMPER ,REAR REINFORCEMENT AND REAR END PANEL ,TO REPAIR BOOTLID AND ALL AREAS AFFECTED BY THE ACCIDENT .INCLUSIVE OF THE REPAIR OF PANEL ,REAR END GJ. | | 2,640.00 | 660.00 |
| | TO RESPRAY REAR BUMPER . | | 2,520.00 | 630.00 |
| | TO REMOVE AND REFIT CARPET AND TRIMS ON THE REAR SECTION TO GIVE WAY FOR THE REPAIR ON THE REAR SECTION . | NOT NECESSARY | 1,320.00 | - |
| | TO SUPPLY TEROSTAT SELANAT ON THE CUTTING AREAS. | NOT NECESSARY | 250.00 | - |
| | TO TRANSFER REVERSE SENSORS . | | 330.00 | 180.00 |
| | TO CARRY -OUT BODY CAVITY PRESERVATION . | NOT NECESSARY | 250.00 | - |
| | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING. | | 250.00 | 120.00 |
| | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS. | | 350.00 | 150.00 |
| | TO SUPPLY BRILA PREMIUM COATING. | | 350.00 | 150.00 |
| | | | 8,260.00 | 1,890.00 |
| | GRAND TOTAL | | 12,231.80 | 3,292.70 |
| RECOMMENDED COST OF REPAIRS | | | | 3,292.70 |

Report Ref No. CC4/LPC20000190/Uba3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SFD 9420U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SFD 9420U

RE-INSPECTION

