

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20000226/R1SD3Q2**Date:** 13/11/2020**REFERENCE**

Insured/Claimant: BEATRICE CHENG BEE ONG

Policy No: 1700086430-01

Date of Loss: 30/12/2019

Nature of Claim: OD

Claim No: 2818726378SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJX753R**

Make & Model: AUDI A5, 2.0 SPORTBACK (A)

Engine No: CVK050875

Reg. Date: 07/12/2017 (Man. Year: 2017)

Chassis No: WAUZZZF5XJA049879

Colour: Green

Odometer: 24418 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$142,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16

Rear Tyre Size: 205/55R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,262.00	3,477.60	5,784.40	62.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,012.00	9,327.00	8,685.00	48.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,274.00	12,804.60	14,469.40	53.05
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	25,674.00	11,204.60	14,469.40	56.36
+ GST 7.00/7.00% (S\$)	1,797.18	784.32	1,012.86	56.36
Nett Amount (S\$)	27,471.18	11,988.92	15,482.26	56.36

INSPECTION

Date of Assignment: 06/01/2020

Date Inspected: 03/01/2020 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 12.0 days

Adjuster: MOHD RASUL**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE PANEL-LH	Bent	2,285.00 FS	*1,828.00 FS
2	1		*SIDE WINDOW-LH	Missing	653.00 FS	*522.40 FS
3	1		*REAR DOOR-LH	Repair	2,829.00 FS	*- FS
4	1		*REAR DOOR OUTER SEAL-LH	Not Necessary	201.00 FS	*- FS
5	1		*BONDING AGENT	Not Necessary	45.00 FS	*- FS
6	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
7	1		*REAR DOOR CATCH	Not Necessary	109.00 FS	*- FS
8	1		*DOOR HANDLE TRIM PLATE-LH	Not Necessary	80.00 FS	*- FS
9	1		*TRIM-LH	Not Necessary	124.00 FS	*- FS
10	1		*SILL PANEL TRIM ATTACHMENT PARTS	Necessary	118.00 FS	*94.00 FS
11	1		*SILL PANEL TRIM ADHESIVE TAPES	Necessary	192.00 FS	*153.20 FS
12	1		*WHEEL HOUSING LINER-LH	Not Necessary	256.00 FS	*- FS
13	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	82.00 FS	*- FS
14	1		*REAR ALUMINIUM RIM-LH	Serviceable	943.00 FS	*- FS
15	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
16	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
17	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
18	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
19	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
20	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 9,262.00 3,477.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.CHECK FUNCTION AND RENEW IF NECESSARY	New	280.00	0.00
3	TO RENEW LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	300.00	300.00
4	TO INSTALL 1/4 GLASS SOLAR FILM	New	400.00	200.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
6	TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENT TRIMS.DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
7	TO DISMANTLE REAR BUMPER,REAR LID,LHS SILL PANEL TRIM AND LHS REAR DOOR.CUT OUT AND WELD LHS REAR FENDER.TO RENEW LHS REAR DOOR.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	8,000.00	3,000.00
8	TO RESPRAY LHS REAR DOOR,DOOR HANDLE,LHS REAR FENDER,LHS SILL PANEL,DOOR ENTRANCES,ROOF CHANNEL,DRAIN PANEL AND END PANELLING.TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	5,400.00	2,475.00
9	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			18,012.00	9,327.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >