

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 03 Jan 2020)
 Parts: N/A TOYOTA DYNA 150 MANUAL 3SEATER 3.0 D (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Hua Hong Pte Ltd/GBD8668B/03/01/2020 16:51
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER / <i>DR</i>	0.00	0.00	*295.00 F
2	1		*FRONT REINFORCEMENT / <i>DD</i>	0.00	0.00	*250.00 F
3	1		*FRONT GRILLE / <i>DR</i>	0.00	0.00	*145.00 F
4	1		*FRONT GRILLE MOULDING (<i>DR</i>) / <i>CUT</i>	0.00	0.00	*18.00 F
5	10		*FRONT GRILLE CLIP / <i>MC</i>	0.00	0.00	*15.00 F
6	1		*EMBLEM / <i>CUT</i>	0.00	0.00	*32.00 F
7	1		*FRONT LOGO (DYNA) / <i>MC</i>	0.00	0.00	*28.00 F
8	1		*FRONT UPPER WIPER PANEL / <i>DD</i>	0.00	0.00	*120.00 F
9	1		*FRONT PANEL GARNISH (CENTER) (<i>DR</i>) / <i>CUT</i>	0.00	0.00	*90.00 F
10	2		*FRONT PANEL GARNISH (LH/RH) (<i>DR</i>) ?	0.00	0.00	*90.00 F
11	1		*FRONT PANEL / <i>DD</i>	0.00	0.00	*330.00 F
12	2		*FRONT CORNER PANEL (LH/RH) LOWER (<i>DR</i>) / <i>DD</i>	0.00	0.00	*136.00 F
13	2		*FRONT CORNER PANEL (LH/RH) UPPER X	0.00	0.00	*90.00 F
14	2		*FRONT HEADLAMP (LH/RH) / <i>DR</i>	0.00	0.00	*700.00 F
15	1		*FRONT DOOR (RH) / <i>DD</i>	0.00	0.00	*535.00 F
16	1		*FRONT DOOR CHECKER (RH) X	0.00	0.00	*50.00 F
17	2		*FRONT DOOR HINGE (RH) (UPPER/LOWER) X	0.00	0.00	*70.00 F
18	1		*FRONT DOOR LOCK (RH) X	0.00	0.00	*110.00 F
19	1		*FRONT DOOR STEP (RH) / <i>DR</i>	0.00	0.00	*90.00 F
20	1		*BLOWER MOTOR ?	0.00	0.00	*980.00 F
21	1		*HEATER UNIT ?	0.00	0.00	*1,100.00 F
22	1		*FRONT WINDSCREEN / <i>DR</i>	0.00	0.00	*580.00 F
23	1		*FRONT WINDSCREEN MOULDING / <i>CUT</i>	0.00	0.00	*135.00 F
24	1		*WIPER ARM COVER (RH) / <i>MC</i>	0.00	0.00	*8.00 F
25	1		*FRONT OUTER PILLAR (RH) X <i>R</i> / <i>DD</i>	0.00	0.00	*220.00 F
26	1		*FRONT LOWER PILLAR (RH) X <i>R</i> / <i>DD</i>	0.00	0.00	*165.00 F
27	1		*FRONT INNER PILLAR (RH) X <i>R</i> / <i>DD</i>	0.00	0.00	*220.00 F
28	1		*METER ?	0.00	0.00	*1,550.00 F
29	1		*DASHBOARD REINFORCEMENT SHAFT ?	0.00	0.00	*980.00 F

F=Franchise part

Sub Total (S\$) 9,132.00
 + Margin on L,N Items 15.00% (S\$) 1,369.80

Total Parts (S\$) 10,501.80

Hua Hong Pte Ltd/GBD8668B/03/01/2020 16:51. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	COMPANY DOOR STICKER ✓ <i>NYC</i>	25.00
2	1	FRONT NUMBER PLATE ✓ <i>DT</i>	35.00
3	1	SEALANT X <i>4</i>	40.00
Sub Total (S\$)			100.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO DISMANTLE, CUT & WELD FRONT PANEL, FRONT RH LOWER PILLAR, CHANGE FRONT BUMPER, FRONT LH/RH CORNER PANEL, FRONT LH/RH HEADLAMP, FRONT RH DOOR, FRONT REINFORCEMENT, KNOCKING & PULL STRAIGHT FRONT RH FLOOR PANEL AND ALL AREA AFFECTED BY ACCIDENT	New	1,400.00 <i>1000</i>
2	TO PERFORM WIRE CHECKING	New	20.00 ✓
3	TO DISMANTLE & REFIT FRONT WINDSCREEN	New	120.00 ✓
4	TO DISMANTLE & REFIT DASHBOARD	New	150.00 ✓
5	TO DISMANTLE & REFIT HEATER ASSY, BLOWER MOTOR ASSY AND TOP UP AIRCON GAS	New	200.00 <i>100</i>
6	TO SPRAY FRONT BUMPER, FRONT GRILLE, FRONT PANEL, FRONT LH/RH CORNER PANEL, FRONT WIPER PANEL, FRONT RH DOOR PILLAR, FRONT RH DOOR AND FRONT RH FLOOR PANEL	New	1,200.00 <i>900</i>
Gross Labour Cost (S\$)			3,090.00

Hua Hong Pte Ltd/GBD8668B/03/01/2020 16:51. Not valid without Reference section.
Generated using Merimen e-Claims IEAS
< END OF ESTIMATES >

*Steve (LKK) OD - Not Author (Ref)
EXPRS - \$600
6/1/20, 2-15pm
10 cks
L/S
Ry AL SJ*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: