

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20000242/AEA3Q2
Date: 20/11/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800150255
Claimant Vehicle No :	SLU5118J	Insured Vehicle No :	SFS9878D
Date of Loss:	30/12/2019	Nature of Claim:	TP
		Claim No:	7364592732SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU5118J	Engine No:	2NRX237145
Make & Model:	TOYOTA SIENNA, 1.5 CVT ELEGANCE (A)	Chassis No:	MHFZ28H3100046701
Reg. Date:	05/12/2017 (Man. Year: 2017)	Odometer:	86367 km
Colour:	Bronze		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/50R16	Rear Tyre Size:	195/50R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,325.37	1,460.40	7,864.97	84.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,730.00	1,580.00	2,150.00	57.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,055.37	3,040.40	10,014.97	76.71
Approved Total (Overridden) (S\$)		2,000.00		

Nett Amount (S\$)	13,055.37	2,000.00	11,055.37	84.68
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		30.00		
Nett Liability (S\$)		2,630.00		

INSPECTION

Date of Assignment: 03/01/2020

Date Inspected: 03/01/2020

Estimated Period of Repair: 4.0 days

Inspected At:

Ace Autolution Pte Ltd (KAKI BUKIT)
 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre
 Singapore 417807

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT SIDE MIRROR COVER LH	Cracked	81.00 FL	*81.00 FL
2	1		*FRONT SIDE MIRROR MOTOR LH ASSY	Damaged	635.00 FL	*635.00 FL
3	1		*FRONT DOOR LH	Repair	1,280.00 FL	*- FL
4	1		*FRONT DOOR INNER TRIM BOARD ASSY LH	Not Necessary	730.00 FL	*- FL
5	1		*FRONT DOOR FRAME GARNISH LH	Not Necessary	125.00 FL	*- FL
6	1		*FRONT DOOR HINGE (UPPER) LH	Not Necessary	70.00 FL	*- FL
7	1		*FRONT DOOR HINGE (LOWER) LH	Not Necessary	70.00 FL	*- FL
8	1		*FRONT DOOR HANDLE LH	Not Necessary	250.00 FL	*- FL
9	1		*FRONT DOOR LOCK	Not Necessary	350.00 FL	*- FL
10	1		*REAR DOOR LH	Repair	1,250.00 FL	*- FL
11	1		*REAR DOOR INNER TRIM BOARD ASSY RH	Not Necessary	680.00 FL	*- FL
12	1		*REAR DOOR FRAME GARNISH RH	Not Necessary	80.00 FL	*- FL
13	1		*REAR POWER SLIDE DOOR SENSOR ASSY RH	Not Necessary	400.00 FL	*- FL
14	1		*REAR SLIDE DOOR OUTSIDE HANDLE RH	Not Necessary	250.00 FL	*- FL
15	1		*REAR SLIDE DOOR LOCK ASSY	Not Necessary	550.00 FL	*- FL
16	1		*REAR DOOR CONTROL SWITCH	Not Necessary	110.00 FL	*- FL
17	1		*REAR SLIDE DOOR PROTECT PLATE	Not Necessary	40.00 FL	*- FL
18	1		*REAR DOOR HINGE ASSY CENTRE RH	Not Necessary	155.00 FL	*- FL
19	1		*REAR QUARTER PANEL RH	Not Necessary	780.00 FL	*- FL
20	1		*REAR FENDER LH	Repair	1,151.00 FL	*- FL
21	1		*REAR FENDER INNER SHIELD LH	Not Necessary	269.50 FL	*- FL
22	1		*REAR BUMPER	Deformed	1,355.20 FL	*495.00 FL
23	1		*REAR BUMPER SIDE GARNISH RH	Cut	160.80 FL	*160.80 FL
24	1		*REAR BUMPER SIDE RETAINER LH & RH	N/S Necessary	170.80 FL	*85.40 FL
25	1		*REAR TAILLAMP LH	Cut	657.20 FL	*450.00 FL
26	1		*REAR TAILLAMP PANEL LH	Not Necessary	250.00 FL	*- FL
27	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
28	1		*REAR BODY SEALANT	Not Necessary	100.00 FS	*- FS
29	1		*SET REAR DOOR INNER TRIM BOARD CLIPS	Not Necessary	80.00 FS	*- FS
30	1		*REAR FENDER SELANT	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,300.50	1,937.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,975.13	476.80
Total Parts (\$\$)	9,325.37	1,460.40

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,600.00	500.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED	New	1,200.00	1,000.00
3	TO REMOVE ,REFIX WIRING SYSTEM AT ACCIDENT DAMAGE AREAS AND CHECK FOR PROPER FUNCTION	New	150.00	30.00
4	TO REMOVE REAR BOOTLID MECHANISM	New	120.00	0.00
5	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	150.00	50.00
6	CAVITY TREATMENT ON NEW PARTS	New	120.00	0.00
7	TO REMOVE AND REFIX FENDER UPPER GLASS	New	120.00	0.00
8	TO REMOVE AND REFIX PASSENGER SEAT	New	150.00	0.00
9	TO CONDUCT WATER SEEPAGE TEST	New	120.00	0.00
			Gross Labour Cost (\$\$)	3,730.00
				1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >