

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20000246/APA3Q2

**Date:** 19/10/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SKB8568K	<b>Insured Vehicle No :</b>	SHA7592L
Date of Loss: 30/12/2019	Nature of Claim: TP	Claim No: MCT19120771

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB8568K	Engine No:	2AZF438565
Make & Model:	TOYOTA ESTIMA, 2.4 Aeras G (A)	Chassis No:	ACR507090896
Reg. Date:	05/07/2010 (Man. Year: 2010)	Odometer:	214428 km
Colour:	Black		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,657.45	6,498.39	3,159.06	32.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,430.00	1,640.00	790.00	32.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,087.45</b>	<b>8,138.39</b>	<b>3,949.06</b>	<b>32.67</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,500.00</b>		
<b>(S\$)</b>	12,087.45	6,500.00	5,587.45	46.23
<b>+ GST 7.00/7.00% (S\$)</b>	846.12	455.00	391.12	46.23
<b>Nett Amount (S\$)</b>	<b>12,933.57</b>	<b>6,955.00</b>	<b>5,978.57</b>	<b>46.23</b>
<b>+ Car Rental (7.0 x S\$100.00/day) (S\$)</b>		700.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>+ Other Costs (S\$)</b>		100.00		
<b>Nett Liability (S\$)</b>		<b>7,762.45</b>		

### INSPECTION

Date of Assignment: 03/01/2020

Date Inspected: 03/01/2020 Inspected At:

N-51 Automotive Pte Ltd (kaki Bukit  
Autohub) (HQ)  
KAKI BUKIT AUTOHUB 2 KAKI  
BVUKIT AVE 2 #01-18  
Singapore 417921

Estimated Period of Repair: 6.0 days

---

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2020)
<b>Parts:</b>	M1-MPV	TOYOTA ESTIMA 2.4 Aeras G (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKB8568K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AIR CLEANER RESONATOR	Cracked	185.00 FL	*185.00 FL
2	1		*FRONT BUMPER	Deformed	1,731.35 FL	*866.00 FL
3	1		*FRONT BUMPER SIDE RETAINER L/R	N/S Damaged	345.00 FL	*116.00 FL
4	1		*FRONT LH BUMPER FOGLAMP	Cracked	371.70 FL	*371.70 FL
5	1		*FRONT LH BUMPER FOGLAMP BRACKET	Cracked	172.45 FL	*172.45 FL
6	1		*FRONT LH BUMPER FOGLAMP COVER	Not Necessary	172.50 FL	*- FL
7	1		*FRONT LH DOOR	Dented	1,712.40 FL	*1,481.00 FL
8	1		*FRONT LH DOOR FRAME UPPER STICKER (INNER)	Necessary	136.42 FS	*60.00 FS
9	1		*FRONT LH DOOR FRAME UPPER STICKER (OUTER)	Necessary	129.37 FS	*60.00 FS
10	1		*FRONT LH DOOR FRAME VERTICAL STICKER (INNER)	Necessary	133.27 FS	*60.00 FS
11	1		*FRONT LH DOOR FRAME VERTICAL STICKER (OUTER)	Necessary	133.27 FS	*60.00 FS
12	1		*FRONT LH DOOR INNER PLASTIC SEAL COVER	Not Necessary	72.10 FL	*- FL
13	1		*FRONT LH DOOR PROTECTOR	Deformed	978.10 FL	*688.00 FL
14	1		*FRONT LH FENDER	Distorted	981.70 FL	*782.00 FL
15	1		*FRONT LH FENDER INNER SEAL COVER	Not Necessary	174.45 FL	*- FL
16	1		*FRONT LH FENDER INNER SHIELD	Deformed	371.70 FL	*371.70 FL
17	1		*FRONT LH FENDER PROTECTOR	Cracked	374.50 FL	*184.00 FL
18	1		*FRONT LH FENDER SIDE BRACKET	Bent	171.50 FL	*95.00 FL
19	1		*FRONT LH HEADLAMP (HID)	Cracked	2,712.45 FL	*2,190.00 FL
20	1		*LH SLIDING DOOR PROTECTOR	Deformed	972.50 FL	*695.00 FL
21	1		*LH SLIDING DOOR RUBBER SEAL (FRONT)	Not Necessary	174.10 FL	*- FL
22	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
23	1		*SET FRONT LH DOOR INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
24	1		*SET FRONT LH DOOR PROTECTOR CLIPS	Necessary	80.00 FS	*20.00 FS
25	1		*SET FRONT LH FENDER INNER SEAL COVER CLIPS	Not Necessary	20.00 FS	*- FS
26	1		*SET FRONT LH FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*30.00 FS
27	1		*SET FRONT LH FENDER PROTECTOR CLIPS	Necessary	40.00 FS	*10.00 FS
28	1		*SET LH SLIDING DOOR PROTECTOR CLIPS	Necessary	80.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>12,575.83</b>	<b>8,547.85</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	<b>2,918.38</b>	<b>2,049.46</b>
<b>Total Parts (S\$)</b>	<b>9,657.45</b>	<b>6,498.39</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING (TO FR)	New	50.00	30.00
2	TO TRANSFER DOOR GLASS ,REGULATOR GEAR ,MOTOR ,RAILING ,CHANNEL ,TRIM BOARD ,MECHANISM LOCK AND HANDLE	New	100.00	80.00
3	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	800.00
4	TO PROVIDE LABOUR ,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	700.00
5	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	30.00
<b>Gross Labour Cost (\$)</b>			<b>2,430.00</b>	<b>1,640.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >