

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20000247/UPS3Q2

Date: 07/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994322

Claimant
Vehicle No : SJP7805X **Insured Vehicle No :** SME710D

Date of Loss: 24/12/2019 Nature of Claim: TP Claim No: 4599928420SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP7805X	Engine No:	G4KD8H501050
Make & Model:	KIA CERATO FORTE, 1.6 (A)	Chassis No:	KNAFH222395024362
Reg. Date:	09/04/2009 (Man. Year: 2008)	Odometer:	176050 km
Colour:	Gold		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,283.40	6,025.54	4,257.86	41.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,550.00	2,760.00	790.00	22.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,833.40	8,785.54	5,047.86	36.49
Approved Total (Overridden) (\$\$)		7,000.00		
Nett Amount (\$\$)	13,833.40	7,000.00	6,833.40	49.40
+ Loss of Use (10.0 x S\$120.00/day) (\$\$)		1,200.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		8,207.45		

INSPECTION

Date of Assignment: 06/01/2020

Date Inspected: 06/01/2020 Inspected At:

LIU'S BROTHER AUTO WORKSHOP (HQ)

1 Kaki Bukit Ave 6 #01-01, Auto

Bay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent / Buckled	793.80 F	*793.80 FL
2	1		*REAR BOOTLID INNER LOCK	Twisted	91.60 F	*91.60 FL
3	1		*REAR BOOTLID WEATHERSTRIP	Twisted	128.50 F	*128.50 FL
4	1		*REAR BOOTLID INNER TRIM	Deformed / Torn	211.20 F	*211.20 FL
5	1		*SET REAR BOOTLID INNER TRIM	Not Necessary	40.00 F	*- FL
6	1		*REAR BOOTLID KIA MOTIF	Necessary	42.50 F	*42.50 FL
7	1		*REAR BOOTLID 2.0 EMBLEM	Necessary	45.00 F	*45.00 FL
8	1		*REAR BOOTLID CERATO EMBLEM	Necessary	43.20 F	*43.20 FL
9	1		*REAR BOOTLID FORTE EMBLEM	Necessary	40.80 F	*40.80 FL
10	1		*REAR BUMPER	Deformed	658.00 F	*658.00 FL
11	1		*REAR BUMPER LOWER GARNISH	Deformed / Cracked	198.50 F	*198.50 FL
12	1		*REAR BUMPER SPONGE	Torn	145.50 F	*145.50 FL
13	1		*REAR BUMPER REINFORCEMENT	Cracked	356.00 F	*356.00 FL
14	1		*REAR BUMPER REINFORCEMENT BRACKET	N/S Bent	130.00 F	*65.00 FL
15	2		*REAR TAIL LAMP	Serviceable	736.00 F	*- FL
16	1		*REAR END PANEL	Badly Dented	598.50 F	*598.50 FL
17	1		*REAR END PANEL TOP GARNISH	Twisted	152.50 F	*152.50 FL
18	1		*REAR FENDER INNER TRIM	Deformed / Torn	211.30 F	*211.30 FL
19	1		*REAR EXHAUST	Repair	762.00 F	*- FL
20	1		*FRONT BUMPER	Deformed / Torn	562.00 F	*562.00 FL
21	1		*FRONT BUMPER SPONGE	Torn	123.60 F	*123.60 FL
22	1		*FRONT BUMPER REINFORCEMENT	Bent	396.50 F	*396.50 FL
23	1		*FRONT BUMPER LOWER GARNISH	Not Necessary	450.00 F	*- FL
24	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
25	1		*FRONT BUMPER LICENCE HOLDER	Torn	66.80 F	*66.80 FL
26	1		*FRONT SUPPORT PANEL	Serviceable	671.00 F	*- FL
27	2		*FRONT HEAD LAMP	Cracked	1,092.00 F	*1,092.00 FL
28	1		*FRONT GRILLE	Cracked	285.30 F	*285.30 FL
29	1		*FRONT GRILLE KIA MOTIF	Necessary	42.50 F	*42.50 FL
30	1		*FRONT BONNET	Repair	778.80 F	*- FL
31	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
32	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
33	1		*FRONT NUMBER PLATE	Necessary	50.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 10,283.40 6,665.60
- List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 640.06

Total Parts (\$\$) 10,283.40 6,025.54

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	80.00	30.00
2	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR	New	50.00	50.00
3	REMOVE AND REFIX REAR BOOTLID MECHANISM	New	80.00	60.00
4	REMOVE & REFIX CUSHION UPHOLSTERY TO FACILITATE REPAIR	New	80.00	80.00
5	REMOVE AND REPLACE REAR EXHAUST PIPE SYSTEM TO FACILITATE REPAIRS	New	80.00	0.00
6	TO REMOVE & REFIX AIR CON ,REFILL AIR CON GAS & TEST FOR LEAKAGES	New	100.00	0.00
7	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	60.00
8	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	1,200.00	1,000.00
9	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	1,800.00	1,480.00
Gross Labour Cost (\$)			3,550.00	2,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >