

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000259/APS3Q2

Date: 06/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SMM5359K **Insured Vehicle No :** SJB5072E

Date of Loss: 02/01/2020 Nature of Claim: TP Claim No: 8977586002SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMM5359K**

Make & Model: HONDA SHUTTLE, 1.5 G CVT (A) Engine No: L15B6002218

Reg. Date: 03/07/2019 (Man. Year: 2019) Chassis No: GK82001867

Colour: Silver Odometer: 7662 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R16 Rear Tyre Size: 205/50 R16

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,071.60	2,366.88	3,704.72	61.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	1,250.00	2,130.00	63.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,451.60	3,616.88	5,834.72	61.73
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	9,451.60	2,800.00	6,651.60	70.38
+ GST 7.00/7.00% (S\$)	661.61	196.00	465.61	70.38
Nett Amount (S\$)	10,113.21	2,996.00	7,117.21	70.38
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,403.45		
Global Sum Settlement (S\$)		3,400.00		

INSPECTION

Date of Assignment: 03/01/2020

Date Inspected: 14/01/2020 Inspected At:

Vision Autowork Pte Ltd (HQ)
 8 KAKI BUKIT AVE 4,, #08-09
 PREMIER @ KAKI BUKIT
 Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	1,150.60 FL	*1,150.60 FL
2	1		*REAR BUMPER REFLECTOR LH	Cracked	43.80 FL	*43.80 FL
3	1		*REAR BUMPER REFLECTOR GARNISH LH	Cracked	45.10 FL	*45.10 FL
4	2		*REAR BUMPER SIDE INNER GARNISH	Torn	196.80 FL	*196.80 FL
5	2		*REAR BUMPER SIDE RETAINER LH	Damaged	53.00 FL	*26.50 FL
6	2		*REAR BUMPER SIDE BRACKET	Not Necessary	48.00 FL	*- FL
7	2		*REAR BUMPER SPONGE LH	Cracked	94.00 FL	*47.00 FL
8	1		*TAIL GATE EMBLEM SHUTTLE	Necessary	55.70 FL	*55.70 FL
9	1		*TAIL GATE WEATHERSTRIP	Not Necessary	168.10 FL	*- FL
10	1		*TAIL LAMP LH	Cracked	520.50 FL	*520.50 FL
11	1		*TAIL LAMP LOWER PANEL LH	Repair	235.20 FL	*- FL
12	1		*REAR FENDER LH	Repair	1,610.90 FL	*- FL
13	1		*REAR FENDER COWLING LH	Not Necessary	147.50 FL	*- FL
14	1		*REAR FENDER AIR VENT LH	Not Necessary	64.80 FL	*- FL
15	1		*REAR QUARTER GLASS C/W MOULDING LH	Not Necessary	720.40 FL	*- FL
16	1		*REAR END PANEL	Dented	685.10 FL	*685.10 FL
17	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
18	1		*SET REAR BUMPER REFLECTOR GARNISH CLIP LH	Necessary	30.00 FS	*10.00 FS
19	1		*SET TAIL GATE OUTER GARNISH CLIP	Not Necessary	40.00 FS	*- FS
20	1		*TAIL GATE LAMP LOWER PANEL LH	Not Necessary	80.00 FS	*- FS
21	1		*SET TAIL LAMP CLIP	Necessary	40.00 FS	*10.00 FS
22	1		*TAIL LAMP LOWER PANEL SEALANT LH	Not Necessary	60.00 FS	*- FS
23	1		*REAR FENDER SEALANT LH	Not Necessary	150.00 FS	*- FS
24	1		*SET REAR FENDER INNER COWLING	Necessary	80.00 FS	*30.00 FS
25	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
26	1		*REAR QUARTER GLASS SEALANT LH	Not Necessary	60.00 FS	*- FS
27	1		*REAR QUARTER GLASS INNER SEAL LH	Not Necessary	40.00 FS	*- FS
28	1		*REAR QUARTER GLASS SOLAR FILM LH	Not Necessary	250.00 FS	*- FS
29	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
30	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	40.00 FS	*10.00 FS
31	1		*REVERSE SENSOR	Not Necessary	220.00 FS	*- FS
					Sub Total (\$\$)	7,239.50 2,921.10
					- List Item Discount on L Items 20.00/20.00% (\$\$)	1,167.90 554.22
					Total Parts (\$\$)	6,071.60 2,366.88

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVAL AND REPALCING PARTS	New	1,400.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	600.00
3	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
4	TRANSFER TAILGATE MECHANISM	New	80.00	0.00
5	REMOVE AND REFIX REAR FENDER GLASS LH	New	120.00	0.00
6	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	300.00	0.00
Gross Labour Cost (\$\$)			3,380.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >