



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1912-157
DATE : 26-Dec-2019
POLICY NO. : FWD PNPV2019-00003262
VEHICLE REG. NO. : SLX789P
VEHICLE MAKE : HONDA SHUTTLE HYBRID 1.5 A

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Front Bumper / re	1	\$ 1,200.00	\$ 1,200.00
2	Front Bumper Clips / MCL	10	\$ 5.00	\$ 50.00
3	Front Bumper Retainer LH / re	1	\$ 30.00	\$ 30.00
4	Front Bumper Retainer RH	1	\$ 30.00	\$ 30.00
5	Front Bumper Tow Eye Cover / OPA	1	\$ 20.00	\$ 20.00
6	Front Upper Grille Beam Bracket (Center) No. 4 X NN	1	\$ 60.00	\$ 60.00
7	Front Upper Grille (Center) / SCR	1	\$ 400.00	\$ 400.00
8	Front Upper Grille Chrome / SCR	1	\$ 380.00	\$ 380.00
9	Front Upper Grille Clips / MCL	6	\$ 5.00	\$ 30.00
10	Front Honda H Emblem with base / SCR	1	\$ 30.00	\$ 30.00
11	Front Head Lamp RH / SCR	1	\$ 2,200.00	\$ 2,200.00
12	Front Head Lamp LH X NN	1	\$ 2,200.00	\$ 2,200.00
Total Spare Parts				\$ 6,630.00
SPECIAL NETT				
13	Front License Plate with Frame / SCR	1	\$ 40.00	\$ 40.00
Total Special Nett				\$ 40.00
LABOUR				
14	Spray Painting Front Bumper, Bonnet and Inner Panel	1	\$ 600.00	\$ 600.00
15	Replace Front Affected including Fitting, Cut, Weld and Re-align	1	\$ 600.00	\$ 600.00
16	Remove and Refit Front Bumper Parking Sensor	1	\$ 100.00	\$ 100.00
17	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 1,330.00
Amount Before Excess				\$ 8,000.00
Add GST @ 7%				560.00
Total Amount Payable				\$ 8,560.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3 Days.

lumpsum repair.

After repair photos.

Guo Qiang - 82880282

Page 1 of 1 Guo Qiang @ lkk auto. com

13/01/2020.

1050

15

15

15

20

23.4

4173.4

20%: 3338.72

400

200

40

20

660

4038.72

20%: 3200

0. C

1,050. +

50. +

15. +

15. +

20. +

400. +

380. +

20. +

23.4 +

2,200. =

4,173.4 *

4,173.4 x

80. %

3,338.72 *

40. +

=

40. *

L/s - \$3200

400. +

200. +

40. +

20. =

660. *

3,338.72 +

40. +

660. =

4,038.72 *

4,038.72 x

80. %

3,230.976 *

0. C