

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20000262/EGS3Q2

Date: 19/10/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : FBN1533A	Insured Vehicle No :	SHA3774E
Date of Loss: 23/12/2019	Nature of Claim:	TP Claim No: MCT19120572

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN1533A	Engine No:	ZDM937W4C006656
Make & Model:	DUCATI SUPERSPORT S, 937cc	Chassis No:	ZDMVA00AAJB005944
Reg. Date:	26/07/2018 (Man. Year: 2018)	Odometer:	2947 km
Colour:	Red		
Engine Capacity:	937 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70Z R17	Rear Tyre Size:	190/55Z R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,474.10	1,474.10	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,000.00	800.00	44.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,274.10	2,474.10	800.00	24.43
+ GST 7.00/7.00% (S\$)	229.19	173.19	56.00	24.43
Nett Amount (S\$)	3,503.29	2,647.29	856.00	24.43
+ Loss of Use (1.0 x S\$30.00/day) (S\$)		30.00		
		Nett Liability (S\$)	2,677.29	

INSPECTION

Date of Assignment:	15/01/2020	
Date Inspected:	15/01/2020 Inspected At:	Wearnes Automotive Pte Ltd (Leng Kee) 28 Leng Kee Road Singapore 159105
Estimated Period of Repair:	1.0 days	

Adjuster: CHEN TSUE YEE

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Jul 2020)	
Parts:	N/A	DUCATI SUPERSPORT S 937cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN1533A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LEFT LOWER FAIR	Cut	616.70 FS	*616.70 FS
2	1		*RED COMP RH SI	Cut	857.40 FS	*857.40 FS
Total Parts (S\$)					1,474.10	1,474.10

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE DAMAGED PARTS	New	1,800.00	1,000.00
			Gross Labour Cost (\$)	1,800.00
				1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >