

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20000268/R1GS3Q2

**Date:** 15/05/2020

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MCV0001580_01
<b>Claimant Vehicle No :</b>	XD9303L	<b>Insured Vehicle No :</b>	YP4075C
Date of Loss:	28/12/2019	Nature of Claim:	TP
		Claim No:	MCV2020D0000066

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XD9303L	Engine No:	11550601
Make & Model:	VOLVO FEE300, 1.7 D 64R RSS (M)	Chassis No:	YV2VH70D5EB685978
Reg. Date:	15/07/2014 (Man. Year: 2014)	Odometer:	202022 km
Colour:	White		
Engine Capacity:	7146 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5 (D)
Front Left Side:	Hankook 8 mm	Rear Left Side:	Hankook 8/8 mm
Front Right Side:	Hankook 8 mm	Rear Right Side:	Hankook 8/8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,500.00	11,400.00	2,100.00	15.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>13,500.00</b>	<b>11,400.00</b>	<b>2,100.00</b>	<b>15.56</b>
<b>+ Loss of Use (14.0 x S\$150.00/day) (S\$)</b>		2,100.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>13,507.45</b>		

### INSPECTION

Date of Assignment:	03/01/2020		
Date Inspected:	06/01/2020	Inspected At:	Zenith Engineering Pte Ltd (HQ) NO 34 JOO KOON CIRCLE Singapore 629060
Estimated Period of Repair:	14.0 days		

**Adjuster:** MOHD RASUL

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 23 Mar 2020)

**Parts:** N/A VOLVO FEE300 1.7 D 64R RSS (M) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for XD9303L)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	SUPPLY LABOUR AND MATERIAL FOR THE REPAIR OF RCV XD9303L AS FOLLOWS ,REMOVING OF DAMAGED BINLIFTER ASSY ,FORMING & WELDING ,FABRICATION OF SUB ASSEMBLY,RETROFITTING NEW BIN LIFTER ONTO THE RCV AND TESTING AND PAINTING OF BINLIFTER OF AFFECTED AREA OF REPAIR	New	13,500.00	11,400.00
<b>Gross Labour Cost (\$)</b>			<b>13,500.00</b>	<b>11,400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >