

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20000272/KBS3Q2

**Date:** 03/08/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700011969-02

**Claimant**  
**Vehicle No :** SLM381P **Insured Vehicle No :** SKC5599K

Date of Loss: 16/12/2019 Nature of Claim: TP Claim No: 9743190100SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLM381P</b>		
Make & Model:	TOYOTA AQUA HYBRID, 1.5 E S CVT (A)	Engine No:	1NZ7923757
Reg. Date:	20/03/2017 (Man. Year: 2016)	Chassis No:	NHP102538198
Colour:	White	Odometer:	61810 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	KAPSEN 9 mm	Rear Left Side:	KAPSEN 9 mm
Front Right Side:	KAPSEN 9 mm	Rear Right Side:	KAPSEN 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	489.23	0.00	489.23	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	580.00	200.00	380.00	65.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>1,069.23</b>	<b>200.00</b>	<b>869.23</b>	<b>81.29</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	74.85	14.00	60.85	81.30
<b>Nett Amount (\$\$)</b>	<b>1,144.08</b>	<b>214.00</b>	<b>930.08</b>	<b>81.30</b>
<b>+ Loss of Use (1.0 x S\$60.00/day) (\$\$)</b>		60.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>276.00</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>270.00</b>		

### INSPECTION

Date of Assignment: 03/01/2020

Date Inspected: 03/01/2020 Inspected At: Optima Werkz Pte Ltd (HQ)  
6 Kung Chong Road  
Singapore 159143

Estimated Period of Repair: 1.0 days

**Adjuster:** KENNETH KONG

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	608.31 FL	*- FL
2	8		*REAR BUMPER CLIPS	Not Necessary	44.00 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT (NPA)	Repair	0.00 FL	*- FL
					<b>Sub Total (\$)</b>	<b>652.31 0.00</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	<b>163.08 0.00</b>
					<b>Total Parts (\$)</b>	<b>489.23 0.00</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE,REPLACE ,REPAIR ,READJUST REAR ACCIDENT AREAS & ETC	New	250.00	0.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER & ETC	New	250.00	200.00
3	LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC	New	80.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>580.00</b>	<b>200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >