



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

NTUC INCOME INSURANCE CO-OPERATIVE LTD INV No. AC2004043
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSE INV Date 20/05/2020
SINGAPORE 189556 Reference CS/INC20000295/Gyd3n2
ATTN: JEFF Code INC



PROFESSIONAL SERVICE FEE

Vehicle No. SLJ 8914R
Insured Veh. GBG 772U
Claim No. MT/1078653-001
Policy No.
Accident Date 27/12/2019
Inspection Date 16/01/2020

Description	Total
Damage Assessment	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC20000295/Gyd3n2
73 BRAS BASAH ROAD Date: 20-05-2020
#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556
ATTN: JEFF Code: INC



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 772U	Veh. Inspected	SLJ 8914R
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1078653-001	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	06/01/2020

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3 1.5	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JM6BN22A8H0129108	Colour	GREY
Odometer	142442 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	LING LONG	6 mm
L/H Front Tyre	205/60 R16	LING LONG	6 mm
R/H Rear Tyre	205/60 R16	LING LONG	6 mm
L/H Rear Tyre	205/60 R16	LING LONG	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/12/2019	Inspect Date / Time	16/01/2020 (03:30 PM)
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 8914R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOT LID	NOT NECESSARY	1,258.50	-
1	BOOT LID LOCK	NOT NECESSARY	260.00	-
1	BOOT LID BOTTOM LOCK STRIKER	NOT NECESSARY	131.00	-
1	BOOT LID "MAZDA" LOGO	NOT NECESSARY	48.00	-
1	BOOT "MAZDA 3" EMBLEM	NOT NECESSARY	39.00	-
1	BOOT LID "SKYACTIV" EMBLEM	NOT NECESSARY	36.00	-
1	BOOT LID WEATHERSTRIP	NOT NECESSARY	185.60	-
2	BOOT LID LAMP L+R @\$277.40	NOT NECESSARY	554.80	-
2	TAIL LAMP L+R @\$538.20	NOT NECESSARY	1,076.40	-
1	REAR BUMPER-UPPER	DEFORMED	1,098.70	998.00
1	REAR BUMPER-LOWER	NOT NECESSARY	346.20	-
2	REAR BUMPER REFLECTOR L+R @\$64.30	NOT NECESSARY	128.60	-
1	REAR BUMPER TOW COVER	NOT NECESSARY	22.60	-
1	REAR BUMPER CENTER PROTECTOR LOWER	NOT NECESSARY	128.70	-
2	REAR BUMPER SIDE RETAINER L+R @\$36.10	NOT NECESSARY	72.20	-
2	REAR BUMPER BRACKET L+R @\$45.60	NOT NECESSARY	91.20	-
1	REAR BUMPER REINFORCEMENT	BENT	558.00	538.00
1	END PANEL	NOT NECESSARY	567.00	-
1	END PANEL TOP GARNISH	NOT NECESSARY	216.50	-
1	SPARE WHEEL PANEL	NOT NECESSARY	653.00	-
1	SPARE WHEEL PANEL TOP BOARD	NOT NECESSARY	285.70	-
	LESS 20% DISCOUNT		-1,551.54	-307.20
			6,206.16	1,228.80
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER REVERSE SENSOR (FACTORY ORIGINAL)(SN)	NOT NECESSARY	648.00	-
1	SET REAR BUMPER REVERSE SENSOR HOLDER (SN)	NOT NECESSARY	72.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	SET END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	60.00	-
1	END PANEL SEALANT (SN)	NOT NECESSARY	120.00	-
1	SPARE WHEEL PANEL SEALANT (SN)	NOT NECESSARY	180.00	-

Report Ref No. CS/INC20000295/Gyd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE AND FRAME (SN)	NOT NECESSARY	55.00	-
			1,195.00	30.00
	LABOUR			
	TO STRAIGHTEN AND PANEL BEAT REAR ACCIDENT AREA. BOOTLID AND GARNISH, BUMPER AND ALL OTHER AFFECTED PORTIONS.		1,000.00	200.00
	TO PUTTY SPRAY PAINT AND POLISH REAR ACCIDENT AREA. BOOTLID AND GARNISH, END PANEL AND ALL OTHER AFFECTED PORTIONS.		1,000.00	200.00
	CHECK WIRING AFTER REPAIR FOR PROPER FUNCTION.	NOT NECESSARY	80.00	-
	TO REMOVE AND REFIT REVERSE SENSORS.		80.00	40.00
	TO RUST PROOF AFFECTED AREAS.	NOT NECESSARY	160.00	-
			2,320.00	440.00
GRAND TOTAL			9,721.16	1,698.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,350.00

Report Ref No. CS/INC20000295/Gyd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLJ 8914R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLJ 8914R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLJ 8914R

RE-INSPECTION

