

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000316/ABA3Q2

Date: 12/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800141134

Claimant
Vehicle No : SGY3982G **Insured Vehicle No :** GR7327J

Date of Loss: 31/12/2019 Nature of Claim: TP Claim No: 3215553487SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGY3982G		
Make & Model:	CHEVROLET AVEO 4, 1.4 (A)	Engine No:	F14D3521044K
Reg. Date:	25/09/2007 (Man. Year: 2007)	Chassis No:	KL1SA69717H207747
Colour:	Black	Odometer:	290787 km
Engine Capacity:	1399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Linglong 6 mm	Rear Left Side:	Linglong 6 mm
Front Right Side:	Linglong 6 mm	Rear Right Side:	Linglong 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,616.80	3,660.60	5,956.20	61.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,860.00	1,600.00	2,260.00	58.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	13,476.80	5,260.60	8,216.20	60.97
Approved Total (Overridden) (\$)		1,500.00		
(S\$)	13,476.80	1,500.00	11,976.80	88.87
+ GST 7.00/7.00% (S\$)	943.38	105.00	838.38	88.87
Nett Amount (\$)	14,420.18	1,605.00	12,815.18	88.87
Global Sum Settlement (\$)		0.00		

INSPECTION

Date of Assignment: 03/01/2020

Date Inspected: 09/01/2020 Inspected At:

8 Kaki Bukit Ave 4 #08-46 Premier
Repairer: SK Automobile Pte Ltd (HQ)

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	1,159.00 FL	*1,159.00 FL
2	1		*BOOT LID EMBLEM AVEO	Necessary	49.00 FL	*49.00 FL
3	1		*BOOT LID EMBLEM CHEVROLET	Necessary	64.00 FL	*64.00 FL
4	1		*BOOT LID INNER LOCK	Not Necessary	242.00 FL	*- FL
5	2		*BOOT LID LOWER LOCK	Not Necessary	82.00 FL	*- FL
6	1		*BOOT LID WEATHERSTRIP	Cut	98.00 FL	*98.00 FL
7	2		*REAR FENDER INNER TRIM	Not Necessary	48.00 FL	*- FL
8	1		*REAR BUMPER	Deformed	1,415.00 FL	*1,415.00 FL
9	2		*REAR BUMPER BRACKET	Not Necessary	102.00 FL	*- FL
10	1		*REAR BUMPER SPONGE	Not Necessary	356.00 FL	*- FL
11	2		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	386.00 FL	*- FL
12	2		*REAR BUMPER SIDE RETAINER	Not Necessary	124.00 FL	*- FL
13	2		*TAILLAMP	Not Necessary	656.00 FL	*- FL
14	2		*REAR FENDER INNER TRIM	Not Necessary	1,388.00 FL	*- FL
15	1		*REAR END PANEL	Repair	641.00 FL	*- FL
16	1		*REAR END PANEL TOP GARNISH	Deformed	249.00 FL	*249.00 FL
17	1		*REAR SPARE TYRE BOLT	Not Necessary	49.00 FL	*- FL
18	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	569.00 FL	*- FL
19	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
20	8		*REAR BUMPER CLIPS	Necessary	52.00 FS	*30.00 FS
21	20		*REAR FENDER INNER TRIM CLIPS	Not Necessary	130.00 FS	*- FS
22	3		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	25.50 FS	*- FS
23	1		*REAR END PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
24	1		*REAR FLOOR PANEL INSULATOR SEAL	Not Necessary	280.00 FS	*- FS
25	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
26	1		*REAR BUMPER LIP	Deformed	1,800.00 FS	*700.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,384.50	3,964.00
- List Item Discount on L Items 10.00/10.00% (\$)	767.70	303.40
Total Parts (\$)	9,616.80	3,660.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,400.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	800.00
3	TUFF COAT	New	250.00	60.00
4	WIRING AND BULB CHECK	New	80.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	250.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	REAR CHASSIS ALIGNMENT	New	250.00	0.00
8	TRANSFER BOOT LID MECHANISM	New	80.00	0.00
9	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
10	REMOVE AND REFIX REAR EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (\$\$)			3,860.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >