

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20000336/DGA3N2

Date: 21/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SHA9980L	Insured Vehicle No :	SH7735A
Date of Loss: 29/12/2019	Nature of Claim: TP	Claim No: MCT19120694

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA9980L		
Make & Model:	HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)	Engine No:	D4FDEU441554
Reg. Date:	07/08/2014 (Man. Year: 2014)	Chassis No:	KMHLB41UMEU058030
Colour:	Yellow	Odometer:	651668 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,831.80	5,730.12	5,101.68	47.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,910.00	1,810.00	3,100.00	63.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,741.80	7,540.12	8,201.68	52.10
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	15,741.80	6,000.00	9,741.80	61.88
+ GST 7.00/7.00% (S\$)	1,101.93	420.00	681.93	61.89
Nett Amount (S\$)	16,843.73	6,420.00	10,423.73	61.88
+ Loss of Use (10.0 x S\$40.00/day) (S\$)		400.00		
+ Car Rental (10.0 x S\$110.67/day) (S\$)		1,106.70		
Nett Liability (S\$)		7,926.70		
Global Sum Settlement (S\$)		7,900.00		

INSPECTION

Date of Assignment: 03/01/2020

Date Inspected: 03/01/2020 Inspected At:

Chunni Motor Work Pte Ltd (HQ)
Blk 10 Ang Mo Kio Industrial Park 2A,
#03-19 AMK Autopoint
Singapore 568047

Estimated Period of Repair: 7.0 days

Adjuster: BRYAN TANI

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2020)
Parts:	143	HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA9980L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	553.00 FL	*- FL
2	10		*REAR BUMPER CLIP	Serviceable	22.00 FL	*- FL
3	1		*TAIL LAMP (RH)	Not Necessary	697.80 FL	*- FL
4	1		*REAR FENDER WITH HOUSING (RH)	Dented	4,736.80 FL	*2,020.00 FL
5	1		*REAR WINDSCREEN MOULDING	Necessary	28.30 FL	*28.30 FL
6	1		*REAR DOOR (RH)	Dented	2,201.10 FL	*2,201.10 FL
7	1		*ROCKER PANEL OUTER GARNISH (RH)	Repair	341.40 FL	*- FL
8	1		*REAR TYRE RIM (RH)	Not Necessary	325.30 FL	*- FL
9	1		*REAR WHEEL HUP-CAP (RH)	Cut	107.10 FL	*107.10 FL
10	1		*REAR WHEELBEARING ING & HUB	Damaged	362.00 FL	*362.00 FL
11	1		*REAR TRAILING ARM (RH)	Distorted	192.00 FL	*192.00 FL
12	1		*REAR ASSIST (RH)	Distorted	145.70 FL	*145.70 FL
13	1		*REAR SHOCK ABSORBER (RH)	Distorted	276.30 FL	*276.30 FL
14	1		*REAR SHOCK ABSORBER MOUNTING (RH)	Not Necessary	81.30 FL	*- FL
15	1		*REAR CROSSMEMBER	Not Necessary	1,021.50 FL	*- FL
16	1		*STABILIZER BAR	Not Necessary	199.60 FL	*- FL
17	1		*STABILIZER LINK	Not Necessary	85.90 FL	*- FL
18	1		*REAR UPPER ARM (RH)	Distorted	335.75 FL	*335.75 FL
19	1		*REAR LOWER ARM (RH)	Distorted	353.80 FL	*353.80 FL
20	1		*REAR KNUCKLE ARM (RH)	Distorted	545.60 FL	*545.60 FL
21	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
22	1		*REAR BUMPER RUBBER MAT	Not Necessary	50.00 FS	*- FS
23	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS
24	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
25	1		*REAR DOOR ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
26	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (RH)	Necessary	80.00 FS	*80.00 FS
27	1		*REAR TYRE (RH)	Not Necessary	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,354.25	7,043.65
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,522.45	1,313.53
Total Parts (\$\$)	10,831.80	5,730.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,800.00	600.00
2	SPRAY PAINTING CHARGE	New	1,250.00	600.00
3	WIRING CHARGE	New	50.00	0.00
4	TUFF KOTE	New	50.00	30.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE /REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
8	REMOVE/REFIX REVERSE SENSOR	New	120.00	0.00
9	TRANSFER OF DOOR	New	120.00	60.00
10	REMOVE/REFIX UNDERCARRIAGE (RR)	New	200.00	150.00
11	REAR WHEEL ALIGNMENT	New	120.00	60.00
12	RE-SET REAR ABS SYSTEM }	New	200.00	150.00
13	RE-SET REAR POWER WINDOW SYSTEM }	New	200.00	0.00
14	DIAGNOSTIC & RESETING TO ERASE FAULT CODE }	New	480.00	0.00
Gross Labour Cost (\$\$)			4,910.00	1,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >