

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 6524M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	CRACKED	1,980.00	1,840.00
2	FRONT BUMPER RETAINERS	N/S DISTORTED	110.00	55.00
2	FRONT BUMPER BRACKETS	TO REPAIR SEE LABOUR	140.00	-
1	FRONT BUMPER FOG LAMP ASSY LH	SERVICEABLE	480.00	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	690.00	-
1	FRONT BUMPER SENSOR	SERVICEABLE	420.00	-
1	HEAD LAMP LH	CUT	1,290.00	1,290.00
1	FRONT SUPPORT PANEL	SERVICEABLE	920.00	-
1	FRONT FENDER LH	BENT	760.00	760.00
1	FRONT FENDER INNER SHIELD LH	SERVICEABLE	230.00	-
1	FRONT FENDER REFLECTOR LH	SERVICEABLE	92.00	-
1	FRONT WHEEL RIM LH	CRACKED	590.00	590.00
	LESS 10% DISCOUNT		-	-453.50
			7,702.00	4,081.50
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	760.00	50.00
			760.00	50.00
	<u>LABOUR</u>			
	LABOUR CHARGE TO REMOVE, CUT OUT DAMAGE PORTION, JACK OUT, STRAIGHTEN, PANEL BEATING, WELDING, ALIGN AND RENEW REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER BRACKETS.		1,200.00	400.00
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS.		800.00	400.00
	TO REMOVE, REPLACE FRONT FENDER FITTINGS TO FACILITATE REPAIR.	NOT NECESSARY	300.00	-
	TO REMOVE, REPLACE FRONT TYRE AND WHEEL RIM.		100.00	20.00
	TO CHECK WIRING AND LIGHTINGS.		80.00	20.00
			2,480.00	840.00
	GRAND TOTAL		10,942.00	4,971.50

Report Ref No. CS/UOI20000351/Kyf3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,950.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/UOI20000351/Kyf3e2

KONG SENG CHEONG

Licensed Appraiser