



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

UNITED OVERSEAS INSURANCE LTD

Ref : CS/UOI20000351/Kyf3e2

3 ANSON ROAD #28-01
SPRINGLEAF TOWER SINGAPORE 079909

Date : 27-08-2020



Code : UOI2

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|------------------|----------------|------------|
| Insured Veh. | PA 8052C | Veh. Inspected | SMN 6524M |
| Policy No. | DHOM110152001602 | Coverage (\$) | 0.00 |
| Claim No. | | Excess (\$) | 0.00 |
| Assign From | FELIS | Assign Date | 06/01/2020 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------|--------------|--------------------|
| Make & Model | OPEL ASTRA (A) | c.c | 1598 |
| Engine No. | HIDDEN | Year of Reg. | 2019 |
| Chassis No. | W0VBD8EG4K8031215 | Colour | METALLIC BLACK |
| Odometer | 33959 | Steering | JAMMED |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------------|-------------|---------|
| R/H Front Tyre | 205/55 R16 | CONTINENTAL | 7 mm |
| L/H Front Tyre | 205/55 R16 | CONTINENTAL | 7 mm |
| R/H Rear Tyre | 205/55 R16 | CONTINENTAL | 7 mm |
| L/H Rear Tyre | 205/55 R16 | CONTINENTAL | 7 mm |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT AND UNDERCARRIAGE PORTION.

DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|-----------------------------|-----------------|------------|
| Accident Date | 25/12/2019 | Inspection Date | 07/01/2020 |
| Survey held at | 160 SIN MING #08-13 AUTOBAY | | |
| Repairer | HENG YAP SENG AUTO SERVICE | | |

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

| | |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 4 Working Days |
|-------------------------------------|----------------|